

بِسْمِ اللّٰهِ الرَّحْمٰنِ الرَّحِیْمِ



Republic of Maldives

SAFETY INVESTIGATION REPORT 2023/03

FINAL REPORT

INVESTIGATION OF THE OCCURRENCE INVOLVING MANTA AIR OPERATED

DHC-6-200, 8Q-RAL FLOATPLANE WHILST LANDING

AT VELANA INTERNATIONAL AIRPORT

ON 6 October 2023

INTRODUCTION

Maldives is a signatory to the Convention on International Civil Aviation (Chicago, 1944) which established the principles and arrangements for the safe and orderly development of international air transport. Article 26 of the Convention obligates Signatories to investigate accidents and serious incidents to civil aircraft occurring in their State.

This report is based upon the investigation carried out by the Accident Investigation Coordinating Committee (AICC) in accordance with Annex 13 to the Convention, the Civil Aviation Act 2/2001 and the Civil Aviation Regulations. The sole objective of this investigation is to prevent accidents and incidents. It is not the purpose of this investigation to apportion blame or liability.

In investigating this accident, AICC was assisted by Manta Aviation Pvt Ltd.

All times in this report are local time unless otherwise stated. Time difference between local and UTC is +5 hrs.

The report is released on 17 September 2025.

Mr. Abdul Razzak Idris

Chairperson

Accident Investigation Coordinating Committee



TABLE OF CONTENTS

1.	FACTUAL INFORMATION.....	7
1.1	History of Flight	7
1.1.1	Background.....	7
1.2	Injuries to Persons	10
1.3	Damage to aircraft	10
1.4	Other Damage	10
1.5	Personnel Information.....	10
1.5.1	Pilot-In-Command	10
1.5.2	Co-pilot	11
1.5.3	Cabin Crew.....	12
1.6	Aircraft Information	12
1.6.1	Airframe	12
1.6.2	Engines and Propellers	13
1.6.5	Recent maintenance	15
1.6.6	Defects.....	16
1.6.7	Aircraft Load.....	16
1.7	Meteorological information	16
1.8	Aids to Navigation	16
1.9	Communications	16
1.10	Aerodrome information	17
1.11	Flight Recorders.....	17
1.12	Wreckage and impact information.....	17
1.12.1	Wreckage Condition.....	17
1.12.2	Salvage operations.....	17
1.13	Medical and pathological information	17
1.14	Fire.....	17
1.15	Survival Aspect.....	18
1.16	Tests and research.....	18

1.17	Organizational and Management Information	18
1.18	Additional Information.....	18
2.	ANALYSIS.....	19
3.	CONCLUSIONS.....	21
3.1	Findings	21
3.2	Causes / Contributing Factors.....	21
4.	APPENDICES.....	22
4.1	Load sheet – Soneva Jani – MLE sector	22
4.2	ATL showing entries pre and post incident	23
4.3	Woodward report.....	24

LIST OF ABBREVIATIONS

AICC	Accident Investigation Coordinating Committee
AMP	Approved Maintenance Programme
ATL	Aircraft Technical Log
CAMO	Continuous Airworthiness Management Organization
CG	Centre of Gravity
CSU	Constant Speed Unit
DHC-6-200	Viking Air DHC-6, series 200 aircraft
EMMA	Equalized Maintenance for Maximum availability
FDR	Flight Data Recorder
FO	First Officer
lbs.	Pounds
LT	Local Time
LH, RH	Left Hand, Right Hand
MCAA	Maldives Civil Aviation Authority
MCAR	Maldives Civil Aviation Regulations
MLE	IATA designated three letter code for Velana International Airport
MMS	Maldives Meteorological Service
MSN	Manufacturer Serial Number
MTOM	Maximum Take-Off Mass
OEM	Original Equipment Manufacturer
PF	Pilot Flying
PIC	Pilot-in-command
PM	Pilot Monitoring
PWC	Pratt & Whitney, Canada
TBO	Time Between Overhaul

VFR	Visual Flight Rules
UTC	Coordinated Universal Time
VOM	Operator designated 3 letter code for Vommuli water aerodrome
WNW	West of Northwest

SYNOPSIS

On 6 October 2023, at about 1645 hours local time (LT), a Viking Air DHC-6-200 (Registration Markings 8Q-RAL) on approach to land at Velana International Airport water aerodrome (MLE), suffered loss of engine power on the RH engine while descending through, approximately 350 feet. The crew temporarily lost control of the aircraft but managed to land on water with a bounce and did a 360-degree right turn, before coming to rest. No damage was observed on the aircraft. There were no reports of any injuries to any passengers or crew.

The occurrence was reported to the AICC at 1715 hours, and an investigation was initiated on the same day.

1. FACTUAL INFORMATION

Aircraft Legal Owner:	MG Adriatic Leasing Limited
Registered owner:	Manta Aviation Pvt Ltd.
Aircraft Type:	Viking Air DHC-6-200 (Floatplane)
Operator:	Manta Air (Air Operator Certificate No.014)
Registration:	8Q-RAL
Number and type of engines:	2 engines / PT6A-27 (PWC)
Engine hours / cycles since new:	LH engine: 30,409.55 hours RH engine: 2,061.11 hours
Location of Occurrence:	MLE water aerodrome (North-Right Takeoff / South-West landing) (04° 11' 50.76"N/73° 32' 22.47"E)
Date and Time:	6 October 2023 at 16:43 hours LT
Persons on board:	08

1.1 History of Flight

1.1.1 Background

On 06 October 2023, about 1643 hrs, a DHC-6-200 Twin Otter floatplane (registration markings 8Q-RAL), operated by Manta Air departed Soneva Jani water aerodrome (Medhufaru, Noonu Atoll) on a charter service (NR2205) destined to MLE. There were 5 passengers, 2 flight crew and 1 cabin crew onboard. The PIC was the Pilot Flying (PF) and the FO was the Pilot Monitoring (PM).

The aircraft was released for flight from the Operator's base at Velana International Airport (MLE), at 1800 hours on the previous day with all relevant inspections completed. On the day of the occurrence, prior to the occurrence flight, the aircraft had operated on sectors MLE-FSE (Soneva Fushi, Baa Atoll)–MLE and MLE-FSE–JSE.

The flight from JSE to MLE was uneventful until about 350 feet altitude on approach to MLE. The PIC called for full flaps, max propeller rpm and landing checks. Immediately after flaps were fully extended and the propeller levers were selected to fully FWD position, for max rpm, the aircraft reacted violently and yawed to the right, with a right bank. The crew reported that they did lose control of the aircraft initially and felt as if it was entering into a spin.

Flight radar recordings and the ATC Communication recordings indicate the aircraft was at about 350 feet altitude on final course to water runway South Left and the speed was 80 knots at 16:43:43 hours. Just 4 seconds later the aircraft had turned right by about 30 degrees and descended to 300 feet giving a descend rate of 750 per minute with a speed of 66 knots. Even though the aircraft continued to turn right the aircraft descend rate changed to 500 per minute over the next 9 seconds. But by this time the speed had bled to 52 knots. After the initial veering to the right of the approach path, the aircraft was seen making a slow left turn before impacting the water.

The PIC stated that he was unable to even glance at the flight instruments or engine instruments since the aircraft was at a critically low altitude. When the crew regained control of the aircraft, the aircraft had veered to almost 60° to the right, and an imminent crash was feared. The PIC stated that an attempt was made to add power on the LH engine but was unable to move the lever as it was stuck and added that he felt both the power levers were stuck.




Figure 1a

Figure 1b

The PIC realized that the aircraft was heading towards the red and white painted tanks located on the south end of HulhuMale' island. At the time the stall warning horn was heard the PIC was attempting to pitch down the aircraft more in a desperate attempt to gain airspeed to avoid the aircraft stalling. At this point the PIC advised the FO to declare MAYDAY. PIC stated that the idea was to gain maximum air speed and flare up so that the touchdown would be on the water instead of land in front.

The PIC was concerned that the float could become detached on impact, hence attempted to land on both floats thus sharing the impact load equally. The aircraft had a very hard landing on water and bounced; the aircraft remained upright on both the floats. When the aircraft stabilised on water, the crew found the LH power lever had come free and was able to gain partial control of the aircraft.

The crew then shut down the RH engine by retarding the fuel lever thus shutting off the fuel to the RH engine. The aircraft taxied with the assistance of the rescue boat and docked on the fixed platform and the left engine was shut down. The passengers then disembarked through the main airstair door.

1.2 Injuries to Persons

Injuries	Flight Crew	Cabin Crew	Passengers	Total on board	Others
Fatal	0	0	0	0	0
Serious	0	0	0	0	0
Minor	0	0	0	0	0
Nil	2	1	5	8	0
Total	2	1	5	8	0

1.3 Damage to aircraft

No damage was reported.

1.4 Other Damage

None

1.5 Personnel Information

1.5.1 Pilot-In-Command

Age:	31 years
Nationality:	Indian
Gender:	ATPL
License issued on:	13 Sep 2022
License expires on:	12 Sep 2027
Type of medical:	Class One (1) medical certificate
Medical issued on:	23 Sep 2023
Medical expires on:	23 Sep 2024
Types flown:	DHC-6
Hrs. on type:	4860.30 hours
Ratings:	DHC6 / IR

Last Proficiency check:	14 Jul 2023
Total hours as PIC:	634.3 hours
Total flight time:	5287.30
Last 90 days:	169.42 hours
Last 28 days:	75.25 hours
Last 24 hours:	5 hours 25 minutes
Previous rest period:	12 hours 45 minutes

1.5.2 Co-pilot

Age:	34 years
Nationality:	Indian
Gender:	Male
Type of License:	Commercial Pilot License (CPL-A)
License issued on:	13 Jan 2022
License expires on:	12 Jan 2025
Type of medical:	Class One (1) medical certificate
Medical issued on:	15 Nov 2022
Medical expires on:	14 Nov 2023
Types flown:	DHC-6
Hrs. on type:	1419.40 hours
Ratings:	DHC6
Last Proficiency check:	13 Jan 2023
Total flight time:	2106.04
Last 90 days:	136.42 hours
Last 28 days:	19.16 hours
Last 24 hours:	05 hours 25 minutes
Previous rest period:	12 hours 45 minutes

1.5.3 Cabin Crew

Age:	27 years
Nationality:	Maldivian
Gender:	Male
Type of License:	Cabin Crew License
License issued on:	28 Feb 2022
License expires on:	27 Feb 2027
Type of medical:	Class Three (3) Medical Certificate
Medical issued on:	01 Feb 2023
Medical expires on:	01 Feb 2025
Previous rest period:	12 hours 45 minutes

1.6 Aircraft Information

DHC-6-200 aircraft bearing MSN 045 was built in 1967 by de Havilland Inc. The aircraft was registered for the first time in the Maldives on 13 December 2018, under registration markings 8Q-TAI and was in operation with TMA until 24 November 2021. The aircraft was re-registered with Manta Aviation Pvt Ltd., in November 2021, and since then the aircraft has been in operation with Manta Air.

1.6.1 Airframe

The DHC-6-200 “Twin Otter” is an unpressurised, all-metal, high wing aircraft powered by two Pratt & Whitney PT6A-27 engines driving four-bladed, reversible-pitch, full feathering propellers. The aircraft is designed for seating two pilots, side by side with dual controls, standard and optional flight instrumentation.

Manufacturer	de Havilland Inc.
Model:	DHC-6-200 series
Manufacturer’s serial number:	045
Year of Manufacture:	1967
Nationality:	8Q (Republic of Maldives)

Registration Markings:	8Q-RAL
Certificate of Registration:	Initial Issued on 31 Dec 2018
Owner:	Manata Aviation Pvt Ltd
Operator:	Manta Air
Validity of Certificate of Airworthiness:	Valid since initial issue on 12 Dec 2021 (Normal category)
Airworthiness Review Certificate:	ARC Reference MV.MI.0123 Issue 3
	Last issue: 07 June 2023
	Date of Expiry: 15 February 2024
Total Flying Hours since manufacture:	44,254:39 hours
Total Landings since manufacture:	78,306 landings
Last periodic inspection:	EMMA 37
Last inspection carried out at TAT/TAC:	44,201:09 hours / 78,221 cycles
Total Flying Hours since last periodic inspection:	54:30 hours

1.6.2 Engines and Propellers

Right Engine (Gas Generator)	
Right engine manufacturer	PWC
Year of manufacture	1985
Model	PT6A-27
Serial number	PCE-42433
Total Hrs. since new	2,061.11 hours
Last overhaul date	05 Oct 2021
Hrs. since overhaul	938.02 hours
Last check carried out	EMMA No 37 on 22 Sep 2023
Hrs. since last check	47.18 hours
Right Engine (Power section)	
Right engine manufacturer	PWC
Year of manufacture	1985
Model	PT6A-27

Serial number	42433-100
Last overhaul date`	05 Oct 2021
Hrs. since overhaul:	938.02 hours
Last check carried out:	EMMA No 37 on 22 Sep 2023
Hrs. since last check:	47.18 hours
Left Engine (Gas Generator)	
Left engine manufacturer:	PWC
Year of manufacture:	1985
Model:	PT6A-27
Serial number:	PCE-42432
Total hrs. since new:	30,409.55 hrs
Last overhaul date:	11 October 2021
Hrs. since overhaul:	453:07 hours
Last check carried out:	EMMA No 37 on 22 Sep 2023
Hrs. since last check:	47.18 hours
Left Engine (Power section)	
Left engine manufacturer:	PWC
Year of manufacture:	1985
Model:	PT6A-27
Serial number:	42432-100
Last overhaul date:	11 October 2021
Hrs. since overhaul:	453:07 hours
Last check carried out:	EMMA No 37 on 22 Sep 2023
Hrs. since last check:	47.18 hours
Right Propeller	
Manufacturer:	Hartzell
Year of manufacture:	Unknown
Model:	HC-B3TN-3DY
Serial number:	BUA19757
Last overhaul date:	10 May 2019
Hrs. since last overhaul:	2873:37 hours

Last check carried out:	EMMA No 37 on 22 Sep 2023
Left Propeller	
Manufacturer:	Hartzell
Year of manufacture:	Unknown
Model:	HC-B3TN-3DY
Serial number:	BUA35198
Last overhaul date:	15 April 2023
Hrs. since last overhaul:	191:09 hours
Last check carried out:	EMMA No 37 on 22 Sep 2023

*Engine / Propellor details including hours are stated as provided by the Operator and has not been independently verified.

1.6.3 Flight Controls

The flight controls consist of conventional, manually actuated primary flight controls operated through cables, pulleys, and mechanical linkages. Rudder and elevator trim are manually controlled and mechanically actuated; aileron trim is electrically actuated. Secondary flight controls consist of hydraulically actuated wing flaps.

1.6.4 Fuel

Jet A-1 fuel was used on the aircraft engines. The aircraft was last refueled at the main base at MLE. The mass of fuel as per records on the ATL are detailed below:

Departure from MLE:	1400 lbs.
Arrival at JSE:	890 lbs.
Arrival at MLE:	400 lbs.

1.6.5 Recent maintenance

The most recent maintenance inspections carried out include Equalized Maintenance for Maximum Availability (EMMA) check number 37, complied with on 22 Sep 2023, at 44,201:09 TAT and 78,221 TAC. The next maintenance inspection would fall due at 44,326:09 hours TAT.

As per Aircraft Technical Log (ATL) sheet number 11131, the latest daily inspection was carried out at 1800 hrs on 05 Oct 2023.

Past records show that a defect relating to the same system was reported on 4 October 2023. It stated: "After landing right prop went to almost feather NP 20-30%, could not get

reverse.” Troubleshooting carried out, post pilot report, revealed that the RH Engine Reversing Lever Carbon Block was damaged, and as such it was replaced in accordance with PSM 163-2 CH 61-00-00 Rev 21 with satisfactory results. The carbon block is a component attached to the beta valve of the CSU.

1.6.6 Defects

There was no record of open deferred defects, and the crew did not report any defects prior to the incident.

1.6.7 Aircraft Load

The aircraft departed JSE with a take-off mass of 11,066 lbs. The estimated landing mass at arrival in MLE was 10,616 lbs.

The crew were provided with a printed load sheet which was accepted and signed by the PIC. Based on the load sheet, both takeoff and landing masses were well within the limitations set by the Operator.

The Mass & Balance Report prepared for the flight by the PIC using the aircraft Tablet, recorded the Take-Off CG at 29.5% MAC, and the landing CG also at 30.1 % MAC.

1.7 Meteorological information

The maximum wind speed recorded between 1600 to 1700 hours on 06 Oct 2023 was 12 knots from WSW direction.

1.8 Aids to Navigation

The aircraft was operating under VFR. No navigational aids were available at the water aerodrome.

1.9 Communications

There were no communication issues or defects recorded. Both VHF Communication systems were operating normally.

1.10 Aerodrome information

Arrival Aerodrome: MLE water aerodrome
(North-Right Takeoff / South-West landing) water runway

Water runway coordinates: 04.1974 N (04° 11' 50.76"E)
73.5396 E (73° 32' 22.47"E)

1.11 Flight Recorders

No flight data recorder (FDR) or Cockpit Voice Recorder (CVR) was installed on the aircraft, and they are not required under MCARs.

1.12 Wreckage and impact information

1.12.1 Wreckage Condition

No damage was reported.

1.12.2 Salvage operations

Upon landing, the aircraft taxied to the nearest dock, using left engine power. A powered dinghy from ARFF Marine rescue, tied to the right float provided assistance to taxi the aircraft.

1.13 Medical and pathological information

All three crew members were subjected to drug tests and the results were reported negative for all crew.

1.14 Fire

There were no fires or fire alarms.

1.15 Survival Aspect

The airports ARFF Marine rescue attended to the aircraft soon after the aircraft landed and assisted the aircraft to taxi to the dock while the passengers and crew were on board. The passengers and crew disembarked onto the dock safely using the airstair door.

1.16 Tests and research

The defective CSU Part number 8210-304, Serial number 11393795 was sent to the OEM, Woodward Inc. Loves Park, Illinois, United States of America for investigation. The investigation was carried out under the direct oversight of the NTSB.

Woodward's investigation report is attached as Appendix 4.3.

1.17 Organizational and Management Information

Manta Air (MA) is a MCAA approved Air Operator Certificate holder who commenced their operation in 2019. MA provides domestic air services using 3 ATR 72 and 16 DHC-6 floatplanes. DHC-6 floatplane aircraft is authorized to conduct day VFR Operations only. The company also holds Aircraft Maintenance Organization Approval (MV.145.077) and CAMO Approval reference MV. CAMO.007. While its operating base is located at VIA, Manta carries out majority of the scheduled and unscheduled maintenance at their maintenance based in Dhaalu Airport, located in the south of the country – Maldives.

1.18 Additional Information

None

2. ANALYSIS

The PIC and FO were medically fit and held valid licenses. They had operated within the FDTL limits, prior to the flights on the day of the occurrence. Crew training records suggest that both crew members had undergone necessary trainings and were qualified to operate the flight.

The aircraft experienced engine power loss (RH position) at about 350 feet on approach to landing. Troubleshooting actions carried out immediately after the occurrence found LH engine and the power lever was functioning normally while the RH engine power lever was stuck with the RH propeller locked in feather position. RH engine and its power lever worked well after replacement of the corresponding CSU. Thus, the power loss on the RH engine was attributed to failure of the CSU.

When the CSU was examined, the Beta valve clevis was found to be loose. The CSU was sent to Woodward Inc., for further investigation. The task was carried out by Woodward under the direct oversight of the NTSB.

Testing and research carried out by Woodward found that the beta valve plunger assembly, a constituent part of the CSU, was detached at the brazed joint: clevis piece separated completely from the plunger.

Prior to power loss on RH engine, the propeller was operating in Beta Range with the propeller lever brought forward to the maximum RPM (96% NP) position, which is the standard configuration for landing Twin Otter aircraft.

In Beta Range the propeller blade angle is controlled by the beta reverse valve, the plunger moving within the through-hole, exerting an axial load on the plunger. The axial load on the Beta Valve separated the clevis from the plunger of the Beta valve assembly. According to the Woodward report, this separation was due to a shear overload of the copper braze material.

Past records show that a defect relating to the same system was reported on 4 October 2023. It stated: "After landing right prop went to almost feather NP 20-30%, could not get reverse." Troubleshooting carried out, post pilot report, revealed that the RH Engine Reversing Lever Carbon Block was damaged, and it was replaced in accordance with PSM 163-2 CH 61-00-00 Rev 21 with satisfactory results. The carbon block is a component

attached to the beta valve of the CSU. This may have been the indication of an impending failure of the CSU that occurred on this flight.

3. CONCLUSIONS

3.1 Findings

AICC determines that:

1. Medical fitness and FTDL of the crew were not factors.
2. The LH engine was operating normally
3. Propeller latches were engaged on RH engine following failure of the CSU.
4. Beta Valve clevis piece and plunger of the CSU were separated completely from each other at the brazed joint.

3.2 Causes / Contributing Factors


The AICC determines that the cause of the serious incident is related to the CSU failure due to the separation of clevis from the plunger of the Beta valve assembly.

3.3 Safety Recommendations

Nil

4. APPENDICES

4.1 Load sheet – Soneva Jani – MLE sector



8QRAL

LOADSHEET

FCGO-029 ISS01REV02 161221
ALL WEIGHTS IN POUNDS (LB)

Flight number	NR2205	Date	6 Oct 2023	Crew	2	1
A/c Registration	8QRAL	A/c Type	DHC-6 on Floats	From	JSE	
Seating version	09 Y	Time	15:07:52	To	MLE	


Passengers	Standard PW		E	Actual PW		Weight	Index	Total Passengers	
	A	D		A	D			Male	Female
Row 1						0	0.0		2
Row 2	M	M				378	-1.1		2
Row 3	F	F				300	0.2		1
Row 4	C					77	0.4		0
Row 5						0	0.0		
Total						755	-0.554	Total (incl. inf)	5

Deadload	Area D		Rear cpt		Aft Shelf		Total	
	Pcs	Weight	Pcs	Weight	Pcs	Weight	Pcs	Weight
Cabin Baggage			3	39			3	39
Checked Baggage	5	187					5	187
Cargo							0	0
Others				4			0	4
Total	5	187	3	43	0	0	8	230

Fuel	Weight	Index	Notes
FWD Tank	437.5	-1.5	
AFT Tank	437.5	0.6	
Trip Fuel	450	-0.4	

	Weight	Index	MAC %
Dry Operating Weight	9206	10.3	
Total Traffic Load	985	2.0	
Actual Zero Fuel Weight	10191	12.3	
Take Off Fuel	875	-0.9	
Actual Take Off Weight	11066	11.4	29.5
Trip Fuel	450	-0.4	
Actual Landing Weight	10616	11.8	30.1
Underload	1434		

Total Passengers	5
Total Onboard	8



Prepared by	
Name	
Signature	

Approved by	
Name	
Signature	

Non-Standard Passenger weights used

Standard weights used for Passengers and Cabin baggage, unless ticked above.

Actual weights used for checked baggage, Cargo and Other deadloads

I certify that this aircraft is loaded in accordance with the approved weight and balance schedule. LMC is not allowed on this loadsheet

4.2 ATL showing entries pre and post incident

Manta Aviation Pvt. Ltd.
Karama, Villa (4th Floor), Grand Magh, Madat, 20212, Republic of Maldives, Tel: +960 331 0911

AIRCRAFT TECHNICAL LOGBOOK
Log No. **11132**

DATE: **16.10.23** REG: **BQ-RAL** TYPE: **DHC-6-350**

Route	TIMES		BLOCK TIME		LDG		FUEL IN POUNDS		P/C	Crew Details PC / FO / CA				
	Off Block	Take Off	Land	On Block	Air Time	Time	L	R			Remain	Up/lt	Departure	Sign
1 To FSC	0950	1007	1041	1045	34	55	01	1	900	320	1220	527	599	206
2 To MCE	1145	1150	1227	1235	37	50	01	1	860	-	860	-	4	4
3 To FSE	1405	1416	1450	1455	34	50	01	1	500	1220	1520	-	4	4
4 To SSE	1505	1510	1538	1540	26	35	01	1	1160	-	1160	-	4	4
5 To MNG	1555	1600	1648	1710					890	-	890	-	11	11

ENGINE TREND MONITOR	LEFT	RIGHT
Torque	45	45
Level Flight - Cruise conditions		
Electrical Loading - Normal	Np	76
Engine - stabilis 5 mins	ITT	550
	Ng	95
OAT °C	21°C	94
PRESS ALT.	1520	300
OIL Temp	78	90
OIL PSI	130	84

Next Check	EMMA #	38	TAT	4432609
Sign & Stamp:	Routine AAE and Float-50			
Date & Time	12/10/23			
Next Due	12/10/23			

ON PR	M17/60	- R6, 142	SIN	-
OFF PR	M17/60	- R6, 142	SIN	-
ON PAN				
OFF PAN				

Level	3.0	2.0
Up/lt	L+1	AICR

Hours	44252:00	72301
Landings	44250:39	78306

PAGE TOTALS
BROUGHT FWD
TOTAL

TCAS INTERMITTENT

BOTH ENGINES RESPONSIVE AT 200 FT FOLLOWED BY EMERGENCY LANDING

HARD LANDING INSPECTION.

ACTION TAKEN: T/S of A15800 SYSTEM ANTENNA CABLES REPLACED
OPS CHECK CO. IAW A15800 MAINTENANCE MANUAL 19D-012.79-01
REV2 - FOUND SAT

ACTION TAKEN: BOTH ENG CONTROLS INSPECTED PER AILS AND ACE MONITORING
NFF - CONTROL INSPECTED CHECKED PER SHEET AND COMPANY. NFF - EMP
PER-COOLS, PROB SENSITIVE W/LET SCREEN AND COMPRESSOR 1ST STAGE
ACTION TAKEN: REFER TO WJO RAL-0046/0010 PER
CORRECTIVE ACTION - NFF

4.3 Woodward report


		INVESTIGATION/8D REPORT Class 1 Published: 12-JUL-2024 (D8)	
CUSTOMER MANTA AVIATION PVT. LTD		INVESTIGATION NO 1194855	
CUSTOMER ORDER Crash Investigation		WOODWARD SALES ORDER 3907740	WOODWARD WORK ORDER C888526
CUSTOMER REJECTION DOCUMENT (CAR, ON, RFA, DMR, ETC.) N/A		WARRANTY DISPOSITION N/A	PRODUCT STATUS N/A
PROGRAM/ENGINE TYPE P&WC PT6 CSU		ITEM RECEIVED 8210-304	ENGINE MFR MODEL RECEIVED N/A
PROGRAM CODE 83053 CSU	SERIAL NUMBER 11393795	ITEM SHIPPED 8210-304	ENGINE MFR MODEL SHIPPED 3075355-01
PARENT ITEM NUMBER 8210-304	PARENT ITEM SERIAL NUMBER 11393795	FIRST SHIPPED 21-OCT-1994	LAST SHIPPED 21-OCT-1994
CUSTOMER SERIAL NUMBER N/A	APPLICATION N/A	VESSEL TYPE & VESSEL NUMBER N/A	SITE & LOCATION GRID ID N/A
TIME/CYCLES SINCE NEW, OVERHAUL, OR REPAIR N/A			
DATE REPORT OPENED N/A		DATE PART REMOVED N/A	DATE RECEIVED 06-DEC-2023
TEAM MEMBERS (D1) Product Engineer: Nathan Bogdonas Customer Service Rep: Shannon L. Cote			
REASON FOR INVESTIGATION (D2) Reported Issue: INCIDENT DETAILS: ON OCTOBER 6, 2023, ABOUT 1643 LOCAL TIME, A TWIN OTTER, REGISTRATION 8Q-RAL OPERATED ON FLOATS WHILST ON APPROACH TO MLE SUFFERED LOSS OF ENGINE POWER ON RH ENGINE AT ABOUT 350 FEET ALTITUDE. THE AIRCRAFT MADE A SUDDEN RIGHT TURN WHICH RESULTED IN THE COCKPIT CREW BEING UNABLE TO CONTROL THE AIRCRAFT AND DECLARED EMERGENCY; BUT MANAGED TO LAND ON WATER. AT TOUCHDOWN, THE AIRCRAFT BOUNCED AND LANDED AGAIN. THE AIRCRAFT WAS CIRCLING ON WATER BEFORE IT FINALLY SETTLED ON WATER. THE CREW THEN SHUT DOWN THE RIGHT HAND ENGINE USING THE FUEL LEVER: SHUTTING OFF THE FUEL TO THE RIGHT HAND ENGINE. THE AIRCRAFT WAS THEN TAXIED WITH THE ASSISTANCE OF THE RESCUE BOAT AND FINALLY DOCKED ON THE FIXED PLATFORM AND THE LEFT ENGINE SHUTDOWN, NORMALLY. THE PASSENGERS DISEMBARKED THROUGH THE MAIN AIRSTAIR DOOR.			
INVESTIGATION SUMMARY (D4) Confirmation Text: NOT KNOWN IF REASON FOR INVESTIGATION/RETURN IS CAUSED BY DISCREPANCY FOUND Discrepant Item Number: 3535-035 Discrepancy: PART IS DAMAGED Finding: BROKEN/ CRACKED/ FRACTURED/ SEPARATED Conclusion: An as received visual inspection was conducted on the unit. It was noted that the lockwire, lockwire seal, and torque sealant were all non-Woodward indicating the originals had been removed after leaving the Woodward facility. Additionally, the beta valve braze joint between the plunger and head had separated (see Figure 1). The beta valve head/clevis had dented material on the outside of the prongs (see Figure 2). It was determined that the unit could proceed with testing even with the damaged beta valve.			
<small>This document contains technical data that are controlled under the Export Administration Regulations (15 CFR 770, et seq.). Any transfer to a non-U.S. person or export from the United States must be in accordance with the Export Administrations Regulations. Diversion contrary to U.S. law is prohibited. Export Administration Regulations Export Control Classification (ECCN): 9E991</small>			
<small>4-14-3712</small>			



Figure 1 Separated Beta Valve Assembly



Figure 2 Beta Valve Clevis Damage

This document contains technical data that are controlled under the Export Administration Regulations (15 CFR 770, et seq.). Any transfer to a non-U.S. person or export from the United States must be in accordance with the Export Administrations Regulations. Diversion contrary to U.S. law is prohibited. Export Administration Regulations Export Control Classification (ECCN): 9E991

4-14-3712

During the As Received Test all test points were found to be within limits except the following:

- "Relief Valve Pressure" was out of limits low at 370 psig (Limits 385 ± 10 psig)
- "Maximum Speed Setting" was out of limits low at 4057 rpm (Limits 4246 ± 5 rpm)
- "Speed Setting Lever Travel" was out of limits low at 49 degrees (Limits 210 ± 2.5 degrees)
- "Maximum RPM" was out of limits low at 4057 rpm (Limits 4032 ± 5 rpm)
- "Pump Capacity" was out of limits low at 4.4 qts/min (Limits 5.5 qts/min Minimum)
- "Internal Leakage" was out of limits high at 2.7 qts/min (Limits 2.5 qts/min Maximum)
- "Beta Valve Travel" could not be run due to beta valve damage.

Testing was repeated and the max speed setting was readjusted back to test limits. The following changes were observed:

- Relief Valve Pressure and Maximum Speed Setting test points returned to limits.
- The speed setting lever travel was out of limits high at 78 degrees (Limits 73 ± 3 degrees)
- The pump capacity increased from 4.4 to 5.4 qts/min (Limits 5.5 qts/min Minimum)
- The internal leakage increased from 2.7 to 3.2 qts/min (Limits 2.5 qts/min Maximum)

Following testing the unit was disassembled. The beta valve assembly was removed. The components of the beta valve are designed to be brazed together. The braze operation is performed by Woodward during manufacturing. As a process control, the joints are 100% tested with a 500lb load. On this returned unit it was confirmed that there was separation of the braze joint between the plunger and head (see Figure 3).

Upon further inspection the joint was fully covered in copper braze indicating the braze was properly applied. Additionally, there was no sign of corrosion or other environmental factors that appeared to weaken the joint. The beta valve assembly was bagged and sent to Woodward's materials lab for analysis. The materials lab confirmed there was no signs of corrosion/pitting but found a region with silver/dark gray appearance that was consistent with porosity (see Figure 4). However, the valve allows up to 50% porosity of the internal joint and the region detected was well below the requirement. The materials lab came to the following conclusions "The fracture surface showed predominantly shear overload of the copper braze material in a direction of the long axis of the assembly. Mechanical damage was present on both halves of the assembly which would have been caused by an event which placed a shear load on the braze joint. Composition of components and braze filler metal were all consistent with the specified materials."



Figure 3 Beta Valve Separated



Figure 4 Braze Joint Porosity

During disassembly the governor cover was removed and the ballhead assembly, air bleed system, and pilot valve were all inspected and there were no anomalies. The baseplate was also removed exposing the pump and there were no notable findings.

Following the teardown Woodward engineering reviewed the loads the braze joint could experience during normal operation and determined that the loads are an order of magnitude lower than the 500 lb. load the braze joint is 100% inspected against when manufactured. Additionally, Woodward reviewed engineering change history and the drawing had not been revised since 1992 confirming that there were no recent changes to the beta valve.

In summary, the beta valve was found separated and the braze joint was sent to Woodward's material lab for investigation. The lab determined the cause of the separation was due to a shear overload of the copper braze material. The Woodward team reviewed the operating loads that the joint would be subject to and determined that the loads are an order of magnitude lower than the 500 lb. load the braze joint is 100% inspected against. The braze joint was inspected and no corrosion/pitting was observed that would have reduced the joints structural integrity. Due to these findings, there was no evidence to suggest that the braze joint separated under normal operation, further root cause into the overload event was not isolated during the investigation.

ROOT CAUSE (D4)

Origin of Cause: OTHER

General Cause: No Cause Found

Cause: Cause Not Isolated or Determined

Root Cause: The beta valve braze joint was found separated. The braze joint was sent to Woodward's material lab for investigation and the lab determined the cause of the separation was due to a shear overload of the copper braze material. The Woodward team reviewed the operating loads that the joint would be subject to and determined that the loads are an order of magnitude lower than the 500 lb. load the braze joint is 100% inspected against. The braze joint was inspected and no corrosion/pitting was observed that would have reduced the joints structural integrity. Due to these findings there was no evidence to suggest that the braze joint separated under normal operation, further root cause into the overload event was not isolated during the investigation.

CORRECTIVE ACTION PLAN (D5)

General Corrective Action: No Action without Additional Customer Input

Specific Corrective Action: No Direct Action, Continue to Monitor

CORRECTIVE ACTION IMPLEMENTATION (D6)

Corrective Action Status: NO ACTION

This document contains technical data that are controlled under the Export Administration Regulations (15 CFR 770, et seq.). Any transfer to a non-U.S. person or export from the United States must be in accordance with the Export Administrations Regulations. Diversion contrary to U.S. law is prohibited. Export Administration Regulations Export Control Classification (ECCN): 9E991