

		APPROVAL #										
DATE	TYPE	YEAR	#	SUBJECT	A/C TYPE / PN	MSN	OPERATOR	DESIGN INFORMATION	PREVIOUS APP. #	INSPECTOR		
2008-06-18	DHC-6	2008	01	Installation of McMaster-Carr fan at AFT cabin	DHC-6	All	MAT	Mod designed by MAT engineer Waqar Ahmed	N/A	Husam/Fazeel		
39664	DHC-6	2008	02	Repair on 8Q-MAI RH wing	DHC-6	279	MAT	Structural Integrity Engineering (SIE). SIE drawing approved by Mr. Kirk Odian	N/A	Husam/Sinwaan		
39709	DHC-8	2008	01	Installation KHF-950 HF system	DHC-8-300	544	IASL	Aeronautical Engineers Australia and Australian Avionics	MOD/DHC-8/2007/01	Husam/Fazeel		
39709	DHC-8	2008	02	4000 ELT with Artex 406MHz	DHC-8-300	544	IASL	Aeronautical Engineers Australia and Australian Avionics		Husam/Fazeel		
39709	DHC-8	2008	03	Personal Locator Beacon	DHC-8-300	544	IASL	IASL own design		Husam/Fazeel		
39741	DHC-8	2008	04	Medical Oxygen Container	DHC-8-200/300	all	IASL	IASL own design	N/A	Husam/Shifzan		
39817	DHC-6	2009	01	Floor carpet	DHC-6	all	MAT	Complies with FAR Part 25.853. Verified by Air India Limited 30 Jan 2006	N/A	Husam/Adam		
39909	DHC-8	2009	02	Floor carpet	DHC-8	all	IASL	Centro de Tecnologias Aeronauticas. flammability C/O IAW with FAR25.853 (a); FAR 25 Appendix F, Part I	N/A	Shifzan		
39909	Do-228	2009	03	Floor carpet	Do228-212	all	IASL	Centro de Tecnologias Aeronauticas. flammability C/O IAW with FAR25.853 (a); FAR 25 Appendix F, Part I	N/A	Shifzan		
39968	DHC-6	2009	04	Repair on 8Q-MAO LH wing spar	DHC-6-300	259	MAT	Structural Integrity Engineering (SIE 23-KB-250001-1). SIE drawing approved by FAA DER Mr. Kirk Odian	N/A	Sinwaan		
40036	DHC-8	2009	05	Installation of SafrGlo Inc. Photoluminescent Emergency Escape Path Marking System.	DHC-8-200/300	all	IASL	FAA approved STC No. ST02311AT to SaftGlo Inc. (Original Product Type Certificate No. A13NM) FAA Approved Flight Manual Supplement No. M07-11, Rev B STG Aerospace Manual No. M07-10	N/A	Somith / Husam		
40041	DHC-6	2009	06	Installation of INDIGO ONE GPS Tracking / Satellite messaging unit	DHC-6	All	MAT	STC Information: Field Mod by IndigoSat and type supplement for DHC-6 Series. <a href="http://www.indigosat.com/stc.aspx">www.indigosat.com/stc.aspx</a>	N/A	Husam/Abdulla		
40052	DHC-6	2009	07	De-Activation of Beta Back-up system	DHC-6-100/300	All	TMA	TMA Modification Bulletin TMA 61-001.	N/A	Abdulla		
40063	DHC-6	2009	08	Approval of GPS (Trimble and Garmin)	DHC-6	All	MAT	STC Information: EASA.IM.A.S.02581, TC STC # SA01-93 and SA02-119. LSTC Information: TC LSTC # W-LSA 98-059/D and C-LSA00-541	N/A	Adam		
40105	DHC-6	2009	09	Installation for Garmin GPS	DHC-6-100/300	All	TMA	TMA Modification Bulletin TMA 34-001.	N/A	Shifzan		
40108	DHC-6	2009	10	Repair on 8Q-MAB Wing Strut Attachment	DHC-6-300	287	MAT	RW Martin Inc, Mr. Hillyn Pruntich DER of FAA (No. DERT-605452-NM)	N/A	Adam		
40111	DHC-8	2008	04R1	Medical Oxygen Container	DHC-8-200/300	all	IASL	IASL own design	MOD/DHC-8/2008/04	Abdulla		
40177	DHC-8	2009	11	Installation & Removal of PLB and Holder	DHC-8-202	All	IASL	IASL own design	N/A	Abdulla		
40184	DHC-8	2003	02R1	Removal & Installation of PLB	DHC-8-202	All	IASL	IASL own design	MOD/DHC-8/2003/02	Abdulla		
40248	DO-228	2010	01	Installation and Removal of Oxygen Bottle Carriage	Do-228-212	8244	IASL	IASL own design	N/A	Somith		
40283	DHC-8	2010	02	Installation of Stretcher System	DHC-8-200/300	All	IASL	FAA approved STC No. ST00393NY	N/A	Adam		
40293	DHC-6	2010	03	Installation of a nine passenger executive seating system	DHC-6-300	273	MAT	FAA approved STC No. SA02808CH	N/A	Adam		
40308	DHC-6	2010	04	Rear window removal on LH side	DHC-6-300	571	MAT	MAT own design	N/A	Shifzan		
40315	DHC-6	2010	05	Rear window removal on LH side	DHC-6-300	571	MAT	MAT own design	MOD/DHC-6/2010/04	Adam		
2010-06-10	DHC-6	2010	06	Installation of Wipair 1300 floats	DHC-6-300	All	MAT	FAA STC No. SA2CH	N/A	Abdulla		
2010-06-17	DHC-06	2010	07	Installation of Digital Clock	DHC-6	All	MAT	Modification previously installed by KBAL	N/A	Shifzan		

2010-07-18	DHC-6	2010	08	8Q-OEQ Frame No. 230 Crack Repair	DHC-6-100	44	MAT	RW Martin Repair Drawing RD53-3866A (DHC-6-100 S/N 044, LH FS 200 Upper Frame Crack Repair)	N/A	Somith	
2010-09-16	DHC-6	2010	09	Installation of ASPEN EFD1000/500 on 8Q-MAP	DHC-6-300	571	MAT	FAA STC No. SA10822SC	N/A	Adam	
2010-09-26	DHC-8	2010	10	Repair - Sloping firewall of RH lower cowl assembly	DHC-8-300	491	IASL	IASL Engineering Order # DHC8-71-07 Issue 1 and Bombardier RD # 8-71-610 Rev 2006-08	N/A	Abdulla	
2010-09-28	DHC-6	2010	11	Fleet-wide installation of ASPEN EFD 1000/500	DHC-6-300	All	MAT	FAA STC No. SA10822SC	N/A	Abdulla	
2010-09-28	DHC-6	2010	12	Installation of new flap rollers	DHC-6	All	MAT	Swiss Federal Office for Civil Aviation STC # Z 27-50-03	N/A	Abdulla	
2010-11-09	DHC-8	2008	04R2	Medical Oxygen Container	DHC-8-200/300	All	IASL	IASL Engineering Order # DHC-8-25-05R2	DHC-8/2008/R1	Abdulla	
2010-11-28	DHC-8	2010	13	RH Nacelle Aft Tail Fairing Repair	DHC-8-300	544	IASL	IASL Engineering Order # DHC8-54-01	N/A	Abdulla	
2010-11-28	DHC-6	2010	14	Installation of Garmin Traffic Advisory System	DHC-6-100/200/300	All	MAT	FAA STC # SA02016SE-D	N/A	Abdulla	
2010-12-01	DHC-6	2010	15	Installation of Garmin GNS530W/430W	DHC-6 300 Series	All	TMA	Transport Canada STC# SA02-119	N/A	Shifzan	
2010-12-09	DHC-6	2010	16	Installation of Attitude Indicator RCA 2600-3	DHC-6-100/300	All	TMA	FAA TSO-C4c Authorisation for KMC Model RCA 2600 Electric Attitude Indicator	N/A	Adam	
2010-12-09	DHC-6	2010	17	Installation of Wipair Executive Seating System	DHC-6-300	597	TMA	FAA STC # SA02808CH and EASA STC # 10031133	N/A	Abdulla	
2011-01-04	DHC-6	2011	01	Relocation of Main Battery to Nose Compartment	DHC-6-100/200/300 Series	All	MAT	TC data sheet No. LBA 2034 Rev.09 AIRplus design Organization Handbook	N/A	Shifzan	
2011-01-09	DHC-6	2011	02	Installation of a nine passenger executive seating system	DHC-6-300	375	MAT	FAA approved STC No. SA02808CH	N/A	Shifzan	
2011-01-11	DHC-6	2011	03	Installation of Garmin 400w/500w Series	DHC-6-100/200/300 Series	All	MAT	FAA STC No. SA01933LA-D	N/A	Shifzan	
2011-04-03	DHC-8	2011	04	Installation of Class Divider	DHC-8-200	All	IASL	IASL Engineering report # Q2BCC01-200	N/A	Abdulla	
2011-04-10	DHC-6	2011	05	Stretcher Rack Installation	DHC-6-100/200/300 Series	All	MAT	TC STC No. SA01-97 and Aero Consulting Services Ltd Information Manual	N/A	Shifzan	
2011-04-20	DHC-6	2011	06	Cabin Heating Duct Removal	DHC-6-100/200/300 Series	All	MAT	MAT Mod no: MAT/2011/MOD/06 Document: "Replacing Cabin Heating Ducts with KYDEX Material"	N/A	Ibrahim/Shifzan	
2011-04-28	DHC-6	2011	07	Installation of Whelen Anti Collision Lights	DHC-6-100/200/300 Series	All	MAT	FAA STC No. SA615EA	N/A	Adam	
2011-05-09	DHC-6	2011	08	Installation of Whelen Landing Lights	DHC-6-100/200/300 Series	All	MAT	Whelen Engineering Documentations	N/A	Shifzan	
2011-05-29	DHC-6	2011	09	Installation of Fuel Cap Protection	DHC-6-100/200/300 Series	All	MAT	MAT own design and as per DHC-6-100/200/300 Series Structural Repair Manual	N/A	Adam	
2011-06-06	DHC-6	2011	10	Wipaire cabin VIP interior modification	DHC-6-300	283	MAT	FAA STC SA02808CH	N/A	Sinwaan	
2011-06-09	DHC-6	2011	11	Installation of Cabin Evacuation Lightings	DHC-6-300	283	MAT	Transport Canada STC# SA01-17 Issue 2	N/A	Ibrahim/Abdulla	
2011-06-09	DHC-6	2011	12	Installation of an Amphibian Landing Gear Position Advisory System	DHC-6-300	283	MAT	FAA STC SA39CH	N/A	Abdulla	
2011-06-15	DHC-6	2011	13	Installation of ATPST57 cabin interior kit	DHC-6-300	273	MAT	TC STC # SA08-71 dated August 14, 2008	N/A	Sinwaan	
2011-03-13	DHC-6	2011	14	Elevator Trailing Edge Replacement	DHC-6	449-L22	MAT	TC STC # SA01-135 dated October 31, 2001	N/A	Sinwaan	
2011-06-29	B767	2011	15	Cabin Reconfiguration	B767-3P6ER	24496	MGA	SR Technics (EASA.21J.358) Classification and Certification Sheet # C.OSMD.000147-CCS	N/A	Somith	
2011-07-10	DHC-6	2011	14R1	Elevator Trailing Edge Replacement	DHC-6-100/200/300	as per agreement with RMA	MAT	TC STC # SA01-135 dated October 31, 2001	N/A	Abdulla	

2011-07-12	DHC-8	2011	04R1	Installation of Class Divider	DHC-8-200/315	All	IASL	IASL Engineering report # Q2CD501-DHC	DHC-8/2011/04	Shifzan	
2011-07-28	DHC-6	2011	16	Installation of Wipair Executive Seating System	DHC-6-300	657	TMA	FAA STC # SA02808CH and EASA STC # 10031133	DHC-6/2010/17	Abdulla	
2011-09-08	DHC-6	2011	17	Installation of Vista Vents	DHC-6-300/400	All	TMA	TMA modification bulletin TMA 56-001	N/A	Abdulla	
2011-09-26	B767	2011	18	Installation of uQAR Quick Access Reader	B767-3P6ER	24496	MGA	FAA STC #ST02776AT	N/A	Abdulla	
2011-10-02	B767	2011	15R1	Cabin Reconfiguration	B767-3P6ER	24496	MGA	SR Technics (EASA.21J.358) Classification and Certification Sheet # C.OSMD.000147-CCS	B767/2011/15	Ibrahim	
2011-10-13	DHC-8	2011	19	Installation of Passenger Sliding Window Blinds	DHC-8-200/300	All	IASL	TC STC # SA98-48 dated August 03, 2011	N/A	Abdulla	
2011-11-02	DHC-6	2011	20	Installation of Sandel Avionics SN3500 EHSI	DHC-6-300	All	TMA	TMA Modification Bulletin TMA 34-004	N/A	Abdulla	
2011-12-01	DHC-6	2011	21	Rain Protection - Cabin Door	DHC-6-100/200/300	All	MAT	TMA Modification document # MAT/2011/MOD/20	N/A	Abdulla	
2011-12-12	DHC-6	2011	22	Chip Detector Indication System	DHC-6-100/200/300	All	MAT	Western Avionics Drawing # 35397-001	N/A	Abdulla	
2011-12-26	DHC-8	2008	03R1	Installation of PLB Holder	DHC-8-200/300	All	IASL	IASL Engineering Order # DASH 8-25-04R1	DHC-8/2008/03	Abdulla	
2012-02-06	B767	2012	01	Installation of uQAR Quick Access Reader	B767-300	All	MGA	FAA STC #ST02776AT	B767/2011/18	Abdulla	
2012-02-13	DHC-6	2012	02	Installation of Whelen Beacon Light	DHC-6-300	All	TMA	TMA Modification Bulletin TMA 33-002 and FAA STC SA615EA	N/A	Abdulla	
2012-02-13	DHC-6	2012	03	Installation of Whelen Anti Collision Strobe Light System	DHC-6-300	All	TMA	TMA Modification Bulletin TMA 33-001 and FAA STC SA800EA	N/A	Ibrahim	
2012-03-13	DHC-6	2012	04	Installation of Garmin GTX330 Transponder	DHC-6-300	All	TMA	ETSO EASA.IM.210.1254	N/A	Adam	
2012-03-13	DHC-6	2012	05	Installation of Garmin GTS800 Traffic Advisory System	DHC-6-300	All	TMA	FAA STC SA02016SE-D and ETSO EASA.IM.210.1057	N/A	Adam	
2012-03-13	DHC-6	2012	06	Installation of Attitude Indicator RCA 2600-3	DHC-6-100/200/300	All	MAT	FAA TSO-C4c Authorisation for KMC Model RCA 2600 Electric Attitude Indicator	N/A	Adam	
2012-03-13	DHC-6	2012	07	Installation of Garmin GTX330 Transponder	DHC-6-100/200/300	All	MAT	ETSO EASA.IM.210.1254	N/A	Adam	
2012-08-23	B757	2012	08	Cabin Reconfiguration	B757-204	25623	MGA	Cabin Reconfiguration MOD-1231 by AedoDec (EASA.21J.307)	N/A	Ibrahim	
2012-09-09	B767	2012	09	Cabin Reconfiguration	B767-30YER	26206	MGA	Main Passenger Cabin Interior Arrangement Engineering Authorization Doc No: 76L2521849 Revision 3 dated 5 September 2012 by Jossair Company, FAA Form 8110-3 dated 9 September 2012, FAA DER Ref: DERT-510352-CE	N/A	Ibrahim	
2012-10-18	A320	2012	10	Cabin Reconfiguration	A320-214	2347	IASL	A320 MSN 2347 Cabin Reconfiguration AFSB-A320-12-015-25-001 Revision 00 by Air France under Societe AIR FRANCE DO Approval EASA.21J.027	N/A	Ibrahim	
2012-10-22	B767	2012	09R1	Cabin Reconfiguration	B767-30YER	26206	MGA	Main Passenger Cabin Interior Arrangement Engineering Authorization Doc No: 76L2521849 Revision 5 dated 16 October 2012 by Jossair Company, FAA Form 8110-3 FAA DER Ref: DERT-510352-CE	MOD/B767/2012/09	Ibrahim	
2012-11-01	DHC-6	2012	11	Major Repair - Stringer repair on SIE Wing Assy S/N 302	DHC-6-300	All	MAT	FAA STC SA00364LA and SIE EO #SIE-23-940 Rev. V	N/A	Abdulla	
2012-11-13	A320	2012	12	Installation of PLB and Holder	A320-214	2347	IASL	IASL Modification Bulletin No. A320X-25-01	N/A	Abdulla	
2012-11-14	A320	2012	13	Installation of Stretcher System on A320-214	A320-214	2347	IASL	EASA STC No. 10031757, Rev 4	N/A	Abdulla	
2012-12-02	DHC-6	2012	14	Repair for corrosion on stringer and doubler	DHC-6-300	256	MAT	REO6-57-V114 Corrosion on Stringer, C6W1021-31, and Doubler, C6W1022-27, at Yw89.15 LHS Lower Surface of Wing C6W1002-59, approved in accordance with Transport Canada DAO No. 04-V-02	N/A	Ibrahim	

2012-12-09	A320	2012	15	Installation and Removal of SICMA Leg Rest Assy	A320-214	2347	IASL	IASL Modification Bulletin No. A320X-25-03	N/A	Abdulla	
2012-12-13	B757	2012	16	Installation of L3 MicroQAR	B757-204	25623	MGA	FAA STC: STC02679AT	N/A	Ibrahim	
2013-01-05	DHC-6	2013	01	Electric Motor and Hydraulic Pump Replacement	DHC-6-100/200/300	All	MAT	FAA STC: SA104075C	N/A	Abdulla	
2013-02-19	DHC-6	2013	02	Repair of Corrosion on Stringer	DHC-6-300	659	MAT	Viking REO 6-57-V115. Applicable to wing P/N C6W1002-59, S/N VAL0033	N/A	Abdulla	
2013-03-10	DHC-8	2013	03	Replacement of UNS-1B Management System with UNS-1Lw	DHC-8-200	429	IASL	Australian Avionics Pty Ltd EO No. AA1676-02-01 Rev 0	N/A	Shifzan	
2013-03-25	A320	2013	04	Installation of Donica Digital Media Reproducer type number AE-DMR300	A320-214	2347	IASL	EASA STC No. 10039614, Rev 5	N/A	Shifzan	
2013-06-05	C150	2013	05	Replacement of engine oil screen with an external mounted filter	C150	All	AAA	FAA STC no: SE4315NM	N/A	Abdulla	
2013-06-13	B767	2013	06	AFIRS 228 Automated Flight Information Reporting System Installation (Provisions)	B767-30YER	26206	MEGA	Transport Canada STC: SA12-67, Issue No: 1	N/A	Ibrahim	
2013-08-06	B767	2013	06R1	AFIRS 228 Automated Flight Information Reporting System Installation (Provisions)	B767-300	26206, 24496	MGA	Transport Canada STC: SA12-67, Issue No: 1	B767/2013/06	Shifzan	
2013-08-18	B767	2013	07	Deactivation of Standalone UNS-1Fw FMS	B767-3P6ER	24496	MGA	Avionics Support Group EO213144-1, Rev: IR and DER Services Inc. Dwg. A2013-061-101	N/A	Abdulla	
2013-09-02	B767	2013	06R2	AFIRS 228 Automated Flight Information Reporting System Installation (Provisions)	B767-300ER	26206, 24496	MGA	Transport Canada STC No. SA12-67, Issue No.2	B767/2013/06	Shifzan	
2013-09-22	DHC-6	2013	08	14V Power System and Storage Pouch	DHC-6-300	All	TMA	FAA TSO C-71, RTCA DO-160d	N/A	Shifzan	
2013-09-27	DHC-8	2013	09	Installation of Wardrobe Trolley Securing Device	DHC-8-314	499	IASL	IASL EO Q2/DHC8/EO/002 Parts 1 and 2	N/A	Abdulla	
2013-12-02	DHC-8	2013	10	Temporary repair of frangible switch cover	DHC-8-315	491	IASL	IASL EO # Q2/DHC8/EO/006	N/A	Abdulla	
2014-02-10	B767	2014	1	De-Activation of PRAM	B767-300ER	26206	MEGA	Deactivation of PRAM Engineering Order by Aerospace Design & Engineering Consultants Pte Ltd, approved by DERT-510389-CE.	N/A	Aflaam	
2014-02-16	PW127	2014	2	Main Harness, heat shrinkable sleeve repair of PW127F Engine	PW127 Engine	AV0050	VA	Minor repair EBR 00121941 by Lufthansa Technik DOA EASA.21J.019	N/A	Ibrahim	
2014-06-11	DHC-6	2014	3	Relocation of Voltage Regulator	DHC-6-300	ALL	IASL	IASL EO # Q2/DHC6/EO/002	N/A	Yooshau	
2014-06-12	DHC-6	2014	4	Installation of two Meradyne model 3200 cabin fans	DHC-6-300	ALL	IASL	IASL EO # Q2/DHC6/EO/001	N/A	Shifzan	
2014-06-26	DHC-6	2014	5	Installation of Pc Safety Valve Kit	DHC-6-300	ALL	IASL	Transport Canada STC No. SE00-9 Issue No.1	N/A	Shifzan	
2014-07-24	DHC-6	2014	6	Installation of Wipaire Model 100 Seaplane Floats	DHC-6-200/300	As per Wipaire Authorisation	IASL	FAA STC No. SA2CH	N/A	Abdulla	
2014-08-07	DHC-6	2010	06R1	Installation of Wipaire Model 13000 Amphibious or Model 1300 Seaplane Floats	DHC-6-100/200/300/400	As per Wipaire Authorisation	TMA	Transport Canada STC: SA93-103 & Transport Canada STC: SA11-7	MOD-DHC6-2010-06	Ibrahim	
2014-08-18	DHC-6	2014	07	Fuel Cap Protection	DHC-6-100/200/300	ALL	IASL	IASL EO # Q2/DHC6/EO/003	N/A		
2014-08-18	DHC-6	2014	08	Cabin Blower Fan Installation	DHC-6-100/200/300	ALL	IASL	IASL EO # Q2/DHC6/EO/004	N/A		
2014-09-03	DHC-6	2014	09	DHC-6 LH Wing Stringer Damage Repair	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-001-0.R issued on 2-Aug-2014 and Data Documents 14K002-RP-001-0.R, 14K002-CCS-001-0.R, 14K002-SSR-001-0.R and 14K002-GA-001-0.R	N/A	Ibrahim	
2014-09-03	DHC-6	2014	10	DHC-6 RH Wing #05 and #06 Stringer Damage Repair	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-002-0.R issued on 4-Aug-2014 and Data Documents 14K002-RP-002-0.R, 14K002-CCS-002-0.R, 14K002-SSR-002-0.R and 14K002-GA-002-0.R	N/A	Ibrahim	

2014-09-03	DHC-6	2014	11	DHC-6 RH Wing #01 Stringer Damage Repair	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-003-0.R issued on 5-Aug-2014 and Data Documents 14K002-RP-003-0.R, 14K002-CCS-003-0.R, 14K002-SSR-003-0.R and 14K002-GA-003-0.R	N/A	Ibrahim	
2014-09-03	DHC-6	2014	12	DHC-6 RH Wing Top Skin Damage Repair	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-004-0.R issued on 12-Aug-2014 and Data Documents 14K002-RP-004-0.R, 14K002-CCS-004-0.R, 14K002-SSR-004-0.R and 14K002-GA-004-0.R	N/A	Ibrahim	
2014-09-03	DHC-6	2014	13	DHC-6 LH Wing Top Skin Damage Repair	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-005-0.R issued on 17-Aug-2014 and Data Documents 14K002-RP-005-0.R, 14K002-CCS-005-0.R, 14K002-SSR-005-0.R and 14K002-GA-005-0.R	N/A	Ibrahim	
2014-10-13	DHC-6	2014	14	Repair - Wing Leading Edge Corrugation Damage	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K002-CSS-007-0.R	N/A	Abdulla	
2014-10-13	DHC-6	2014	15	Repair - Wing Rear Spar Damage	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K002-CSS-008-0.R	N/A	Abdulla	
2014-10-15	DHC-6	2014	16	Repair - Wing Leading Edge Corrugation Damage	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K002-CSS-006-1.R	N/A	Abdulla	
2014-11-18	B757	2014	17	AFIRS 228 Installation (Provisions)	B757-204	25623	MEGA	Transport Canada STC: SA14-39, Issue 1 issued to FLYHT Aerospace Solutions Ltd.	N/A	Ibrahim	
2015-04-06	B757	2014	17R1	AFIRS 228 Installation (Provisions)	B757-204	25623	MEGA	Transport Canada STC: SA14-39, Issue 2 issued to FLYHT Aerospace Solutions Ltd.	N/A	Shifzan	
2014-12-03	DHC-6	2014	18	Stabilizers - Horizontal Stabilizer Skins and Rear Spar Repair	DHC-6 Horizontal Stabilizer and Rear Spar C6TP1004 and C6TP1016	All	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K110 RP-001-0.R	N/A		
2015-01-13	DHC-6	2015	01	Repair - Wing Main Spar Fitting	DHC-6 Wing C6W1001-27	449	TMA	FAA STC No. SA00364LA and TC STC No. SA97-100	N/A		
2015-01-20	DHC-6	2015	02	Repair - Wing Stringer Damage	DHC-6 Wing C6W1001-27	ALL	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K141 RP-001-0.R	N/A	Yooshau	
2015-01-25	DHC-6	2015	03	Elevator Replacement Trailing Edge	DHC-6-100/200/300	ALL	TMA	Transport Canada STC: SA01-135 Issue 1, 31 October 2001	N/A	Ibrahim	Requested for LH Elevator SN 70079, RH Elevator SN 70059
2015-02-03	DHC-6	2015	04	LH Wing Stringer (# 01) Damage Repair	DHC-6 Wing C6W1001-25	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-001-0.R	N/A	Shifzan	
2015-02-03	DHC-6	2015	05	RH Wing Stringer (# 4, 5 & 8) Damage Repair	DHC-6 Wing C6W1001-27	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-001-0.R	N/A	Shifzan	
2015-02-03	DHC-6	2015	06	LH Wing Stringer (# 5, 7 & 8) Damage Repair	DHC-6 Wing C6W1001-25	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-006-0.R	N/A	Shifzan	
2015-02-04	DHC-6	2015	07	EFB Container	DHC-6 Cockpit	All	TMA	TMA Modification Bulletin TMA 25-002 - EFB Container TMA Drawing TMA 25-002-DR001 - EFB Container TMA Maintenance Manual Supplement TMA 25-002-01 - EFB container	N/A	Aflaam	
2015-02-26	DHC-6	2015	08	DHC-6-300 W.S. 58 Wing Main Spar Web Slice	DHC-6-300 Wing Boxes 1. LHS; PN: C6W1002-21 2. RHS; PN: C6W1002-23	DHC-6-300 Wing Boxes 1. LHS; SN: 210110 2. RHS; SN: 230120	TMA	SIE Drawing SIE-23941 and FAA Form 8110-3 dated 6th February 2015	N/A	Ibrahim	
2015-03-01	DHC-6	2015	09	8Q-TMU RH Wing Top Skin Damage Repair	DHC-6 Wing C6W1001-27	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112 RP-005-0.R	N/A	Yooshau	

2015-03-01	DHC-6	2015	10	8Q-TMU LH Wing Top Skin Damage Repair	DHC-6 Wing C6W1001-25	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112 RP-002-0.R	N/A	Yooshau	
2015-03-02	DHC-6	2015	11	First Aid Kit (FAK) Stowage Installation	DHC-6	All	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 15K035-CCS-001-0.R	N/A	Ibrahim	
2015-03-11	DHC-6	2015	12	Wing Main Spar Splice Repair	DHC-6 Wing C6W1001-27	467-L23	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-004-0.R	N/A	Abdulla	
2015-04-23	DHC-6	2015	12R1	Wing Main Spar Splice Repair	DHC-6 Wing	Refer to Doc 15K038-CCS-001-1.R	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 15K038-CCS-001-1.R	N/A	Aflaam	
2015-03-12	DHC-6	2015	13	De-Activation of Beta Back-up system	DHC-6-100/300	All	IASL	Transport Canada STC: SA02-58 Issue 02 , 19 July 2002	N/A	Yooshau	
2015-03-17	DHC-6	2015	14	Installation of Sun Visor Clip	DHC-6	All	TMA	TMA Modification Bulletin No. TMA-25-003	N/A	Abdulla	
2015-03-19	DHC-6	2015	15	Removal of Bleed Air, Cabin Heat & Engine Intake Deflectors	DHC-6-100/200/300	AS per KBAL IN 395.01	IASL	Transport Canada STC: SA09-62 Issue 02, 03 September 2009	N/A	Aflaam	
2015-04-28	DHC-6	2015	16	Fuel Gallery Corrosion Protection	DHC-6-100/200/300	All	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 15K041-CCS-001-0.R	N/A	Shifzan	
2015-07-09	DHC-6	2015	17	Relocation of Main Battery and External Power Receptacle to Nose Compartment	DHC-6	As per KNSI document # 15K079-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K079-CCS-001-0.R Rev 7	MOD/DHC-6/2011/01	Abdulla	
2015-07-30	DHC-6	2015	18	Repair - DHC-6 Fore Flap Hinge Arm	DHC-6	As per KNSI document # 15K116-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K116-CCS-001-0.R	N/A	Abdulla	
2015-07-30	DHC-6	2015	19	Repair - Elevator Trim Cable Bracket	DHC-6	As per KNSI document # 15K117-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K117-CCS-001-0.R	N/A	Abdulla	
2015-07-30	DHC-6	2015	20	Repair - Wing Skin and Stringer	DHC-6	As per KNSI document # 15K165-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K165-CCS-001-0.R and 15K165-CCS-002-0.R	N/A	Abdulla	
2015-10-11	DHC-8	2013	03R1	Replacement of UNS-1B Management System with UNS-1Lw	DHC-8-200 DHC-8-314	DHC-8-200 MSN 429 DHC-8-314 MSN 591	IASL	Australian Avionics Pty Ltd EO No. AA1676-02-01 Revidion 0 Hawker Pacific Pty Ltd T/A Australian Avionics EO No. AA2112-02-01 Revision 0	MOD/DHC-8/2013/03	Ibrahim	
2015-10-11	DHC-6	2015	21	Rain Protection - Installation of Rain Gutter	DHC-6	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K226-CCS-001-0.R	N/A	Yooshau	
2015-10-15	DHC-8	2015	22								
2015-10-22	DHC-8	2015	23	Installation of Wardrobe Trolley Securing Device	DHC-8-314	591	IASL	IASL EO Q2/DHC8/EO/002 Parts A, B & C	N/A	Aflaam	
2015-11-02	B767	2015	24	Installation of Fifth Lavatory	B767-300ER	27959	MEGA	VT Volant EO 1501-EO-01 Rev B DER NO. DERT-510326-CE	N/A	Shifzan	
2015-11-17	DHC-6	2015	25	Repair - Horizontal Stabiliser Lower Skin	DHC-6	As per KNSI document # 15K237-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K237-CCS-001-0.R	N/A	Abdulla	
2015-11-22	DHC-8	2015	26	Installation of Passenger Briefing System DMP-200	DHC-8-200/300	All	IASL	FAA STC #: ST01820NY IASL EO #: Q2DHC8EO009	N/A	Abdulla	
2015-12-03	B767	2015	24R1	Installation of Fifth Lavatory	B767-300ER	27959	MEGA	VT Volant EO 1501-EO-01 Rev B dated 10/15/2015 (DER NO. DERT-510326-CE) & 1501-ECO-REV-B-MDL-01 Rev C dated 02/12/2015	MOD/B767/2015/24	Yooshau	
2015-12-16	DHC-6	2015	27	Wing stringer repair	DHC-6-300	751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K277-CCS-001-0.R	N/A	Abdulla	
2015-12-16	B767	2015	28	Cabin Reconfiguration	B767-300	24496	MEGA	EASA.21J.358 SR Technics CCS document # C.OAED.000453-CCS	N/A	Abdulla	

2016-01-27	DHC-6	2016	01	Installation of Infant Life Vest Pouch	DHC-6	As per KNSI Change Bulletin 16K009-CB-001-0.R Rev 8	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 16K009-CB-001-0.R	N/A	Ibrahim	
2016-02-22	DHC-6	2016	02	Installation of LED Beacon Light	DHC-6	All	IASL	FAA STC #: SA615EA	N/A	Shifzan	
2016-02-25	DHC-6	2016	03	Wipaire cabin VIP interior modification	DHC-6-300	571	TMA	C-LSA06-289/D	N/A	Shifzan	
2016-03-08	B767	2016	04	PRAM Relocation	B767-300ER	27959	MEGA	E4C Technologies E02321-004 DERT No. DERT-605221-NM	N/A	Aflaam	
2016-03-08	DHC-6	2016	05	Installation of LED Landing Light	DHC-6-100/200/300	All	IASL	FAA STC #: SA02212AK IASL EO #: Q2/DHC6/EO/009	N/A	Shifzan	
2016-03-09	B767	2015	24R2	Installation of Fifth Lavatory	B767-300ER	27960	MEGA	VT Volant EO 1501-EO-01 Rev E dated 28/01/2016 (DER NO. DERT-510326-CE)	MOD/B767/2015/24 and MOD/B767/2015/24R1	Shifzan	
2016-03-12	B767	2013	06R3	Installation of AFIRS 228	B767-300ER	27959, 27960	MEGA	TC STC #: SA12-67 , Issue: 3	B767/2013/06 B767/2013/06R1 B767/2013/06R2	Shifzan	
2016-03-16	DHC-6	2016	06	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6-300	Wingbox SN 210053 and 230057	TMA	FAA STC #: SA00364LA	N/A	Abdulla	
2016-04-03	DHC-6	2016	07	Cargo Net Installation	DHC-6	As per KNSI CB 15K188-CB-001-0.R Rev 8	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd., document # 15K188-CB-001-0.R	N/A	Ibrahim	
2016-04-10	DHC-6	2016	08	Enhanced Air Conditioning System Installation	DHC-6	571	TMA	TC STC # SA16-33 dated March 19, 2016	N/A	Yooshau	
2016-04-25	DHC-6	2016	09	Removal of Bleed Air, Cabin Heat & Engine Intake Deflectors	DHC-6	As specified in EASA STC 10057361 Rev 8	TMA	EASA STC 10057361	N/A	Abdulla	
2016-05-11	B767	2013	06R4	AFIRS 228 Automated Flight Information Reporting System Installation	B767-300ER	24496, 26206, 27959, 27960	MEGA	TC STC #: SA12-67 , Issue: 3 Deviation DCN by STC Holder 185-0987 & 185-0994 for SN 27960	B767/2013/06 B767/2013/06R1 B767/2013/06R2 B767/2013/06R3	Ibrahim	
2016-05-11	B767	2015	24R3	Installation of Fifth Lavatory	B767-300ER	24496, 26206, 27959, 27960	MEGA	VT Volant EO 1501-EO-01 Rev E dated 28/01/2016 (DER NO. DERT-510326-CE) MSN:27959 - 1501-ECO-REV-B-MDL-01 Rev C dated 02/12/2015 MSN:27960 - 1501-ECO-01-020 Rev A MSN:27960 - 1501-ECO-01-021 Rev A MSN:27960 - 1501-ECO-01-022 Rev A MSN:27960 - 1501-ECO-01-023 MSN:27960 - 1501-ECO-01-024 MSN:27960 - 1501-ECO-01-025 MSN:27960 - 1501-ECO-01-026 MSN:27960 - 1501-ECO-01-027 MSN:27960 - EO2321-001E MSN:27960 - EO2321-002B MSN:27960 - EO2321-003	MOD/B767/2015/24 MOD/B767/2015/24R1 MOD/B767/2015/24R2	Aflaam	
2016-05-17	DHC-6	2016	10	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6	Wingbox SN 230152 and SN210153	TMA	FAA STC #: SA00364LA	MOD/DHC-6/2016/06	Aflaam	
2016-05-23	DHC-6	2016	10R1	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6-300	Wingbox SN 283	TMA	FAA STC #: SA00364LA	MOD/DHC-6/2016/06 MOD/DHC-6/2016/10	Shifzan	

2016-05-24	B767	2016	11	Cabin Interphone System Rewiring	B767-300ER	27959, 27960	MEGA	E4C Technologies EO2380-27959-01 and EO2380-27960-01 (DERT No. DERT-605048-CE)	MOD/B767/2015/24 MOD/B767/2015/24R1 MOD/B767/2015/24R2 MOD/B767/2015/24R2	Abdulla	
2016-06-05	DHC-8	2016	12	Installation of UNS - 1Ew & ADS-B Upgrade	DHC-8-315	544	IASL	EO Number AA2199-02-01, Rev 0	N/A	Shifzan	
2016-05-29	B767	2016	11R1	Cabin Interphone System Rewiring	B767-300ER	27959, 27960	MEGA	E4C Technologies EO2380-27959-01 and EO2380-27960-01 (DERT No. DERT-605048-CE) EO2380-27960-01A And EO2380-27959-01A	MOD/B767/2015/24 MOD/B767/2015/24R1 MOD/B767/2015/24R2 MOD/B767/2016/11	Aflaam	
2016-06-09	B767	2016	11R2	Cabin Interphone System Rewiring	B767-300ER	27959, 27960	MEGA	E4C Technologies EO2380-27959-01 and EO2380-27960-01 (DERT No. DERT-605048-CE) EO2380-27960-01A And EO2380-27959-01A MSN:27960 - EO2380-27960-01B	MOD/B767/2015/24 MOD/B767/2015/24R1 MOD/B767/2015/24R2 MOD/B767/2016/11R1	Aflaam	
2016-06-14	DHC-6	2016	13	Installation of new flap rollers	DHC-6	All	IASL	Swiss Federal Office for Civil Aviation STC # Z 27-50-03	N/A	Abdulla	
42556	DHC-6	2016	14	Installation of Document Holder	DHC-6	MSNs on Change Bulletin 16K203-CB-001-0.R Rev 7	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 16K203-CB-001-0.R	N/A	Yooshau	
42565	DHC-6	2015	13R1	De-Activation of Beta Back-up system	DHC-6-100/200/300	All	IASL	Transport Canada STC: SA02-58 Issue 03 , 18 May 2016	N/A	Abdulla	
42585	DHC-6	2016	15	Structural repair	DHC-6-300	Wingbox SNs: 503-L25	TMA	SIE Form 8110-3 dated 27 June 2016	N/A	Abdulla	
2016-08-17	B767	2016	16	Taxi Light Deactivation - Nose Landing Gear	B767-300ER	27959	MEGA	EASA.21J.575 365 Aerospace EO Revision A dated 5 AUG 2016	N/A	Abdulla	
2016-08-24	DHC-6	2016	17	Float Pump Bracket Installation	DHC-6	MSNs on Change Bulletin 16K197-CB-001-0.R or later revision	IASL	KNSI Change Bulletin 16K197-CB-001-0.R dated 21-July-2016	N/A	Ibrahim	
2016-08-25	DHC-6	2016	18	Installation of Card Holder On Control Yoke	DHC-6	MSNs on Change Bulletin 16K245-CB-001-0.R Rev 6	TMA	KNSI Change Bulletin 16K245-CB-001-0.R dated 11-Aug-2016	N/A	Shifzan	
2016-08-25	DHC-6	2016	19	Installation of window shield on RH Rear Cabin Door	DHC-6	MSNs on Change Bulletin 16K243-CB-001-0.R Rev 6	TMA	KNSI Change Bulletin 16K243-CB-001-0.R Dated 03-AUG-2016	N/A	Aflaam	
2016-08-28	DHC-6	2016	20	Repair - LH Wing Upper Skin	DHC-6	MSN # 44, Wing box P/N C6W1001-21, S/N 279	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K257-CCS-001-0.R	N/A	Shifzan	
2016-08-28	DHC-6	2016	21	Repair - RH Wing Stringer Corrosion	DHC-6	MSN # 44, Wing box P/N C6W1001-23 S/N 279	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K256-CCS-001-0.R	N/A	Shifzan	
2016-09-13	DHC-8	2016	22	Installation of DMP-200 MP3 Passenger Briefing System	DHC-8-200/300	MSNs on Change Bulletin 16K223-CB-001-0.R	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K223-CCS-001-0.R	N/A	Yooshau	

2016-09-22	DHC-6	2016	23	Vertical Stabilizer Skin Panel Disbonding - Generic Repair	DHC-6	MSNs on KNSI Doc. 16K240-RAD-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K240-CCS-001-0.R	N/A	Ibrahim	
2016-10-03	DHC-6	2016	24	Installation of Garmin GTS 800	DHC-6-100/200/300	All	IASL	Transport Canada STC: SA12-72 Issue No. 1 and FAA STC SA02016SE-D (22-June-2012) referred to therein	N/A	Ibrahim	
2016-10-03	DHC-6	2016	25	Wing Repair - Alternate Fasteners	DHC-6	MSNs on KNSI Doc. 16K265-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K265-CCS-001-0.R	N/A	Abdulla	
2016-10-06	DHC-6	2016	26	LH, RH Wing Corrosion Repair	DHC-6-300	MSN 375	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K283-CCS-001-0.R	N/A	Aflaam	
2016-10-20	DHC-6	2016	27	LH Wing Top Skin Doubler Reinforcement	DHC-6-300	MSN 597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K288-CCS-002-0.R	N/A	Shifzan	
2016-10-20	DHC-6	2016	10R2	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6-300	Wingbox SN 230049 & 210050	TMA	FAA STC #: SA00364LA	MOD/DHC-6/2016/06 MOD/DHC-6/2016/10 MOD/DHC-6/2016/10R1	Nabeel	
2016-10-26	DHC-6	2016	28	Wing Tip Cap Access Cut Out Doubler & Cover Panel Installation	DHC-6-300	MSNs on KNSI Doc. 16K285-CCS-001-1.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K285-CCS-001-1.R	N/A	Yooshau	
2016-11-10	DHC-8	2016	12R1	Installation of UNS - 1Ew & ADS-B Upgrade	DHC-8-314	503	IASL	EO Number AA2261-02-01, Rev 0	MOD/DHC-8/2016/12	Shifzan	
2016-11-13	DHC-8	2016	29	Extension of Baggage Compartment	DHC-8-314	503	IASL	EASA.21J.323 v-plane GmbH. Document # 216160-c-TO-2520-001-01	N/A	Nabeel	
2016-11-13	C150	2016	30	Installation of Oil Cooler	Continental O200 Engines Installed on C150L/M	All	AAA	FAA STC SA017685E Dated 8th June 2007	N/A	Ibrahim	
2016-11-17	DHC-6	2016	31	Installation of stretcher DHC-6-100/200/300	DHC-6-300	All	IASL	Transport Canada STC SA13-1 Issue 2, dated 27-02-2015	N/A	Yooshau	
2016-11-19	DHC-6	2016	32	Stringer corrosion repair	DHC-6-300	597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K288-CCS-001-0.R	N/A	Abdulla	
2016-11-21	DHC-6	2016	33	Installation of APC starter generator	DHC-6-300	499, 722	TMA	FAA STC # SA390NE	N/A	Abdulla	
2016-12-20	DHC-6	2016	34	LH Wing - Stringers corrosion splice repair	DHC-6-300 C6W1001-25	597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K323-CCS-001-1.R	N/A	Nabeel	
2017-01-17	DHC-6	2017	01	LH Wing - Top skin doubler extension	DHC-6-300	597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K345-CCS-001-0.R	N/A	Abdulla	
2017-01-26	DHC-6	2017	02	Installation of Wipaire Executive Seating System	DHC-6-200	146	TMA	FAA STC SA02808CH IAW Wipaire, Inc. Drawing 1004310	DHC-6/2011/16	Yooshau	
2017-01-31	DHC-6	2017	03	Installation of Two "MARADYNE" Fans in Passenger Compartment	DHC-6-100/200/300/400	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K338-SADD-004-0.R	N/A	Shifzan	
2017-02-09	DHC-6	2017	04	Installation of Crash Axe	DHC6	All MSNs stated on KNSI CB 16K346-CB-001-0.R Rev7	TMA	EASA.21J.560 KNSI Aviation Engineering Lrd. Document SADD # 16K346-SADD-001-0.R	N/A	Ibrahim	
2017-02-19	DHC-6	2017	05	RH Wing - Stringer splice repair	DHC-6-300	561	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K006-CCS-001-0.R	N/A	Nabeel	
2017-02-19	ATR	2017	06	Replacement Overhead Bin Hooks on ATR 42/72	ATR-42/72	All	Villa	EASA.21J.482 ASI Innovation Approval Sheet 20160039	N/A	Abdulla	
2017-02-20	DHC-6	2017	07	Wings - Main Spar Web Splice Repair	DHC-6-300	MSN: 597, Wing Assy P/N: C6W1001-25, C6W1002-21 S/N: 597L29	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 16K337-SADD-001-1.R	N/A	Ibrahim	
2017-03-22	A321	2017	08	INSTALLATION OF THE CURTAIN ON L/H MOVABLE CLASS DIVIDER GLASS WINDOW.	A321-211	2599	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 17K008-SADD-001-1R	N/A	Shifzan	

2017-04-09	DHC-6	2017	09	Installation of Bendix King KN63 DME System	DHC-6-200	146	TMA	EASA.21J.085 AirPlus Document APPN 1942, Issue 2	N/A	Nabeel	
2017-04-26	DHC-6	2017	10	Replacement of existing Audio Panels with Dual NAT AMS 43 System on 8Q-TMU	DHC-6-300	467	TMA	EASA.21J.085 AirPlus Document APPN 1944, Issue 1	N/A	Yooshau	
2017-05-03	DHC-6	2017	11	Aluminium Tape Installation to Prevent Sea Water Ingress into Fuel Gallery and Components	DHC6	All MSNs stated on KNSI CB 17K097-CB-001-0.R Rev4	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 17K097-SADD-001-0.R	N/A	Ibrahim	
2017-05-03	DHC-6	2017	12	Fuel Quantity Indicating System Replacement	DHC-6-100/200/300	MSN 687	TMA	Transport Canada STC SA15-44	N/A	Abdulla	
2017-05-11	DHC-6	2017	13	LH Wing Stringer #5 Splice Repair	DHC-6-200	146	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 17K123-SADD-001-0.R	N/A	Shifzan	
2017-05-18	DHC-6	2017	14	Installation of Cockpit Life Vest Pouch	DHC-6	As per KNSI Change Bulletin 17K096-CB-001-1.R Rev6	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K096-SADD-002-0.R	N/A	Yooshau	
2017-05-24	DHC-6	2017	15	Emergency Torch Pouch Installation	DHC-6	All MSNs stated on KNSI CB 17K081-CB-001-0.R Rev4	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document SADD # 17K081-SADD-001-0.R	N/A	Ibrahim	
2017-06-20	DHC-6	2017	16	Fabrication and Installation of Cockpit Life Vest Pouch	DHC-6	As per KNSI Change Bulletin 17K110-CB-001-0.R	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K110-SADD-001-0.R	N/A	Nabeel	
2017-07-16	DHC-6	2017	17	LH & RH Wings Stringer # 5 Splice Repair	DHC-6	256	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. SADD # 17K152-SADD-001-0.R	N/A	Shifzan	
2017-08-06	DHC-6	2017	18	Installation of Garmin G950 Integrated Flight Deck System	DHC-6-100/200/300	256	TMA	Transport Canada STC SA15-76	N/A	Nabeel	
2017-08-13	DHC-8	2017	19	Upgrade of TCAS 7.0 to 7.1	DHC-8-315	491	IASL	EASA STC 10051448	N/A	Nabeel	
2017-09-02	DHC-8	2017	20	Universal FSM Upgrade & ADS-B Enablement	DHC-8-315	491	IASL	Hawker Pacific Avionics Design Data Approved under CASR 21.M Validation Report Ref: AA2308-20-01 R0	N/A	Ibrahim	
2017-09-06	DHC-6	2017	18R1	Installation of Garmin G950 Integrated Flight Deck System	DHC-6-100/200/300	582, 781	TMA	Transport Canada STC SA15-76	MOD/DHC-6/2017/18	Nabeel	
2017-09-17	DHC-6	2017	21	Installation of Electronics International MVP-50T Engine Display System	DHC-6-300	687	TMA	TCCA STC Number SA12-13	N/A	Abdulla	
2017-09-20	DHC-6	2017	22	Fuselage - Fuel drain valve cap installation	DHC-6-300	As per KNSI Change Bulletin 17K209-CB-001-0.R Rev2	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K209-SADD-001-0.R	N/A	Yooshau	
2017-10-08	DHC-8	2017	19R1	Upgrade of TCAS 7.0 to 7.1	DHC-8-314	591	IASL	EASA STC 10051448	MOD/DHC-8/2017/19	Abdulla	
2017-10-10	DHC-6	2017	23	Installation, Fuselage Plug for Airstair Doors, Enlarged Cargo Door Aircraft	DHC-6-300	687	TMA	TCCA STC Number SA12-13	N/A	Ibrahim	
2017-10-23	DHC-6	2017	24	Equipment & Furnishing - Infant Life Vest Pouch installation	DHC-6-300	As per KNSI Change Bulletin 17K222-CB-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K222-SADD-001-0.R	MOD/DHC-6/2016/01	Yooshau	
2017-10-31	DHC-6	2017	25	CVR Installation	DHC-6-300	493	TMA	TCCA STC Number SA97-101	N/A	Shifzan	
2017-11-08	DHC-6	2017	26	Re-Life of the Viking Air Limited DHC-6 fuselage, horizontal stabilizer and vertical stabilizer	DHC-6-300	279	TMA	FAA STC SA02380LA	N/A	Abdulla	
2017-11-13	DHC-6	2017	27	LH and RH Wing Stringer #2,3,4,5,7 & 8 Splice Repair	DHC-6-300	663	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K275-SADD-001-0.R	N/A	Nabeel	
2017-11-13	DHC-6	2017	28	Replacement of audio panels with AMS 43	DHC-6-300	663	TMA	EASA.21J.085 AirPlus Maintenance GmbH approval number APPN 1944, Issue 1	N/A	Abdulla	
2017-11-22	DHC-6	2017	02R1	Installation of Wipaire Executive Seating System	DHC-6-200/300/400	As per STC holder authorisation	TMA	FAA STC SA02808CH	MOD/DHC-6/2017/02	Shifzan	2021-07-14 Applicability revised. Refer 201-ASD-200/TMA/2021/07

2017-11-22	DHC-6	2017	28R1	Replacement of audio panels with AMS 43	DHC-6-300	687	TMA	EASA.21J.085 AirPlus Maintenance GmbH approval number APPN 1944, Issue 1	MOD/DHC-6/2017/28	Yooshau	
2017-11-26	A320	2017	29	Installation of new ownership plates on A320	A320	2347	IASL	EASA.21J.358 SR Technics CCS document # C.OSMD.000188-CCS	N/A	Abdulla	
2017-11-27	DHC-8	2017	30	Water tank and coffee maker de-modification	DHC-8-315	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K224-SADD-001-0.R	N/A	Nabeel	
2017-11-28	DHC-6	2016	17R1	Float Pump Bracket Installation	DHC-6	MSNs on Change Bulletin 16K197-CB-001-2.R	IASL	KNSI Change Bulletin 16K197-CB-001-0.R dated 28-September-2017	MOD/DHC-6/2016/17	Yooshau	
2017-12-05	DHC-6	2017	31	LH Wing Stringer Splice Repair	DHC-6	283	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document #17K305-CCS-001-0.R dated 25-November-2017	N/A	Shifzan	
2017-12-09	DHC-8	2017	32	Environmental Control System Performance Improvement Modification	DHC-8	As per STC holder authorisation	IASL	Transport Canada STC SA00-69	N/A	Abdulla	
2017-12-12	DHC-8	2017	33	Lead Acid battery to NiCad battery de-modification	DHC-8	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K288-SADD-001-0.R	N/A	Nabeel	
2017-12-26	DHC-8	2017	19R2	Upgrade of TCAS 7.0 to 7.1	DHC-8-315	582	IASL	FAA STC ST00881WI-D	MOD/DHC-8/2017/19	Yooshau	
2017-12-28	DHC-8	2017	34	Hot Jug Installation on 8Q-IAA	DHC-8-315	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K286-SADD-001-0.R dated 18-December-2017	N/A	Ibrahim	
2017-12-30	DHC-6	2017	18R2	Installation of Garmin G950 Integrated Flight Deck System	DHC-6-100/200/300	As per STC holder authorisation dated 27-Apr-21	TMA	Transport Canada STC SA15-76	MOD/DHC-6/2017/18R1	Abdulla	
2018-01-30	DHC-6	2018	01	Installation Of Velcro On Cockpit, Cabin Swing And Cabin Air Stair Doors for Intruder Detection System	DHC-6-300	798	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K340-SADD-001-0.R	N/A	Shifzan	
2018-01-31	DHC-6	2017	16R1	Fabrication and Installation of Cockpit Life Vest Pouch	DHC-6-200/300	As per KNSI Change Bulletin 17K110-CB-001-1.R	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K110-SADD-002-0.R	MOD/DHC-6/2017/16	Nabeel	
2018-02-12	DHC-6	2018	02	Aft Cargo Door Lock Modification	DHC-6-100	44	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K039-SADD-002-0.R	N/A	Yooshau	
2018-02-19	DHC-8	2018	03	Universal FSM Upgrade & ADS-B Enablement	DHC-8-315	582	IASL	Hawker Pacific Avionics Validation Report Ref: AA2357-20-01R1	N/A	Ibrahim	
2018-02-26	DHC-6	2018	04	Installation of Safety Valve Kit	DHC-6-100/200/300	All	TMA	FAA STC # SE02170AT. Aeronautical Accessories Report No. AA-99090 Revision A	N/A	Shifzan	
2018-02-28	DHC-8	2018	05	Aft Cargo Compartment Expansion	DHC-8-315	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K001-SADD-001-0.R	N/A	Nabeel	
2018-02-28	DHC-6	2018	06	Installation of new LED landing Lights	DHC-6-100/200/300	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K018-SADD-004-0.R	N/A	Yooshau	
2018-03-11	DHC-6	2018	07	RH Wing Inboard Flame Track Doubler Extension	DHC-6-300	270	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K064-SADD-002-0.R	N/A	Nabeel	
2018-03-12	DHC-6	2018	08	Removal of Ashtray Assy bracket of the control colummn	DHC-6-100/200/300/400	As per KNSI Change Bulletin 18K040-CB-001-0.R Rev4	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K040-SADD-001-0.R	N/A	Yooshau	
2018-03-14	DHC-6	2018	09	LH & RH Wings Stringer Splice Repairs	DHC-6	As per KNSI Change Bulletin 18K040-CB-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K063-SADD-002-0.R	N/A	Ibrahim	
2018-03-28	DHC-6	2018	10	DHC-6 Life vest pouch	DHC-6	All	TMA	EASA minor change approval # 10064802	N/A	Abdulla	
2018-05-08	DHC-6	2018	11	Rudder Improvements	DHC-6	All	TMA	Transport Canada STC SA18-51	N/A	Shifzan	
2018-05-30	DHC-6	2018	12	LH Wing Stringer Splice Repair	DHC-6	As per KNSI SADD 18K190-SADD-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K190-SADD-001 at latest revision	N/A	Nabeel	

2018-06-19	DHC-6	2018	13	Installation, Cable replacements, Wiapire Modified Airstair Door	DHC-6	All	TMA	Transport Canada STC SA18-13	N/A	Yooshau	
2018-07-10	DHC-6	2018	14	Installation of Torch Holder	DHC-6-300	As per KNSI CB 18K205-CB-001 at latest revision	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K205-CB-001at latest revision	N/A	Abdulla	
2018-07-15	DHC-6	2018	15	Removal of Additional Engine Fire Extinguishing System	DHC-6-300	358	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K341-CB-001.0R at latest revision	N/A	Shifzan	
2018-08-14	DHC-8	2017	20R1	EFIS relocation of FMS on 8Q-IAP	DHC-8-315	491	IASL	Hawker Pacific Avionics Design Data Approved under CASR 21.M Validation Report Ref: AA2308-20-01R1	DHC-8/2017/20	Nabeel	
2018-09-15	DHC-6	2018	16	Operation with forward LH cabin/cargo door removed	DHC-6-300	As per Kenn Borek Air Ltd. authorisation letter	IASL	Transport Canada STC SA02-89	N/A	Abdulla	
2018-10-07	DHC-6	2018	17	Indicating/ Recording Systems - Cockpit Recorder (CVR) Deactivation	DHC-6-300	308 & 493	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K295-CB-001 at latest revision	N/A	Ibrahim	
2018-11-04	DHC-8	2018	18	Installation of a Rosen Sun Visor	DHC-8	All	IASL	FAA STC SA4339NM	N/A	Abdulla	
2018-11-26	DHC-6	2018	19	Replacement, LED Master Caution Panel	DHC-6-300	All	TMA	TCCA STC SA17-78	N/A	Abdulla	
2018-12-04	A320/A321	2018	20	Cargo Stowage Box Installation	A320 A321	A320/A321 Series	IASL	EASA.21J.178 SB# 3114-25-551	N/A	Shifzan	
2018-12-04	DHC-8	2018	21	Installation of Non-electrical Floor Path Marking System	DHC-8	As per STC holder authorisation	IASL	EASA STC 10033691, Rev. 2	N/A	Yooshau	
2018-12-12	A320	2018	22	Seat Covers and Cushions Replacement	A320	2347	IASL	EASA.21J.455 Industrial Neotex, S.A. Minor Design Change Approval Certificate No. 0054/18 Revision 00 and corresponding documents	N/A	Ibrahim	
2018-12-13	A320	2018	23	Cabin Attendant Seat Covers and Cushions Replacement	A320	2347	IASL	EASA.21J.455 Industrial Neotex, S.A. Minor Design Change Approval Certificate No. 0055/18 Revision 00 and corresponding documents	N/A	Nabeel	
2019-03-10	DHC-6	2019	01	Installation of alternative hardware	DHC-6-300	As per KNSI CB 19K028-CB-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K028-CB-001 at latest revision	N/A	Yooshau	
2019-03-11	DHC-6	2019	02	RH Cabin Door Hinge Structure Reinforcement	DHC-6-300	As per KNSI SADD 19K059-SADD-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K059-SADD-001 at latest revision	N/A	Nabeel	
2019-03-11	DHC-6	2019	03	Retirement Life Extension of de Havilland DHC-6-300 Wing	DHC-6-300	As per STC holder authorisation	TMA	FAA STC SA00364LA and Master Drawing List SIE-23-900 at latest revision	N/A	Nabeel	
2019-05-16	DHC-6	2019	04	Installation of 4-blade MT-Propeller Model MTV-16-1-E-C-F-R(P)/CFR240-55 on Viking Air Limited DHC-6	DHC-6-100/200/300	As per STC holder authorisation	TMA	EASA STC 1004396	N/A	Abdulla	
2019-06-10	DHC-6	2019	05	Fabrication and Installation of Float Pump Stowage Bracket, Clips and Dipstick Bracket	DHC-6-100/200/300/400	As per KNSI SADD 19K185-SADD-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K185-SADD-001 at latest revision	N/A	Nabeel	
2019-06-12	DHC-6	2019	06	Fuselage Repairs FS 60.00 - 466.00	DHC-6-300	279	TMA	FAA Form 8110-3 DERT-605164-NM on 31-May-2019	N/A	Ibrahim	
2019-06-17	DHC-6	2019	07	Replacement of external lighting with LED lighting	DHC-6	As per AirPlus document ML-2259-330000 Issue 3	TMA	EASA.21J.085 AirPlus APPN 2259	N/A	Abdulla	
2019-07-08	DHC-8	2019	08	Center Pedestal Pouch Fabrication and Installation	DHC-8-200/300	As per KNSI SADD 18K004-SADD-001 at latest revision	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K004-SADD-001 at latest revision	N/A	Yooshau	

2019-07-14	DHC-6	2019	09	Installation of MD302 Standby Attitude Module	DHC-6	Mid-Continent Instruments and Avionics Authorisation Letter dated 23 April 2019	TMA	FAA STC SA019635E	N/A		
2019-07-19	DHC-6	2019	10	Cabin Reconfiguration	DHC-6	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K253-SADD-002 as latest revision	N/A	Shifzan	
2019-07-25	DHC-6	2019	11	Windows - Retaining Ring Installation	DHC-6	Applicable SNs as stated in 19K254-CB-001	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K254-SADD-001 as latest revision	N/A		
2019-08-08	DHC-8	2019	12	Lavatory Mirror Installation	DHC-8-200	429	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K291-SADD-002 as latest revision	N/A	Yooshau	
2019-08-20	DHC-6	2019	13	Roof Access Steps Installation	DHC-6	Applicable SNs as stated in 19K109-SADD-003 Rev3	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K109-SADD-003 as latest revision	N/A	Shifzan	
2019-09-03	DHC-6	2019	14	Generic Structural Repair for Damage Found in support of FAA STC SA00364LA Modification - DHC6-300 Wing Top Skin & Corrugation Repair	DHC-6	Wing Box: SNs 590010 (L/H) & 530042 (R/H)	TMA	Structural Integrity Engineering, Inc (SIE) RD No. SIE 23-1003 & FAA 8110-3 Issued on 22-Aug-2019	MOD/DHC-6/2019/03		
2019-09-15	DHC-6	2019	15	Installation of Emergency Equipment Closet	DHC-6-300	As per KNSI SADD 18K104-SADD-002 at latest revision	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K104-SADD-002 at latest revision	N/A	Yooshau	
2019-09-26	DHC-6	2019	16	Wing Stringer Splice Repairs	DHC-6-300	755	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K443-MA-001 at latest revision	N/A	Ibrahim	
2019-09-26	DHC-6	2019	17	Wing Inboard Flame Track Repair Doubler Extension	DHC-6-300	755	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K445-MA-001 at latest revision	N/A	Ibrahim	
2019-10-07	DHC-6	2019	18	Cabin Blower Fan Installation	DHC-6	As per KNSI document 19K051-SADD-006 Rev7	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K051-SADD-006 at latest revision	N/A	Abdulla	
2019-10-08	DHC-6	2019	19	Fuselage Belly Skin Splice Repair	DHC-6-300	279	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K488-SADD-001 at latest revision	N/A	Nabeel	
2019-10-17	DHC-6	2019	20	Horizontal Stabilizer Stringer Disbonding Repair	DHC-6-300	755	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K533-SADD-001 at latest revision	N/A	Shifzan	
2019-10-17	DHC-6	2019	21	Velcro strap removal	DHC-6-300	798	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K394-SADD-001 at latest revision	N/A	Abdulla	
2019-10-22	DHC-6	2019	22	Installation of Wipaire Model 13000 Seaplane Floats	DHC-6	As per Wipaire Authorisation	Manta	FAA STC SA2CH As amended	N/A	Ibrahim	
2019-10-31	DHC-6	2019	23	Life Vest Pouch Assy Fabrication & Installation	DHC-6-300	As per KNSI document 19K463-SADD-001	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K463-SADD-001 at latest revision	N/A	Yooshau	
2019-11-04	A320	2019	24	Seat Footrest Deactivation	A320	2347	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K382-CB-001 at latest revision	N/A	Shamaan	
2019-11-19	DHC-6	2019	25	Wiper Drain Assembly Installation	DHC-6	As per KNSI document 19K306-SADD-002	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K306-SADD-002 at latest revision	N/A	Nabeel	
2019-11-21	DHC-6	2019	26	Minor change - Removal of two Maradyne Fans in passenger compartment	DHC-6-100/200/300/400	As per KNSI document 19K594-SADD-002	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K594-MA-001 at latest revision	MOD/DHC-6/2017/03	Husam & Nabeel	

2019-11-24	DHC-6	2019	27	Minor Change - Cabin Reconfiguration	DHC-6-200/300	As per KNSI document 19K573-SADD-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K573-SADD-001 at latest revision	N/A	Shifzan	
43797	DHC-6	2019	28	Minor Change - Cabin Reconfiguration	DHC-6	As per KNSI document 19K536-SADD-001	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K536-SADD-001 at latest revision	N/A	Yooshau	
43801	DHC-6	2019	29	Minor Change - Installation of Whelen Anti-Collision Position Light System	DHC-6	As per Effectivity in KNSI document 19K640-CB-001	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Changes to Type Certificate Approval # 19K640-MA-001 at latest revision and accompanying documents	N/A		
43844	DHC-6	2020	01	Major Mod Approval - Removal of Cabin Heating, Intake Deflection and Bleed Air Systems	DHC-6	As per KBL authorisation letter	Manta	Transport Canada STC SA09-62	N/A	Shamaan	
43859	DHC-6	2020	02	Roof Access Steps Installation - Field Aviation Design	DHC-6-100/200/300/400	As per Field Aviation "permission to use" letter	TMA	Transport Canada STC SA93-81	N/A	Husam & Yooshau	
43863	DHC-6	2020	03	Stall Warning Tone Generator and Optional AMS43 Audio Control Panel Installation	DHC-6-100/200/300	As per Genesys Certification Services Inc. authorisation letter dated 29-Jan-21	TMA	Transport Canada STC SA19-111	N/A	Nabeel	
43866	DHC-6	2020	04	LH & RH Wings Stringer Splice Repairs	DHC-6-300	754	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K046-SADD-001	N/A	Husam & Yooshau	
43867	DHC-6	2020	05	Manufacturing and Installation of Bracket Electrical Bonding	DHC-6-100/200/300	MSN listed on KNSI CB 19K577 Rev1	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K577-SADD-001	N/A	Shifzan	
43880	DHC-6	2020	06	Cabin Ceiling Panel Replacement	DHC-6-300	As per Authorisations Letter(s) issued by the STC Holder	TMA	Transport Canada STC SA17-111	N/A		
2020-02-25	DHC-6	2020	07	Minor Change - Protection of Fuel Gallery	DHC-6-100/200/300	As per KNSI document 19K567-SADD-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K567-MA-001	N/A	Shamaan	
2020-04-06	A320	2020	08	Installation Bennetts Seat Coverter Stowage Compartments	A320/A321	All	IASL	CASA STC ASA028ML	N/A	Abdulla	
2020-04-06	A320	2020	09	Installation of cargo restrains on aircraft passenger seats	A320/A321	02599 / 02347	IASL	IASL EO Q2/A320/EO/121 CAA Exemption 201-ASD-D/EX/IAS/2020/02	N/A	Abdulla	
2020-04-25	DHC-6	2020	10	Minor Repair - LH and RH Wing Stringer Splice Repair	DHC-6	493	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K183-SADD-001	N/A	Abdulla	
2020-05-02	DHC8	2020	11	Installation Bennetts Seat Coverter Stowage Compartments	DHC-8	All	IASL	CASA STC ASA028ML	N/A	Abdulla	
2020-08-12	DHC-6	2020	12	De-Modification Of Bleed Air, Cabin Heating & Engine Air Intake System Removal	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K288-SADD-001	N/A	Shifzan	
2020-08-13	DHC-6	2020	13	De-modifications related to 14 change bulletins	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K278-SADD-001	N/A	Husam & Abdulla	
2020-08-14	DHC-6	2020	14	De-Modification Of Fuel Gallery Corrosion Protection	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K287-SADD-001	N/A	Yooshau	
2020-08-16	DHC-8	2020	15	Upgrade of TCAS 7.0 to 7.1	DHC-8-315	542, 544, 546 and 557	IASL	EASA STC 10056169	MOD/DHC-8/2017/19	Yooshau	

2020-08-26	DHC-6	2020	16	Installation of VIP Club Seating	DHC-6-200	226	Manta	Transport Canada STC SA15-70	N/A	Nabeel	
2020-08-26	DHC-6	2020	17	Stretcher Rack Installation	DHC-6-200/300	ALL	Manta	Transport Canada STC SA13-1 at latest revision	N/A	Yooshau & Husam	
2020-09-06	DHC-6	2020	18	Removal of Cabin Blower Fan	DHC-6-300	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K349-SADD-001 at latest revision and accompanying documents	MOD/DHC6/2019/18 To install the blower fan	Ibrahim	
2020-09-24	DHC-6	2020	19	De-modification of Relocation of External Power Receptacle and Main Battery	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K339-SADD-001	MOD/DHC6/2015/17	Shamaan	
2020-12-17	DHC-6	2020	16R1	Installation of VIP Club Seating	DHC-6	As per IKHANA Aircraft Canada Inc. authorisation	Manta	Transport Canada STC SA15-70	MOD/DHC6/2020/16	Nabeel	
2020-12-28	DHC-6	2020	20	Installation of Document Holder	DHC-6	MSNs on Change Bulletin 16K564-CB-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 19K564-MA-001 at latest revision	N/A	Yooshau	
2021-01-03	DHC-6	2021	01	Minor change - KNSI CB 19K571 - Installation of Emergency Equipment Provisions	DHC-6	MSNs on Change Bulletin 19K571-CB-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 19K571-MA-001 at latest revision	N/A	Husam	
2021-01-13	DHC-6	2021	02	20K499 - Wings - Wing Upper Skin Damage Repair	DHC-6-300 Series	754	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document #20K499-MA-001 at latest revision	N/A	Shamaan	
2021-01-24	DHC-6	2021	03	Major change - Inst. of Fuselage Hinged Fuel Caps	DHC-6-300 Series	355	Manta	FAA STC # SA09653RC and Texas Air Services Installation instructions and IPC document # TAS281001	N/A	Husam	
2021-01-25	ATR 72	2021	04	Minor change - Inst. of Provisions for Apple iPad 9.7" (6th Gen)	ATR 72-600	1506 & 1508	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 18K293-MA-001 at latest revision	N/A	Husam	
2021-01-31	DHC-6	2021	05	Minor change - Protection of Fuel Gallery and Its Components	DHC-6-300 Series	MSNs on Change Bulletin	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 19K561-MA-001 at latest revision	N/A	Abdulla	
2021-02-09	DHC-6	2021	06	Minor Change - Wings Alternate Fasteners	DHC-6	MSNs on Change Bulletin	TMA	DOA No. UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U022-MA-001 at latest revision	MOD/DHC-6/2016/25	Shifzan	
2021-03-18	DHC-6	2021	07	Minor Change - Face Mask Caution Decal	DHC-6-100/200/300/400	All	TMA	TMA Modification Bulletin TMA 2021-01 Rev. A	N/A	Nabeel	2021-03-18 Modification approval valid until 18-March-2022. 2022-03-06 Validity extended to 18-March-2023.
2021-03-23	DHC-6	2021	08	Major Change - DHC-6 Flap Roller Modification	DHC-6	MSNs in the Zimex Authorisation Letter	Manta	Zimex Aviation Ltd, EASA STC #10072571 Rev 1	N/A	Ibrahim	
2021-03-29	DHC-6	2021	09	Major Change - STC SA09-69 - Decommission of SOO 6095 Fuel System	DHC-6	MSNs in Kenn Borek Air Authorisation Letter dated 1-Mar-2021	TMA	Transport Canada STC SA09-69 and AERO Design Ltd. Document Control List, DCL812, Revision 1, dated 11 September 2009, or later Transport Canada approved revision	N/A	Husam	
2021-03-30	DHC-6	2021	10	Installation of VIP Club Seating	DHC-6-300 Series	655	TMA	Transport Canada STC SA15-70	N/A	Shamaan	
2021-04-05	DHC-6	2021	11	Installation of ELT model ELT4000 (Manufacturer - Artex)	DHC-6-100/200/300	MSNs on Change Bulletin	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U026-MA-001 at latest revision	N/A	Yooshau	
2021-04-14	DHC-6	2021	12	RH Wing Stringer Splice Repairs	DHC-6-300	657	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U079-MA-001 at latest revision	N/A		
2021-05-02	DHC-6	2021	13	RH Wing Stringer Splice Repairs	DHC-6-300	657	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U097-MA-001 at latest revision	N/A	Abdulla	

2021-05-03	DHC-6	2021	14	Installation of Concorde Lead Acid Battery	DHC-6-100/200/300	All	TMA	FAA STC# SA03971AT at latest revision	N/A	Abdulla	
2021-05-18	DHC-6	2021	15	Ram Air Valve Removal and Blanking Plate Fabrication & Installation	DHC-6-100/200/300	As per KNSI document 21U084-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U084-MA-001 at latest revision	N/A	Nabeel	
2021-06-09	DHC-6	2021	16	Wing Main Spar Lower Fwd Cap & Stringer Repair Scheme	DHC-6-100/200/300	As per KNSI document 21U125-MA-001	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U125-MA-001 at latest revision	N/A	Shifzan	
2021-06-29	DHC-6	2021	17	NS/FSB Sign Relocation - DHC-6-200 MSN 045	DHC-6-200	45	TMA	IKHANA Aircraft Services, document no. 529003 Rev. NC dated 5/3/21 & FAA 8110-3 Issued on 14-May-2021	N/A	Yooshau	
2021-07-07	DHC-6	2021	18	LH Wing Main Spar Web & RH Wing Stringer Repair	DHC-6-300	722	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U129-MA-001 at latest revision	N/A	Shamaan	
2021-08-02	ATR-72	2021	19	Information Systems: Flight Compartment EFB Mount Installation	ATR 72-600	As per KNSI document 21U119-MA-001	Manta	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U119-MA-001 at latest revision	N/A	Ibrahim	
2021-08-10	DHC-6	2021	20	Installation of Document Holders in Flight Deck	DHC-6-300	367	Manta	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U117-MA-001 at latest revision	N/A	Shifzan	
2021-08-11	DHC-6	2021	21	DHC-6 RH Wing Top Skin Repair, P/N: WR6-1002-61, S/N 108	DHC-6-300	As per IKHANA RD57-529-30A	TMA	IKHANA Repair Drawing RD57-529-30A and FAA Form 8110-3 dated 10 August 2021 (signed by DERT-605164-MN)	N/A	Yooshau	
2021-10-31	DHC-6	2015	11R1	First Aid Kit (FAK) Stowage Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U203-MA-001 at latest revision	MOD/DHC-6/2015/11	Husam	
2021-10-31	DHC-6	2015	17R1	Relocation of Main Battery and External Power Receptacle to Nose Compartment	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U205-MA-001 at latest revision	MOD/DHC-6/2015/17	Husam	
2021-10-31	DHC-6	2015	21R1	Rain gutter installation - Cabin and Cockpit doors	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U191-MA-001 at latest revision	MOD/DHC-6/2015/21	Husam	
2021-10-31	DHC-6	2016	01R1	Infant Life Vest Pouch Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U182-MA-001 at latest revision	MOD/DHC-6/2016/01 MOD/DHC-6/2017/24	Husam	
2021-10-31	DHC-6	2016	07R1	Equipment and Furnishing - Cargo Net Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U204-MA-001 at latest revision	MOD/DHC-6/2016/07	Husam	
2021-10-31	DHC-6	2016	14R1	Installation of Document Holders on DHC-6-100/200 and 300 Series	DHC-6-100/200/300	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U183-MA-001 at latest revision	MOD/DHC-6/2016/14	Husam	
2021-10-31	DHC-6	2016	18R1	Installation of card holder on control yokes	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U193-MA-001 at latest revision	MOD/DHC-6/2016/18	Husam	
2021-10-31	DHC-6	2016	19R1	Installation of Window Shield on RH Rear cabin door window	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U184-MA-001 at latest revision	MOD/DHC-6/2016/19	Husam	
2021-10-31	DHC-6	2017	04R1	Crash Axe Installation on Cockpit Sidewall	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U185-MA-001 at latest revision	MOD/DHC-6/2017/04	Husam	
2021-10-31	DHC-6	2017	11R1	Aluminium tape to prevent seawater ingress into fuel gallery	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U195-MA-001 at latest revision	MOD/DHC-6/2017/11	Husam	
2021-10-31	DHC-6	2017	14R1	Cockpit Life Vest Pouch Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U189-MA-001 at latest revision	MOD/DHC-6/2017/14	Husam	
2021-10-31	DHC-6	2017	15R1	Emergency Torch Pouch Installations	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U187-MA-001 at latest revision	MOD/DHC-6/2017/15	Husam	
2021-10-31	DHC-6	2017	22R1	Fuel Drain Valve Cap Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U200-MA-001 at latest revision	MOD/DHC-6/2017/22	Husam	

2021-10-31	DHC-6	2018	08R1	Removal of Ashtray Assy Bracket of the Control Column	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U196-MA-001 at latest revision	MOD/DHC-6/2018/08	Husam	
2021-10-31	DHC-6	2019	01R1	Installation of Alternative Hardware in Various Components	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U197-MA-001 at latest revision	MOD/DHC-6/2019/01	Husam	
2021-10-31	DHC-6	2019	05R1	Fabrication & Installation of float pump stowage brkt., clips & dip stick brkt.	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U199-MA-001 at latest revision	MOD/DHC-6/2019/05	Husam	
2021-10-31	DHC-6	2019	10R1	Cabin Reconfiguration	DHC-6-100/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U202-MA-001 at latest revision	MOD/DHC-6/2019/10	Husam	
2021-10-31	DHC-6	2019	13R1	Installation of roof access steps on fuselage	DHC-6-100/200/300	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U192-MA-001 at latest revision	MOD/DHC-6/2019/13	Husam	
2021-10-31	DHC-6	2019	28R1	LOPA Cabin Reconfiguration	DHC-6-100/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U223-MA-001 at latest revision	MOD/DHC-6/2019/28	Husam	
2021-10-31	DHC-6	2020	05R1	Manufacturing and Installation of Electrical bonding brackets.	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U188-MA-001 at latest revision	MOD/DHC-6/2020/05	Husam	
2021-11-04	DHC-6	2021	22	Installation of PDM Airstair door	DHC-6-100/200/300	All	TMA	FAA STC SA612NE dated March 4, 2020 or later and PMA Design & Manufacturing (PDM) ICA Doc # PDM-ICA110 Rev B dated 8 Dec 2020 or later	N/A	Husam	
2021-11-08	DHC-6	2021	23	Generic Structural Repairs on Wing Box SNs 210053 & 230057	DHC-6-300	Wing Box SNs: 210053 (LH) & 230057 (RH)	TMA	FAA Form 8110-3 dated 15 October 2021 (SIE EO #: SIE-23-936 Rev. H, SIE-23-967 Rev. M, SIE-23-999 Rev. B, SIE-23-1001 Rev. L, SIE-23-1003 Rev. G and SIE-23-1038 Rev. IR)	MOD/DHC-6/2016/06	Nabeel	
2021-12-28	DHC-6	2021	24	Aluminium Tape Installation to Prevent Sea Water Ingress	DHC-6-300	As per KNSI Doc. 20K106-MA-001	IASL	EASA.21.J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 20K106-MA-001 at latest revision	N/A	Shamaan	
2022-01-12	DHC-6	2022	01	Life Vest Pouch Installation	DHC-6-300	As per R&R Consulting Doc RRC-FOR88-01-TMA001	TMA	EASA.21J.749 R&R Consulting, Under EASA Approval Number 10078038 at latest revision	N/A	Ibrahim	
2022-01-20	DHC-6	2022	02	Aluminium Tape Installation to Prevent Sea Water Ingress	DHC-6-200/300	As per KNSI Doc. 22U009-MA-001	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U009-MA-001 at latest revision	N/A	Husam	
2022-01-26	DHC-6	2016	09R1	Removal of Bleed Air, Cabin Heat & Engine Intake Deflectors	DHC-6	As specified in KNSI 15K263-SADD-008, Rev 00	TMA	UK STC 00101	MOD/DHC-6/2016/09	Shifzan	
2022-02-21	DHC-6	2022	03	Aluminium Tape Installation to Prevent Sea Water Ingress	DHC-6-200	As per KNSI Doc. 22U277-MA-001. MSN 045	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U277-MA-001 at latest revision	N/A	Husam	
2022-02-28	DHC-6	2015	16R1	Fuel Gallery Corrosion Protection	DHC-6-100/200/300	As per KNSI document 21U190-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U190-MA-001 at latest revision	MOD/DHC-6/2015/16	Nabeel	
2022-02-28	DHC-6	2016	28R1	Wing Tip Cap Access Cut Out Doubler & Cover Panel Installation	DHC-6-300	As per KNSI document 22U014-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U014-MA-001 at latest revision	MOD/DHC-6/2016/28	Nabeel	
2022-02-28	DHC-6	2019	11R1	Windows - Retaining Ring Installation	DHC-6-100/300/400	As per KNSI document 22U016-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U016-MA-001 at latest revision	MOD/DHC-6/2019/11	Nabeel	
2022-02-28	DHC-6	2019	25R1	Wiper Drain Assembly Installation	DHC-6-100/200/300/400	As per KNSI document 22U015-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U015-MA-001 at latest revision	MOD/DHC-6/2019/25	Nabeel	

2022-03-15	DHC-6	2022	04	Major Change - Replacement of Fixed Wing Control Cables	DHC-6	MSNs as listed in the Thunder Bay Aviation Authorisation Letter	TMA	Thunder Bay Aviation , FAA STC #SA04701NY	N/A	Yooshau	
2022-03-16	DHC-8	2020	15R1	Upgrade of TCAS 7.0 to 7.1	DHC-8	As per Scandinavian Avionics Design ApS Authorization Letter	IASL	Scandinavian Avionics Design ApS, FAA STC ST03776NY at latest revision	MOD/DHC-8/2020/15	Nabeel	
2022-04-26	DHC-6	2022	05	Installation of Emergency Equipment Provisions	DHC-6	As per KNSI document 22U020-MA-001 at latest revision	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U020-MA-001 at latest revision	N/A	Shamaan	
2022-05-18	DHC-6	2022	06	Major Repair - Wing Box SNs 525L26 LH & RH Along with incorporation of STC SA00364LA	DHC-6	Wing Box SNs 525L26 LH & RH	TMA	FAA 8110-3 of 9 May 2022 by DERT-605410-NM	N/A	Ibrahim	
2022-06-21	152	2022	07	FTS Aircraft - G5 Electronics Flight System	152	Cessna 152	IASL	FAA STC SA01818WI	N/A	Shifzan	
2022-06-13	150	2022	08	Garmin GTX 33X	C152	As per FAA Document ODA-240087-CE, Garmin International	IASL	FAA STC No# SA01714WI	N/A	Maail / Ibrahim	
2022-06-13	150	2022	09	Use of Automotive Gasoline	Cessna 152, A152 Textron Aviation F152, FA152	8Q-MFC, MSN 15283358 8Q-MFB, MSN 15280719 8Q-MFD, MSN F152-1893	IASL	FAA STC No. SA00329WI, SA2613CE, SE2606CE	N/A	Husam	
2022-06-09	150	2022	10	Installation of Garmin Model 400W/500W Series GPS-WAAS Navigation System	C152	As per FAA Approved Model List attached with STC No. SA01933LA-D	IASL	FAA STC No# SA01933LA-D	N/A	Yooshau	
2022-06-26	DHC-6	2022	11	replacement of the Transmit/interphone switch (PTT sitch) on DHC6 Control Column Wheel.	DHC-6-200/300	Applicable for all TMA DHC6 -200-300 with MSN defined in RRC_FOR87_01_TM A003_00 §2.3	TMA	EASA.21J.749 R&R CONSULTING, Toulouse, France. Minor Change REF PROJECT: TMA003 REF DOC: RRC_FOR88_01_TMA003_00	N/A	Husam	
2022-08-22	DHC-6	2022	12	LH and RH Wing Corrosion Damage Repair	DHC-6-200/300	451	TMA	22U220-SADD-001 22U219-SADD-001	N/A	Shifzan	
2022-08-26	C150	2022	13	Instrument Panel Installation	C152	As per KNSI SADD 22U197-SADD-001 at latest Revision	IASL	UK.21J.0560 Minor Change Approval Ref 22U197-MA-001 and Statement of Approved Design Data 22U197-SADD-001	N/A	Ibrahim	
2022-08-28	C152	2022	14	Use of Automotive Gasoline	C152	8Q-MFF MSN 15279718	IASL	FAA STC No. SE2606CE	N/A	Maail / Husam	
2022-08-29	C152	2022	15	Installation of BENDIX/KING KI 204 AND KX 155A on Cessna 152	Cessna 152	As per KNSI document 22U195-MA-001 at latest revision	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U195-MA-001 at latest revision	N/A	Husam	

2022-09-30	DHC-6	2022	16	Removal of the optional additional rear baggage compartment and the installation of a cover at the station 376.0.	DHC-6-200/300	Applicable to MSN specified in R&R Consulting document no. RRC_FOR88_01_TMA002_02	TMA	EASA.21J.749 R&R CONSULTING, Toulouse, France. Minor Change REF PROJECT: TMA002 REF DOC: RRC_FOR88_01_TMA002_02	N/A	Yooshau	
2022-10-06	DHC-6	2022	17	Generic Structural Repairs on Wing Box SNs 210161 & 230160	DHC-6-300	Wing Box SNs: 210161 (LH) & 230160 (RH)	TMA	FAA Form 8110-3 dated 28 September 2022 (SIE EO #: SIE-23-936 Rev. J, SIE-23-967 Rev. N, SIE-23-1002 Rev. F and SIE-23-1003 Rev. J)	N/A	Nabeel	
2022-10-19	C152	2022	18	Installation of Sensenich 72CK56 Props on Cessna 152	Cessna 152	MSN 152-79718	IASL	FAA STC No. SA1219EA	N/A	Shamaan	
2022-10-23	C152	2022	18R1	Installation of Sensenich 72CK56 Props on Cessna 152	Cessna 152	Applicable to all IASL Cessna 152 & F152 as defined in FAA STC SA1219EA	IASL	FAA STC No. SA1219EA	MOD-C152-2022-18	Shamaan	