

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2008-06-18	MOD/DHC-6/2008/01	Installation of McMaster-Carr fan at AFT cabin	DHC-6	All	MAT	Mod designed by MAT engineer Waqar Ahmed
2008-08-04	MOD/DHC-6/2008/02	Repair on 8Q-MAI RH wing	DHC-6	279	MAT	Structural Integrity Engineering (SIE). SIE drawing approved by Mr. Kirk Odian
2008-09-18	MOD/DHC-8/2008/01	Installation KHF-950 HF system	DHC-8-300	544	IASL	Aeronautical Engineers Australia and Australian Avionics
2008-09-18	MOD/DHC-8/2008/02	4000 ELT with Artex 406MHz	DHC-8-300	544	IASL	Aeronautical Engineers Australia and Australian Avionics
2008-09-18	MOD/DHC-8/2008/03	Personal Locator Beacon	DHC-8-300	544	IASL	IASL own design
2008-10-20	MOD/DHC-8/2008/04	Medical Oxygen Container	DHC-8-200/300	all	IASL	IASL own design
2009-01-04	MOD/DHC-6/2009/01	Floor carpet	DHC-6	all	MAT	Complies with FAR Part 25.853. Verified by Air India Limited 30 Jan 2006
2009-04-06	MOD/DHC-8/2009/02	Floor carpet	DHC-8	all	IASL	Centro de Tecnologias Aeronauticas.flammability C/O IAW with FAR25.853 (a); FAR 25 Appendix F, Part I
2009-04-06	MOD/Do-228/2009/03	Floor carpet	Do228-212	all	IASL	Centro de Tecnologias Aeronauticas.flammability C/O IAW with FAR25.853 (a); FAR 25 Appendix F, Part I
2009-06-04	MOD/DHC-6/2009/04	Repair on 8Q-MAO LH wing spar	DHC-6-300	259	MAT	Structral Integrity Engineering (SIE 23-KB-250001-1). SIE drawing approved by FAA DER Mr. Kirk Odian
2009-08-11	MOD/DHC-8/2009/05	Installation of SafrGlo Inc. Photoluminescent Emergency Escape Path Marking System.	DHC-8-200/300	all	IASL	FAA approved STC No. ST02311AT to SaFTGlo Inc. (Original Product Type Certificate No. A13NM) FAA Approved Flight Manual Supplement No. M07-11, Rev B STG Aerospace Manual No. M07-10
2009-08-16	MOD/DHC-6/2009/06	Installation of INDIGO ONE GPS Tracking / Satellite messaging unit	DHC-6	All	MAT	STC Information: Field Mod by IndigoSat and type supplement for DHC-6 Series. www.indigosat.com/stc.aspx
2009-08-27	MOD/DHC-6/2009/07	De-Activation of Beta Back-up system	DHC-6-100/300	All	TMA	TMA Modification Bulletin TMA 61-001.
2009-09-07	MOD/DHC-6/2009/08	Approval of GPS (Trimble and Garmin)	DHC-6	All	MAT	STC Information: EASA.IM.A.S.02581, TC STC # SA01-93 and SA02-119. LSTC Information: TC LSTC # W-LSA 98-059/D and C-LSA00-541
2009-10-19	MOD/DHC-6/2009/09	Installation for Garmin GPS	DHC-6-100/300	All	TMA	TMA Modification Bulletin TMA 34-001.
2009-10-22	MOD/DHC-6/2009/10	Repair on 8Q-MAB Wing Strut Attachment	DHC-6-300	287	MAT	RW Martin Inc, Mr. Hillyn Pruntich DER of FAA (No. DERT-605452-NM)
2009-10-25	MOD/DHC-8/2008/04R1	Medical Oxygen Container	DHC-8-200/300	all	IASL	IASL own design
2009-12-30	MOD/DHC-8/2009/11	Installation & Removal of PLB and Holder	DHC-8-202	All	IASL	IASL own design
2010-01-06	MOD/DHC-8/2003/02R1	Removal & Installation of PLB	DHC-8-202	All	IASL	IASL own design
2010-03-11	MOD/DO-228/2010/01	Installation and Removal of Oxygen Bottle Carriage	Do-228-212	8244	IASL	IASL own design
2010-04-15	MOD/DHC-8/2010/02	Installation of Stretcher System	DHC-8-200/300	All	IASL	FAA approved STC No. ST00393NY
2010-04-25	MOD/DHC-6/2010/03	Installation of a nine passenger executive seating system	DHC-6-300	273	MAT	FAA approved STC No. SA02808CH

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2010-05-10	MOD/DHC-6/2010/04	Rear window removal on LH side	DHC-6-300	571	MAT	MAT own design
2010-05-17	MOD/DHC-6/2010/05	Rear window removal on LH side	DHC-6-300	571	MAT	MAT own design
2010-06-10	MOD/DHC-6/2010/06	Installation of Wipair 1300 floats	DHC-6-300	All	MAT	FAA STC No. SA2CH
2010-06-17	MOD/DHC-6/2010/07	Installation of Digital Clock	DHC-6	All	MAT	Modification previously installed by KBAL
2010-07-18	MOD/DHC-6/2010/08	8Q-OEQ Frame No. 230 Crack Repair	DHC-6-100	44	MAT	RW Martin Repair Drawing RD53-3866A (DHC-6-100 S/N 044, LH FS 200 Upper Frame Crack Repair)
2010-09-16	MOD/DHC-6/2010/09	Installation of ASPEN EFD1000/500 on 8Q-MAP	DHC-6-300	571	MAT	FAA STC No. SA10822SC
2010-09-26	MOD/DHC-8/2010/10	Repair - Sloping firewall of RH lower cowl assembly	DHC-8-300	491	IASL	IASL Engineering Order # DHC8-71-07 Issue 1 and Bombardier RD # 8-71-610 Rev 2006-08
2010-09-28	MOD/DHC-6/2010/11	Fleet-wide installation of ASPEN EFD 1000/500	DHC-6-300	All	MAT	FAA STC No. SA10822SC
2010-09-28	MOD/DHC-6/2010/12	Installation of new flap rollers	DHC-6	All	MAT	Swiss Federal Office for Civil Aviation STC # Z 27-50-03
2010-11-09	MOD/DHC-8/2008/04R2	Medical Oxygen Container	DHC-8-200/300	All	IASL	IASL Engineering Order # DHC-8-25-05R2
2010-11-28	MOD/DHC-8/2010/13	RH Nacelle Aft Tail Fairing Repair	DHC-8-300	544	IASL	IASL Engineering Order # DHC8-54-01
2010-11-28	MOD/DHC-6/2010/14	Installation of Garmin Traffic Advisory System	DHC-6-100/200/300	All	MAT	FAA STC # SA02016SE-D
2010-12-01	MOD/DHC-6/2010/15	Installation of Garmin GNS530W/430W	DHC-6 300 Series	All	TMA	Transport Canada STC# SA02-119
2010-12-09	MOD/DHC-6/2010/16	Installation of Attitude Indicator RCA 2600-3	DHC-6-100/300	All	TMA	FAA TSO-C4c Authorisation for KMC Model RCA 2600 Electric Attitude Indicator
2010-12-09	MOD/DHC-6/2010/17	Installation of Wipair Executive Seating System	DHC-6-300	597	TMA	FAA STC # SA02808CH and EASA STC # 10031133
2011-01-04	MOD/DHC-6/2011/01	Relocation of Main Battery to Nose Compartment	DHC-6-100/200/300 Series	All	MAT	TC data sheet No. LBA 2034 Rev.09 AIRplus design Organization Handbook
2011-01-09	MOD/DHC-6/2011/02	Installation of a nine passenger executive seating system	DHC-6-300	375	MAT	FAA approved STC No. SA02808CH
2011-01-11	MOD/DHC-6/2011/03	Installation of Garmin 400w/500w Series	DHC-6-100/200/300 Series	All	MAT	FAA STC No. SA01933LA-D
2011-04-03	MOD/DHC-8/2011/04	Installation of Class Divider	DHC-8-200	All	IASL	IASL Engineering report # Q2BCC01-200
2011-04-10	MOD/DHC-6/2011/05	Stretcher Rack Installation	DHC-6-100/200/300 Series	All	MAT	TC STC No. SA01-97 and Aero Consulting Services Ltd Information Manual
2011-04-20	MOD/DHC-6/2011/06	Cabin Heating Duct Removal	DHC-6-100/200/300 Series	All	MAT	MAT Mod no: MAT/2011/MOD/06 Document: "Replacing Cabin Heating Ducts with KYDEX Material"

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2011-04-28	MOD/DHC-6/2011/07	Installation of Whelen Anti Collision Lights	DHC-6-100/200/300 Series	All	MAT	FAA STC No. SA615EA
2011-05-09	MOD/DHC-6/2011/08	Installation of Whelen Landing Lights	DHC-6-100/200/300 Series	All	MAT	Whelen Engineering Documentations
2011-05-29	MOD/DHC-6/2011/09	Installation of Fuel Cap Protection	DHC-6-100/200/300 Series	All	MAT	MAT own design and as per DHC-6-100/200/300 Series Structural Repair Manual
2011-06-06	MOD/DHC-6/2011/10	Wipaire cabin VIP interior modification	DHC-6-300	283	MAT	FAA STC SA02808CH
2011-06-09	MOD/DHC-6/2011/11	Installation of Cabin Evacuation Lightings	DHC-6-300	283	MAT	Transport Canada STC# SA01-17 Issue 2
2011-06-09	MOD/DHC-6/2011/12	Installation of an Amphibian Landing Gear Position Advisory System	DHC-6-300	283	MAT	FAA STC SA39CH
2011-06-15	MOD/DHC-6/2011/13	Installation of ATPST57 cabin interior kit	DHC-6-300	273	MAT	TC STC # SA08-71 dated August 14, 2008
2011-03-13	MOD/DHC-6/2011/14	Elevator Trailing Edge Replacement	DHC-6	449-L22	MAT	TC STC # SA01-135 dated October 31, 2001
2011-06-29	MOD/B767/2011/15	Cabin Reconfiguration	B767-3P6ER	24496	MGA	SR Technics (EASA.21J.358) Classification and Certification Sheet # C.OSMD.000147-CCS
2011-07-10	MOD/DHC-6/2011/14R1	Elevator Trailing Edge Replacement	DHC-6-100/200/300	as per agreement with RMA	MAT	TC STC # SA01-135 dated October 31, 2001
2011-07-12	MOD/DHC-8/2011/04R1	Installation of Class Divider	DHC-8-200/315	All	IASL	IASL Engineering report # Q2CDS01-DHC
2011-07-28	MOD/DHC-6/2011/16	Installation of Wipair Executive Seating System	DHC-6-300	657	TMA	FAA STC # SA02808CH and EASA STC # 10031133
2011-09-08	MOD/DHC-6/2011/17	Installation of Vista Vents	DHC-6-300/400	All	TMA	TMA modification bulletin TMA 56-001
2011-09-26	MOD/B767/2011/18	Installation of uQAR Quick Access Reader	B767-3P6ER	24496	MGA	FAA STC #ST02776AT
2011-10-02	MOD/B767/2011/15R1	Cabin Reconfiguration	B767-3P6ER	24496	MGA	SR Technics (EASA.21J.358) Classification and Certification Sheet # C.OSMD.000147-CCS
2011-10-13	MOD/DHC-8/2011/19	Installation of Passenger Sliding Window Blinds	DHC-8-200/300	All	IASL	TC STC # SA98-48 dated August 03, 2011
2011-11-02	MOD/DHC-6/2011/20	Installation of Sandel Avionics SN3500 EHSI	DHC-6-300	All	TMA	TMA Modification Bulletin TMA 34-004
2011-12-01	MOD/DHC-6/2011/21	Rain Protection - Cabin Door	DHC-6-100/200/300	All	MAT	TMA Modification document # MAT/2011/MOD/20
2011-12-12	MOD/DHC-6/2011/22	Chip Detector Indication System	DHC-6-100/200/300	All	MAT	Western Avionics Drawing # 35397-001
2011-12-26	MOD/DHC-8/2008/03R1	Installation of PLB Holder	DHC-8-200/300	All	IASL	IASL Engineering Order # DASH 8-25-04R1
2012-02-06	MOD/B767/2012/01	Installation of uQAR Quick Access Reader	B767-300	All	MGA	FAA STC #ST02776AT

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2012-02-13	MOD/DHC-6/2012/02	Installation of Whelen Beacon Light	DHC-6-300	All	TMA	TMA Modification Bulletin TMA 33-002 and FAA STC SA615EA
2012-02-13	MOD/DHC-6/2012/03	Installation of Whelen Anti Collision Strobe Light System	DHC-6 -300	All	TMA	TMA Modification Bulletin TMA 33-001 and FAA STC SA800EA
2012-03-13	MOD/DHC-6/2012/04	Installation of Garmin GTX330 Transponder	DHC-6 -300	All	TMA	ETSO EASA.IM.210.1254
2012-03-13	MOD/DHC-6/2012/05	Installation of Garmin GTS800 Traffic Advisory System	DHC-6 -300	All	TMA	FAA STC SA02016SE-D and ETSO EASA.IM.210.1057
2012-03-13	MOD/DHC-6/2012/06	Installation of Attitude Indicator RCA 2600-3	DHC-6-100/200/300	All	MAT	FAA TSO-C4c Authorisation for KMC Model RCA 2600 Electric Attitude Indicator
2012-03-13	MOD/DHC-6/2012/07	Installation of Garmin GTX330 Transponder	DHC-6-100/200/300	All	MAT	ETSO EASA.IM.210.1254
2012-08-23	MOD/B757/2012/08	Cabin Reconfiguration	B757-204	25623	MGA	Cabin Reconfiguration MOD-1231 by AedoDec (EASA.21J.307)
2012-09-09	MOD/B767/2012/09	Cabin Reconfiguration	B767-30YER	26206	MGA	Main Passenger Cabin Interior Arrangement Engineering Authorization Doc No: 76L2521849 Revision 3 dated 5 September 2012 by Jossair Company, FAA Form 8110-3 dated 9 September 2012, FAA DER Ref: DERT-510352-CE
2012-10-18	MOD/A320/2012/10	Cabin Reconfiguration	A320-214	2347	IASL	A320 MSN 2347 Cabin Reconfiguration AFSB-A320-12-015-25-001 Revision 00 by Air France under Societe AIR FRANCE DO Approval EASA.21J.027
2012-10-22	MOD/B767/2012/09R1	Cabin Reconfiguration	B767-30YER	26206	MGA	Main Passenger Cabin Interior Arrangement Engineering Authorization Doc No: 76L2521849 Revision 5 dated 16 October 2012 by Jossair Company, FAA Form 8110-3 FAA DER Ref: DERT-510352-CE
2012-11-01	MOD/DHC-6/2012/11	Major Repair - Stringer repair on SIE Wing Assy S/N 302	DHC-6-300	All	MAT	FAA STC SA00364LA and SIE EO #SIE-23-940 Rev. V
2012-11-13	MOD/A320/2012/12	Installation of PLB and Holder	A320-214	2347	IASL	IASL Modification Bulletin No. A320X-25-01
2012-11-14	MOD/A320/2012/13	Installation of Stretcher System on A320-214	A320-214	All	IASL	EASA STC No. 10031757, Rev 4
2012-12-02	MOD/DHC-6/2012/14	Repair for corrosion on stringer and doubler	DHC-6-300	256	MAT	REO6-57-V114 Corrosion on Stringer, C6W1021-31, and Doubler, C6W1022-27, at Yw89.15 LHS Lower Surface of Wing C6W1002-59, approved in accordance with Transport Canada DAO No. 04-V-02
2012-12-09	MOD/A320/2012/15	Installation and Removal of SICMA Leg Rest Assy	A320-214	2347	IASL	IASL Modification Bulletin No. A320X-25-03
2012-12-13	MOD/B757/2012/16	Installation of L3 MicroQAR	B757-204	25623	MGA	FAA STC: STC02679AT
2013-01-05	MOD/DHC-6/2013/01	Electric Motor and Hydraulic Pump Replacement	DHC-6-100/200/300	All	MAT	FAA STC: SA10407SC
2013-02-19	MOD/DHC-6/2013/02	Repair of Corrosion on Stringer	DHC-6-300	659	MAT	Viking REO 6-57-V115. Applicable to wing P/N C6W1002-59, S/N VAL0033

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2013-03-10	MOD/DHC-8/2013/03	Replacement of UNS-1B Management System with UNS-1Lw	DHC-8-200	429	IASL	Australian Avionics Pty Ltd EO No. AA1676-02-01 Rev 0
2013-03-25	MOD/A320/2013/04	Installation of Donica Digital Media Reproducer type number AE-DMR300	A320-214	2347	IASL	EASA STC No. 10039614, Rev 5
2013-06-05	MOD/C150/2013/05	Replacement of engine oil screen with an external mounted filter	C150	All	AAA	FAA STC no: SE4315NM
2013-08-06	MOD/B767/2013/06R1	AFIRS 228 Automated Flight Information Reporting System Installation (Provisions)	B767-300	26206, 24496	MGA	Transport Canada STC: SA12-67, Issue No: 1
2013-08-18	MOD/B767/2013/07	Deactivation of Standalone UNS-1Fw FMS	B767-3P6ER	24496	MGA	Avionics Support Group EO213144-1, Rev: IR and DER Services Inc. Dwg. A2013-061-101
2013-09-02	MOD/B767/2013/06R2	AFIRS 228 Automated Flight Information Reporting System Installation	B767-300ER	26206, 24496	MGA	Transport Canada STC No. SA12-67, Issue No.2
2013-09-02	MOD/B767/2013/06R2	AFIRS 228 Automated Flight Information Reporting System Installation	B767-300ER	26206, 24496	MGA	Transport Canada STC No. SA12-67, Issue No.2
2013-09-22	MOD/DHC-6/2013/08	14V Power System and Storage Pouch	DHC-6-300	All	TMA	FAA TSO C-71, RTCA DO-160d
2013-09-27	MOD/DHC-8/2013/09	Installation of Wardrobe Trolley Securing Device	DHC-8-314	499	IASL	IASL EO Q2/DHC8/EO/002 Parts 1 and 2
2013-12-02	MOD/DHC-8/2013/10	Temporary repair of frangible switch cover	DHC-8-315	491	IASL	IASL EO # Q2/DHC8/EO/006
2014-02-10	MOD/B767/2014/1	De-Activation of PRAM	B767-300ER	26206	MEGA	Deactivation of PRAM Engineering Order by Aerospace Design & Engineering Consultants Pte Ltd, approved by DERT-510389-CE.
2014-02-16	MOD/PW127/2014/2	Main Harness, heat shrinkable sleeve repair of PW127F Engine	PW127 Engine	AV0050	VA	Minor repair EBR 00121941 by Lufthansa Technik DOA EASA.21J.019
2014-06-11	MOD/DHC-6/2014/3	Relocation of Voltage Regulator	DHC-6-300	ALL	IASL	IASL EO # Q2/DHC6/EO/002
2014-06-12	MOD/DHC-6/2014/4	Installation of two Meradyne model 3200 cabin fans	DHC-6-300	ALL	IASL	IASL EO # Q2/DHC6/EO/001
2014-06-26	MOD/DHC-6/2014/5	Installation of Pc Safety Valve Kit	DHC-6-300	ALL	IASL	Transport Canada STC No. SE00-9 Issue No.1
2014-07-24	MOD/DHC-6/2014/6	Installation of Wipaire Model 100 Seaplane Floats	DHC-6-200/300	As per Wipaire Authorisation	IASL	FAA STC No. SA2CH

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2014-08-07	MOD/DHC-6/2010/06R1	Installation of Wipaire Model 13000 Amphibious or Model 1300 Seaplane Floats	DHC-6-100/200/300/400	As per Wipaire Authorisation	TMA	Transport Canada STC: SA93-103 & Transport Canada STC: SA11-7
2014-08-18	MOD/DHC-6/2014/07	Fuel Cap Protection	DHC-6-100/200/300	ALL	IASL	IASL EO # Q2/DHC6/EO/003
2014-08-18	MOD/DHC-6/2014/08	Cabin Blower Fan Installation	DHC-6-100/200/300	ALL	IASL	IASL EO # Q2/DHC6/EO/004
2014-09-03	MOD/DHC-6/2014/09	DHC-6 LH Wing Stringer Damage Repair	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-001-0.R issued on 2-Aug-2014 and Data Documents 14K002-RP-001-0.R, 14K002-CCS-001-0.R, 14K002-SSR-001-0.R and 14K002-GA-001-0.R
2014-09-03	MOD/DHC-6/2014/10	DHC-6 RH Wing #05 and #06 Stringer Damage Repair	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-002-0.R issued on 4-Aug-2014 and Data Documents 14K002-RP-002-0.R, 14K002-CCS-002-0.R, 14K002-SSR-002-0.R and 14K002-GA-002-0.R
2014-09-03	MOD/DHC-6/2014/11	DHC-6 RH Wing #01 Stringer Damage Repair	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-003-0.R issued on 5-Aug-2014 and Data Documents 14K002-RP-003-0.R, 14K002-CCS-003-0.R, 14K002-SSR-003-0.R and 14K002-GA-003-0.R
2014-09-03	MOD/DHC-6/2014/12	DHC-6 RH Wing Top Skin Damage Repair	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-004-0.R issued on 12-Aug-2014 and Data Documents 14K002-RP-004-0.R, 14K002-CCS-004-0.R, 14K002-SSR-004-0.R and 14K002-GA-004-0.R
2014-09-03	MOD/DHC-6/2014/13	DHC-6 LH Wing Top Skin Damage Repair	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Limited SADD 14K002-SADD-005-0.R issued on 17-Aug-2014 and Data Documents 14K002-RP-005-0.R, 14K002-CCS-005-0.R, 14K002-SSR-005-0.R and 14K002-GA-005-0.R
2014-10-13	MOD/DHC-6/2014/14	Repair - Wing Leading Edge Corrugation Damage	DHC-6 Wing C6W1002-23	230198	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K002-CSS-007-0.R
2014-10-13	MOD/DHC-6/2014/15	Repair - Wing Rear Spar Damage	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K002-CSS-008-0.R
2014-10-15	MOD/DHC-6/2014/16	Repair - Wing Leading Edge Corrugation Damage	DHC-6 Wing C6W1002-21	210198	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K002-CSS-006-1.R
2014-11-18	MOD/B757/2014/17	AFIRS 228 Installation (Provisions)	B757-204	25623	MEGA	Transport Canada STC: SA14-39, Issue 1 issued to FLYHT Aerospace Solutions Ltd.
2014-12-03	MOD/DHC-6/2014/18	Stabilizers - Horizontal Stabilizer Skins and Rear Spar Repair	DHC-6 Horizontal Stabilizer and Rear Spar C6TP1004 and C6TP1016	All	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K110 RP-001-0.R
2015-01-13	MOD/DHC-6/2015/01	Repair - Wing Main Spar Fitting	DHC-6 Wing C6W1001-27	449	TMA	FAA STC No. SA00364LA and TC STC No. SA97-100
2015-01-20	MOD/DHC-6/2015/02	Repair - Wing Stringer Damage	DHC-6 Wing C6W1001-27	ALL	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K141 RP-001-0.R

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2015-01-25	MOD/DHC-6/2015/03	Elevator Replacement Trailing Edge	DHC-6-100/200/300	ALL	TMA	Transport Canada STC: SA01-135 Issue 1, 31 October 2001
2015-02-03	MOD/DHC-6/2015/04	LH Wing Stringer (# 01) Damage Repair	DHC-6 Wing C6W1001-25	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-001-0.R
2015-02-03	MOD/DHC-6/2015/05	RH Wing Stringer (# 4, 5 & 8) Damage Repair	DHC-6 Wing C6W1001-27	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-001-0.R
2015-02-03	MOD/DHC-6/2015/06	LH Wing Stringer (# 5, 7 & 8) Damage Repair	DHC-6 Wing C6W1001-25	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-006-0.R
2015-02-04	MOD/DHC-6/2015/07	EFB Container	DHC-6 Cockpit	All	TMA	TMA Modification Bulletin TMA 25-002 - EFB Container TMA Drawing TMA 25-002-DR001 - EFB Container TMA Maintenance Manual Supplement TMA 25-002-01 - EFB container
2015-02-26	MOD/DHC-6/2015/08	DHC-6-300 W.S. 58 Wing Main Spar Web Slice	DHC-6-300 Wing Boxes 1. LHS; PN: C6W1002-21 2. RHS; PN: C6W1002-23	DHC-6-300 Wing Boxes 1. LHS; SN: 210110 2. RHS; SN: 230120	TMA	SIE Drawing SIE-23941 and FAA Form 8110-3 dated 6th February 2015
2015-03-01	MOD/DHC-6/2015/09	8Q-TMU RH Wing Top Skin Damage Repair	DHC-6 Wing C6W1001-27	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112 RP-005-0.R
2015-03-01	MOD/DHC-6/2015/10	8Q-TMU LH Wing Top Skin Damage Repair	DHC-6 Wing C6W1001-25	467	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112 RP-002-0.R
2015-03-02	MOD/DHC-6/2015/11	First Aid Kit (FAK) Stowage Installation	DHC-6	All	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 15K035-CCS-001-0.R
2015-03-11	MOD/DHC-6/2015/12	Wing Main Spar Splice Repair	DHC-6 Wing C6W1001-27	467-L23	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 14K112-CCS-004-0.R
2015-03-12	MOD/DHC-6/2015/13	De-Activation of Beta Back-up system	DHC-6-100/300	All	IASL	Transport Canada STC: SA02-58 Issue 02 , 19 July 2002
2015-03-17	MOD/DHC-6/2015/14	Installation of Sun Visor Clip	DHC-6	All	TMA	TMA Modification Bulletin No. TMA-25-003
2015-03-19	MOD/DHC-6/2015/15	Removal of Bleed Air, Cabin Heat & Engine Intake Deflectors	DHC-6-100/200/300	AS per KBAL IN 395.01	IASL	Transport Canada STC: SA09-62 Issue 02, 03 September 2009
2015-04-28	MOD/DHC-6/2015/16	Fuel Gallery Corrosion Protection	DHC-6-100/200/300	All	TMA	EASA.21J.560 - KNSI Aviation Engineering Ltd. document number 15K041-CCS-001-0.R
2015-07-09	MOD/DHC-6/2015/17	Relocation of Main Battery and External Power Receptacle to Nose Compartment	DHC-6	As per KNSI document # 15K079-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K079-CCS-001-0.R Rev 7
2015-07-30	MOD/DHC-6/2015/18	Repair - DHC-6 Fore Flap Hinge Arm	DHC-6	As per KNSI document # 15K116-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K116-CCS-001-0.R
2015-07-30	MOD/DHC-6/2015/19	Repair - Elevator Trim Cable Bracket	DHC-6	As per KNSI document # 15K117-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K117-CCS-001-0.R
2015-07-30	MOD/DHC-6/2015/20	Repair - Wing Skin and Stringer	DHC-6	As per KNSI document # 15K165-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K165-CCS-001-0.R and 15K165-CCS-002-0.R

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2015-10-11	MOD/DHC-8/2013/03R1	Replacement of UNS-1B Management System with UNS-1Lw	DHC-8-200 DHC-8-314	DHC-8-200 MSN 429 DHC-8-314 MSN 591	IASL	Australian Avionics Pty Ltd EO No. AA1676-02-01 Revision 0 Hawker Pacific Pty Ltd T/A Australian Avionics EO No. AA2112-02-01 Revision 0
2015-10-11	MOD/DHC-6/2015/21	Rain Protection - Installation of Rain Gutter	DHC-6	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K226-CCS-001-0.R
2015-10-15	MOD/DHC-8/2015/22					
2015-10-22	MOD/DHC-8/2015/23	Installation of Wardrobe Trolley Securing Device	DHC-8-314	591	IASL	IASL EO Q2/DHC8/EO/002 Parts A, B & C
2015-11-02	MOD/B767/2015/24	Installation of Fifth Lavatory	B767-300ER	27959	MEGA	VT Volant EO 1501-EO-01 Rev B DER NO. DERT-510326-CE
2015-11-17	MOD/DHC-6/2015/25	Repair - Horizontal Stabiliser Lower Skin	DHC-6	As per KNSI document # 15K237-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K237-CCS-001-0.R
2015-11-22	MOD/DHC-8/2015/26	Installation of Passenger Briefing System DMP-200	DHC-8-200/300	All	IASL	FAA STC #: ST01820NY IASL EO #: Q2DHC8EO009
2015-12-03	MOD/B767/2015/24R1	Installation of Fifth Lavatory	B767-300ER	27959	MEGA	VT Volant EO 1501-EO-01 Rev B dated 10/15/2015 (DER NO. DERT-510326-CE) & 1501-ECO-REV-B-MDL-01 Rev C dated 02/12/2015
2015-12-16	MOD/DHC-6/2015/27	Wing stringer repair	DHC-6-300	751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 15K277-CCS-001-0.R
2015-12-16	MOD/B767/2015/28	Cabin Reconfiguration	B767-300	24496	MEGA	EASA.21J.358 SR Technics CCS document # C.OAED.000453-CCS
2016-01-27	MOD/DHC-6/2016/01	Installation of Infant Life Vest Pouch	DHC-6	As per KNSI Change Bulletin 16K009-CB-001-0.R Rev 8	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 16K009-CB-001-0.R
2016-02-22	MOD/DHC-6/2016/02	Installation of LED Beacon Light	DHC-6	All	IASL	FAA STC #: SA615EA
2016-02-25	MOD/DHC-6/2016/03	Wipaire cabin VIP interior modification	DHC-6-300	571	TMA	C-LSA06-289/D
2016-03-08	MOD/B767/2016/04	PRAM Relocation	B767-300ER	27959	MEGA	E4C Technologies EO2321-004 DERT No. DERT-605221-NM
2016-03-08	MOD/DHC-6/2016/05	Installation of LED Landing Light	DHC-6-100/200/300	All	IASL	FAA STC #: SA02212AK IASL EO #: Q2/DHC6/EO/009
2016-03-09	MOD/B767/2015/24R2	Installation of Fifth Lavatory	B767-300ER	27960	MEGA	VT Volant EO 1501-EO-01 Rev E dated 28/01/2016 (DER NO. DERT-510326-CE)
2016-03-12	MOD/B767/2013/06R3	Installation of AFIRS 228	B767-300ER	27959, 27960	MEGA	TC STC #: SA12-67, Issue: 3
2016-03-16	MOD/DHC-6/2016/06	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6-300	Wingbox SN 210053 and 230057	TMA	FAA STC #: SA00364LA



CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2016-04-03	MOD/DHC-6/2016/07	Cargo Net Installation	DHC-6	As per KNSI CB 15K188-CB-001-0.R Rev 8	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd., document # 15K188-CB-001-0.R
2016-04-10	MOD/DHC-6/2016/08	Enhanced Air Conditioning System Installation	DHC-6	571	TMA	TC STC # SA16-33 dated March 19, 2016
2016-04-25	MOD/DHC-6/2016/09	Removal of Bleed Air, Cabin Heat & Engine Intake Deflectors	DHC-6	As specified in EASA STC 10057361 Rev 8	TMA	EASA STC 10057361
2016-05-11	MOD/B767/2013/06R4	AFIRS 228 Automated Flight Information Reporting System Installation	B767-300ER	24496, 26206, 27959, 27960	MEGA	TC STC #: SA12-67 , Issue: 3 Deviation DCN by STC Holder 185-0987 & 185-0994 for SN 27960
2016-05-11	MOD/B767/2015/24R3	Installation of Fifth Lavatory	B767-300ER	24496, 26206, 27959, 27960	MEGA	VT Volant EO 1501-EO-01 Rev E dated 28/01/2016 (DER NO. DERT-510326-CE) MSN:27959 - 1501-ECO-REV-B-MDL-01 Rev C dated 02/12/2015 MSN:27960 - 1501-ECO-01-020 Rev A MSN:27960 - 1501-ECO-01-021 Rev A MSN:27960 - 1501-ECO-01-022 Rev A MSN:27960 - 1501-ECO-01-023 MSN:27960 - 1501-ECO-01-024 MSN:27960 - 1501-ECO-01-025 MSN:27960 - 1501-ECO-01-026 MSN:27960 - 1501-ECO-01-027 MSN:27960 - EO2321-001E MSN:27960 - EO2321-002B MSN:27960 - EO2321-003
2016-05-17	MOD/DHC-6/2016/10	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6	Wingbox SN 230152 and SN210153	TMA	FAA STC #: SA00364LA
2016-05-23	MOD/DHC-6/2016/10R1	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6-300	Wingbox SN 283	TMA	FAA STC #: SA00364LA
2016-05-24	MOD/B767/2016/11	Cabin Interphone System Rewiring	B767-300ER	27959, 27960	MEGA	E4C Technologies EO2380-27959-01 and EO2380-27960-01 (DERT No. DERT-605048-CE)
2016-06-05	MOD/DHC-8/2016/12	Installation of UNS - 1Ew & ADS-B Upgrade	DHC-8-315	544	IASL	EO Number AA2199-02-01, Rev 0
2016-05-29	MOD/B767/2016/11R1	Cabin Interphone System Rewiring	B767-300ER	27959, 27960	MEGA	E4C Technologies EO2380-27959-01 and EO2380-27960-01 (DERT No. DERT-605048-CE) EO2380-27960-01A And EO2380-27959-01A

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2016-06-09	MOD/B767/2016/11R2	Cabin Interphone System Rewiring	B767-300ER	27959, 27960	MEGA	E4C Technologies EO2380-27959-01 and EO2380-27960-01 (DERT No. DERT-605048-CE) EO2380-27960-01A And EO2380-27959-01A MSN:27960 - EO2380-27960-01B
2016-06-14	MOD/DHC-6/2016/13	Installation of new flap rollers	DHC-6	All	IASL	Swiss Federal Office for Civil Aviation STC # Z 27-50-03
2016-07-05	MOD/DHC-6/2016/14	Installation of Document Holder	DHC-6	MSNs on Change Bulletin 16K203-CB-001-0.R Rev 7	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 16K203-CB-001-0.R
2016-07-14	MOD/DHC-6/2015/13R1	De-Activation of Beta Back-up system	DHC-6-100/200/300	All	IASL	Transport Canada STC: SA02-58 Issue 03 , 18 May 2016
2016-08-03	MOD/DHC-6/2016/15	Structural repair	DHC-6-300	Wingbox SNs: 503-L25	TMA	SIE Form 8110-3 dated 27 June 2016
2016-08-17	MOD/B767/2016/16	Taxi Light Deactivation - Nose Landing Gear	B767-300ER	27959	MEGA	EASA.21J.575 365 Aerospace EO Revision A dated 5 AUG 2016
2016-08-24	MOD/DHC-6/2016/17	Float Pump Bracket Installation	DHC-6	MSNs on Change Bulletin 16K197-CB-001-0.R or later revision	IASL	KNSI Change Bulletin 16K197-CB-001-0.R dated 21-July-2016
2016-08-25	MOD/DHC-6 /2016/18	Installation of Card Holder On Control Yoke	DHC-6	MSNs on Change Bulletin 16K245-CB-001-0.R Rev 6	TMA	KNSI Change Bulletin 16K245-CB-001-0.R dated 11-Aug-2016
2016-08-25	MOD/DHC-6/2016/19	Installation of window shield on RH Rear Cabin Door	DHC-6	MSNs on Change Bulletin 16K243-CB-001-0.R Rev 6	TMA	KNSI Change Bulletin 16K243-CB-001-0.R Dated 03-AUG-2016
2016-08-28	MOD/DHC-6/2016/20	Repair - LH Wing Upper Skin	DHC-6	MSN # 44, Wing box P/N C6W1001-21, S/N 279	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K257-CCS-001-0.R
2016-08-28	MOD/DHC-6/2016/21	Repair - RH Wing Stringer Corrosion	DHC-6	MSN # 44, Wing box P/N C6W1001-23 S/N 279	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K256-CCS-001-0.R
2016-09-13	MOD/DHC-8/2016/22	Installation of DMP-200 MP3 Passenger Briefing System	DHC-8-200/300	MSNs on Change Bulletin 16K223-CB-001-0.R	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K223-CCS-001-0.R
2016-09-22	MOD/DHC-6/2016/23	Vertical Stabilizer Skin Panel Disbonding - Generic Repair	DHC-6	MSNs on KNSI Doc. 16K240-RAD-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K240-CCS-001-0.R
2016-10-03	MOD/DHC-6/2016/24	Installation of Garmin GTS 800	DHC-6-100/200/300	All	IASL	Transport Canada STC: SA12-72 Issue No. 1 and FAA STC SA02016SE-D (22-June-2012) referred to therein
2016-10-03	MOD/DHC-6/2016/25	Wing Repair - Alternate Fasteners	DHC-6	MSNs on KNSI Doc. 16K265-CCS-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K265-CCS-001-0.R
2016-10-06	MOD/DHC-6/2016/26	LH, RH Wing Corrosion Repair	DHC-6-300	MSN 375	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K283-CCS-001-0.R

CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2016-10-20	MOD/DHC-6/2016/27	LH Wing Top Skin Doubler Reinforcement	DHC-6-300	MSN 597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K288-CCS-002-0.R
2016-10-20	MOD/DHC-6/2016/10R2	Retirement Life Extension of de Havilland DHC-6-300 wings	DHC-6-300	Wingbox SN 230049 &210050	TMA	FAA STC #: SA00364LA
2016-10-26	MOD/DHC-6/2016/28	Wing Tip Cap Access Cut Out Doubler & Cover Panel Installation	DHC-6-300	MSNs on KNSI Doc. 16K285-CCS-001-1.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K285-CCS-001-1.R
2016-11-10	MOD/DHC-8/2016/12R1	Installation of UNS - 1Ew & ADS-B Upgrade	DHC-8-314	503	IASL	EO Number AA2261-02-01, Rev 0
2016-11-13	MOD/DHC-8/2016/29	Extension of Baggage Compartment	DHC-8-314	503	IASL	EASA.21J.323 v-plane GmbH. Document # 216160-c-TO-2520-001-01
2016-11-13	MOD/C150/2016/30	Installation of Oil Cooler	Continental O200 Engines Installed on C150L/M	All	AAA	FAA STC SA01768SE Dated 8th June 2007
2016-11-17	MOD/DHC-6/2016/31	Installation of stretcher DHC-6-100/200/300	DHC-6-300	All	IASL	Transport Canada STC SA13-1 Issue 2, dated 27-02-2015
2016-11-19	MOD/DHC-6/2016/32	Stringer corrosion repair	DHC-6-300	597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K288-CCS-001-0.R
2016-11-21	MOD/DHC-6/2016/33	Installation of APC starter generator	DHC-6-300	499, 722	TMA	FAA STC # SA390NE
2016-12-20	MOD/DHC-6/2016/34	LH Wing - Stringers corrosion splice repair	DHC-6-300 C6W1001-25	597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K323-CCS-001-1.R
2017-01-17	MOD/DHC-6/2017/01	LH Wing - Top skin doubler extension	DHC-6-300	597	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K345-CCS-001-0.R
2017-01-26	MOD/DHC-6/2017/02	Installation of Wipaire Executive Seating System	DHC-6-200	146	TMA	FAA STC SA02808CH IAW Wipaire, Inc. Drawing 1004310
2017-01-31	MOD/DHC-6/2017/03	Installation of Two "MARADYNE" Fans in Passenger Compartment	DHC-6-100/200/300/400	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 16K338-SADD-004-0.R
2017-02-09	MOD/DHC-6/2017/04	Installation of Crash Axe	DHC6	All MSNs stated on KNSI CB 16K346-CB-001-0.R Rev7	TMA	EASA.21J.560 KNSI Aviation Engineering Lrd. Document SADD # 16K346-SADD-001-0.R
2017-02-19	MOD/DHC-6/2017/05	RH Wing - Stringer splice repair	DHC-6-300	561	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K006-CCS-001-0.R
2017-02-19	MOD/ATR/2017/06	Replacement Overhead Bin Hooks on ATR 42/72	ATR-42/72	All	Villa	EASA.21J.482 ASI Innovation Approval Sheet 20160039

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2017-02-20	MOD/DHC-6/2017/07	Wings - Main Spar Web Splice Repair	DHC-6-300	MSN: 597, Wing Assy P/N: C6W1001-25, C6W1002-21 S/N: 597L29	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 16K337-SADD-001-1.R
2017-03-22	MOD/A321/2017/08	INSTALLATION OF THE CURTAIN ON L/H MOVABLE CLASS DIVIDER GLASS WINDOW.	A321-211	2599	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 17K008-SADD-001-1R
2017-04-09	MOD/DHC-6/2017/09	Installation of Bendix King KN63 DME System	DHC-6-200	146	TMA	EASA.21J.085 AIRplus Document APPN 1942, Issue 2
2017-04-26	MOD/DHC-6/2017/10	Replacement of existing Audio Panels with Dual NAT AMS 43 System on 8Q-TMU	DHC-6-300	467	TMA	EASA.21J.085 AIRplus Document APPN 1944, Issue 1
2017-05-03	MOD/DHC-6/2017/11	Aluminium Tape Installation to Prevent Sea Water Ingress into Fuel Gallery and Components	DHC6	All MSNs stated on KNSI CB 17K097-CB-001-0.R Rev4	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 17K097-SADD-001-0.R
2017-05-03	MOD/DHC-6/2017/12	Fuel Quantity Indicating System Replacement	DHC-6-100/200/300	MSN 687	TMA	Transport Canada STC SA15-44
2017-05-11	MOD/DHC-6/2017/13	LH Wing Stringer #5 Splice Repair	DHC-6-200	146	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document SADD # 17K123-SADD-001-0.R
2017-05-18	MOD/DHC-6/2017/14	Installation of Cockpit Life Vest Pouch	DHC-6	As per KNSI Change Bulletin 17K096-CB-001-1.R Rev6	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K096-SADD-002-0.R
2017-05-24	MOD/DHC-6/2017/15	Emergency Torch Pouch Installation	DHC-6	All MSNs stated on KNSI CB 17K081-CB-001-0.R Rev4	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document SADD # 17K081-SADD-001-0.R
2017-06-20	MOD/DHC-6/2017/16	Fabrication and Installation of Cockpit Life Vest Pouch	DHC-6	As per KNSI Change Bulletin 17K110-CB-001-0.R	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K110-SADD-001-0.R
2017-06-20	MOD/DHC-6/2017/16	Fabrication and Installation of Cockpit Life Vest Pouch	DHC-6	As per KNSI Change Bulletin 17K110-CB-001-0.R	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K110-SADD-001-0.R
2017-07-16	MOD/DHC-6/2017/17	LH & RH Wings Stringer # 5 Splice Repair	DHC-6	256	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. SADD # 17K152-SADD-001-0.R
2017-08-06	MOD/DHC-6/2017/18	Installation of Garmin G950 Integrated Flight Deck System	DHC-6-100/200/300	256	TMA	Transport Canada STC SA15-76
2017-08-13	MOD/DHC-8/2017/19	Upgrade of TCAS 7.0 to 7.1	DHC-8-315	491	IASL	EASA STC 10051448
2017-09-02	MOD/DHC-8/2017/20	Universal FSM Upgrade & ADS-B Enablement	DHC-8-315	491	IASL	Hawker Pacific Avionics Design Data Approved under CASR 21.M Validation Report Ref: AA2308-20-01 R0

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2017-09-06	MOD/DHC-6/2017/18R1	Installation of Garmin G950 Integrated Flight Deck System	DHC-6-100/200/300	582, 781	TMA	Transport Canada STC SA15-76
2017-09-17	MOD/DHC-6/2017/21	Installation of Electronics International MVP-50T Engine Display System	DHC-6-300	687	TMA	TCCA STC Number SA12-13
2017-09-20	MOD/DHC-6/2017/22	Fuselage - Fuel drain valve cap installation	DHC-6-300	As per KNSI Change Bulletin 17K209-CB-001-0.R Rev2	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K209-SADD-001-0.R
2017-10-08	MOD/DHC-8/2017/19R1	Upgrade of TCAS 7.0 to 7.1	DHC-8-314	591	IASL	EASA STC 10051448
2017-10-10	MOD/DHC-6/2017/23	Installation, Fuselage Plug for Airstair Doors, Enlarged Cargo Door Aircraft	DHC-6-300	687	TMA	TCCA STC Number SA12-13
2017-10-23	MOD/DHC-6/2017/24	Equipment & Furnishing - Infant Life Vest Pouch installation	DHC-6-300	As per KNSI Change Bulletin 17K222-CB-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. document # 17K222-SADD-001-0.R
2017-10-31	MOD/DHC-6/2017/25	CVR Installation	DHC-6-300	493	TMA	TCCA STC Number SA97-101
2017-11-08	MOD/DHC-6/2017/26	Re-Life of the Viking Air Limited DHC-6 fuselage, horizontal stabilizer and vertical stablizer	DHC-6-300	279	TMA	FAA STC SA02380LA
2017-11-13	MOD/DHC-6/2017/27	LH and RH Wing Stringer #2,3,4,5,7 & 8 Splice Repair	DHC-6-300	663	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K275-SADD-001-0.R
2017-11-13	MOD/DHC-6/2017/28	Replacement of audio panels with AMS 43	DHC-6-300	663	TMA	EASA.21J.085 AirPlus Maintenance GmbH approval number APPN 1944, Issue 1
2017-11-22	MOD/DHC-6/2017/02R1	Installation of Wipaire Executive Seating System	DHC-6-200/300/400	As per STC holder authorisation	TMA	FAA STC SA02808CH
2017-11-22	MOD/DHC-6/2017/28R1	Replacement of audio panels with AMS 43	DHC-6-300	687	TMA	EASA.21J.085 AirPlus Maintenance GmbH approval number APPN 1944, Issue 1
2017-11-26	MOD/A320/2017/29	Installation of new ownership plates on A320	A320	2347	IASL	EASA.21J.358 SR Technics CCS document # C.OSMD.000188-CCS
2017-11-27	MOD/DHC-8/2017/30	Water tank and coffee maker de-modification	DHC-8-315	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K224-SADD-001-0.R
2017-11-28	MOD/DHC-6/2016/17R1	Float Pump Bracket Installation	DHC-6	MSNs on Change Bulletin 16K197-CB-001-2.R	IASL	KNSI Change Bulletin 16K197-CB-001-0.R dated 28-September-2017
2017-12-05	MOD/DHC-6/2017/31	LH Wing Stringer Splice Repair	DHC-6	283	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document #17K305-CCS-001-0.R dated 25-November-2017
2017-12-09	MOD/DHC-8/2017/32	Environmental Control System Performance Improvement Modification	DHC-8	As per STC holder authorisation	IASL	Transport Canada STC SA00-69

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2017-12-12	MOD/DHC-8/2017/33	Lead Acid battery to NiCad battery de-modification	DHC-8	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K288-SADD-001-0.R
2017-12-26	MOD/DHC-8/2017/19R2	Upgrade of TCAS 7.0 to 7.1	DHC-8-315	582	IASL	FAA STC ST00881WI-D
2017-12-28	MOD/DHC-8/2017/34	Hot Jug Installation on 8Q-IAA	DHC-8-315	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K286-SADD-001-0.R dated 18-December-2017
2017-12-30	MOD/DHC-6/2017/18R2	Installation of Garmin G950 Integrated Flight Deck System	DHC-6-100/200/300	As per STC holder authorisation dated 27-Apr-21	TMA	Transport Canada STC SA15-76
2018-01-30	MOD/DHC-6/2018/01	Installation Of Velcro On Cockpit, Cabin Swing And Cabin Air Stair Doors for Intruder Detection System	DHC-6-300	798	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K340-SADD-001-0.R
2018-01-31	MOD/DHC-6/2017/16R1	Fabrication and Installation of Cockpit Life Vest Pouch	DHC-6-200/300	As per KNSI Change Bulletin 17K110-CB-001-1.R	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K110-SADD-002-0.R
2018-02-12	MOD/DHC-6/2018/02	Aft Cargo Door Lock Modification	DHC-6-100	44	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K039-SADD-002-0.R
2018-02-19	MOD/DHC-8/2018/03	Universal FSM Upgrade & ADS-B Enablement	DHC-8-315	582	IASL	Hawker Pacific Avionics Validation Report Ref: AA2357-20-01R1
2018-02-26	MOD/DHC-6/2018/04	Installation of Safety Valve Kit	DHC-6-100/200/300	All	TMA	FAA STC # SE02170AT. Aeronautical Accessories Report No. AA-99090 Revision A
2018-02-28	MOD/DHC-8/2018/05	Aft Cargo Compartment Expansion	DHC-8-315	582	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K001-SADD-001-0.R
2018-02-28	MOD/DHC-6/2018/06	Installation of new LED landing Lights	DHC-6-100/200/300	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K018-SADD-004-0.R
2018-03-11	MOD/DHC-6/2018/07	RH Wing Inboard Flame Track Doubler Extension	DHC-6-300	270	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K064-SADD-002-0.R
2018-03-12	MOD/DHC-6/2018/08	Removal of Ashtray Assy bracket of the control coloumn	DHC-6-100/200/300/400	As per KNSI Change Bulletin 18K040-CB-001-0.R Rev4	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K040-SADD-001-0.R
2018-03-14	MOD/DHC-6/2018/09	LH & RH Wings Stringer Splice Repairs	DHC-6	As per KNSI Change Bulletin 18K040-CB-001-0.R	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K063-SADD-002-0.R
2018-03-28	MOD/DHC-6/2018/10	DHC-6 Life vest pouch	DHC-6	All	TMA	EASA minor change approval # 10064802
2018-05-08	MOD/DHC-6/2018/11	Rudder Improvements	DHC-6	All	TMA	Transport Canada STC SA18-51
2018-05-30	MOD/DHC-6/2018/12	LH Wing Stringer Splice Repair	DHC-6	As per KNSI SADD 18K190-SADD-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K190-SADD-001 at latest revision

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2018-06-19	MOD/DHC-6/2018/13	Installation, Cable replacements, Wiapire Modified Airstair Door	DHC-6	All	TMA	Transport Canada STC SA18-13
2018-07-10	MOD/DHC-6/2018/14	Installation of Torch Holder	DHC-6-300	As per KNSI CB 18K205-CB-001 at latest revision	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K205-CB-001at latest revision
2018-07-15	MOD/DHC-6/2018/15	Removal of Additional Engine Fire Extinguishing System	DHC-6-300	358	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 17K341-CB-001.0R at latest revision
2018-08-14	MOD/DHC-8/2017/20R1	EFIS relocation of FMS on 8Q-IAP	DHC-8-315	491	IASL	Hawker Pacific Avionics Design Data Approved under CASR 21.M Validation Report Ref: AA2308-20-01R1
2018-09-15	MOD/DHC-6/2018/16	Operation with forward LH cabin/cargo door removed	DHC-6-300	As per Kenn Borek Air Ltd. authorisation letter	IASL	Transport Canada STC SA02-89
2018-10-07	MOD/DHC-6/2018/17	Indicating/ Recording Systems - Cockpit Recorder (CVR) Deactivation	DHC-6-300	308 & 493	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K295-CB-001 at latest revision
2018-11-04	MOD/DHC-8/2018/18	Installation of a Rosen Sun Visor	DHC-8	All	IASL	FAA STC SA4339NM
2018-11-26	MOD/DHC-6/2018/19	Replacement, LED Master Caution Panel	DHC-6-300	All	TMA	TCCA STC SA17-78
2018-12-04	MOD/A320/A321/2018/20	Cargo Stowage Box Installation	A320 A321	A320/A321 Series	IASL	EASA.21J.178 SB# 3114-25-551
2018-12-04	MOD/DHC-8/2018/21	Installation of Non-electrical Floor Path Marking System	DHC-8	As per STC holder authorisation	IASL	EASA STC 10033691, Rev. 2
2018-12-12	MOD/A320/2018/22	Seat Covers and Cushions Replacement	A320	2347	IASL	EASA.21J.455 Industrial Neotex, S.A. Minor Design Change Approval Certificate No. 0054/18 Revision 00 and corresponding documents
2018-12-13	MOD/A320/2018/23	Cabin Attendant Seat Covers and Cushions Replacement	A320	2347	IASL	EASA.21J.455 Industrial Neotex, S.A. Minor Design Change Approval Certificate No. 0055/18 Revision 00 and corresponding documents
2019-03-10	MOD/DHC-6/2019/01	Installation of alternative hardware	DHC-6-300	As per KNSI CB 19K028-CB-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K028-CB-001 at latest revision
2019-03-11	MOD/DHC-6/2019/02	RH Cabin Door Hinge Structure Reinforcement	DHC-6-300	As per KNSI SADD 19K059-SADD-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K059-SADD-001 at latest revision
2019-03-11	MOD/DHC-6/2019/03	Retirement Life Extension of de Havilland DHC-6-300 Wing	DHC-6-300	As per STC holder authorisation	TMA	FAA STC SA00364LA and Master Drawing List SIE-23-900 at latest revision

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2019-05-16	MOD/DHC-6/2019/04	Installation of 4-blade MT-Propeller Model MTV-16-1-E-C-F-R(P)/CFR240-55 on Viking Air Limited DHC-6	DHC-6-100/200/300	As per STC holder authorisation	TMA	EASA STC 1004396
2019-06-10	MOD/DHC-6/2019/05	Fabrication and Installation of Float Pump Stowage Bracket, Clips and Dipstick Bracket	DHC-6-100/200/300/400	As per KNSI SADD 19K185-SADD-001 at latest revision	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K185-SADD-001 at latest revision
2019-06-12	MOD/DHC-6/2019/06	Fuselage Repairs FS 60.00 - 466.00	DHC-6-300	279	TMA	FAA Form 8110-3 DERT-605164-NM on 31-May-2019
2019-06-17	MOD/DHC-6/2019/07	Replacement of external lighting with LED lighting	DHC-6	As per AirPlus document ML-2259-330000 Issue 3	TMA	EASA.21J.085 AirPlus APPN 2259
2019-07-08	MOD/DHC-8/2019/08	Center Pedestal Pouch Fabrication and Installation	DHC-8-200/300	As per KNSI SADD 18K004-SADD-001 at latest revision	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K004-SADD-001 at latest revision
2019-07-14	MOD/DHC-6/2019/09	Installation of MD302 Standby Attitude Module	DHC-6	Mid-Continent Instruments and Avionics Authorisation Letter dated 23 April 2019	TMA	FAA STC SA01963SE
2019-07-19	MOD/DHC-6/2019/10	Cabin Reconfiguration	DHC-6	All	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K253-SADD-002 as latest revision
2019-07-25	MOD/DHC-6/2019/11	Windows - Retaining Ring Installation	DHC-6	Applicable SNs as stated in 19K254-CB-001	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K254-SADD-001 as latest revision
2019-08-08	MOD/DHC-8/2019/12	Lavatory Mirror Installation	DHC-8-200	429	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K291-SADD-002 as latest revision
2019-08-20	MOD/DHC-6/2019/13	Roof Access Steps Installation	DHC-6	Applicable SNs as stated in 19K109-SADD-003 Rev3	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K109-SADD-003 as latest revision
2019-09-03	MOD/DHC-6/2019/14	Generic Structural Repair for Damage Found in support of FAA STC SA00364LA Modification - DHC6-300 Wing Top Skin & Corrugation Repair	DHC-6	Wing Box: SNs 590010 (L/H) & 530042 (R/H)	TMA	Structural Integrity Engineering, Inc (SIE) RD No. SIE 23-1003 & FAA 8110-3 Issued on 22-Aug-2019
2019-09-15	MOD/DHC-6/2019/15	Installation of Emergency Equipment Closet	DHC-6-300	As per KNSI SADD 18K104-SADD-002 at latest revision	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 18K104-SADD-002 at latest revision
2019-09-26	MOD/DHC-6/2019/16	Wing Stringer Splice Repairs	DHC-6-300	755	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K443-MA-001 at latest revision



## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2019-09-26	MOD/DHC-6/2019/17	Wing Inboard Flame Track Repair Doubler Extension	DHC-6-300	755	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K445-MA-001 at latest revision
2019-10-07	MOD/DHC-6/2019/18	Cabin Blower Fan Installation	DHC-6	As per KNSI document 19K051-SADD-006 Rev7	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K051-SADD-006 at latest revision
2019-10-08	MOD/DHC-6/2019/19	Fuselage Belly Skin Splice Repair	DHC-6-300	279	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K488-SADD-001 at latest revision
2019-10-17	MOD/DHC-6/2019/20	Horizontal Stabilizer Stringer Disbonding Repair	DHC-6-300	755	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K533-SADD-001 at latest revision
2019-10-17	MOD/DHC-6/2019/21	Velcro strap removal	DHC-6-300	798	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K394-SADD-001 at latest revision
2019-10-22	MOD/DHC-6/2019/22	Installation of Wipaire Model 13000 Seaplane Floats	DHC-6	As per Wipaire Authorisation	Manta	FAA STC SA2CH As amended
2019-10-31	MOD/DHC-6/2019/23	Life Vest Pouch Assy Fabrication & Installation	DHC-6-300	As per KNSI document 19K463-SADD-001	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K463-SADD-001 at latest revision
2019-11-04	MOD/A320/2019/24	Seat Footrest Deactivation	A320	2347	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K382-CB-001 at latest revision
2019-11-19	MOD/DHC-6/2019/25	Wiper Drain Assembly Installation	DHC-6	As per KNSI document 19K306-SADD-002	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K306-SADD-002 at latest revision
2019-11-21	MOD/DHC-6/2019/26	Minor change - Removal of two Maradyne Fans in passenger compartment	DHC-6-100/200/300/400	As per KNSI document 19K594-SADD-002	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K594-MA-001 at latest revision
2019-11-24	MOD/DHC-6/2019/27	Minor Change - Cabin Reconfiguration	DHC-6-200/300	As per KNSI document 19K573-SADD-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K573-SADD-001 at latest revision
2019-11-28	MOD/DHC-6/2019/28	Minor Change - Cabin Reconfiguration	DHC-6	As per KNSI document 19K536-SADD-001	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 19K536-SADD-001 at latest revision
2019-12-02	MOD/DHC-6/2019/29	Minor Change - Installation of Whelen Anti-Collision Position Light System	DHC-6	As per Effectivity in KNSI document 19K640-CB-001	IASL	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Changes to Type Certificate Approval # 19K640-MA-001 at latest revision and accompanying documents
2020-01-14	MOD/DHC-6/2020/01	Major Mod Approval - Removal of Cabin Heating, Intake Deflection and Bleed Air Systems	DHC-6	As per KBL authorisation letter	Manta	Transport Canada STC SA09-62
2020-01-29	MOD/DHC-6/2020/02	Roof Access Steps Installation - Field Aviation Design	DHC-6-100/200/300/400	As per Field Aviation "permission to use" letter	TMA	Transport Canada STC SA93-81
2020-02-02	MOD/DHC-6/2020/03	Stall Warning Tone Generator and Optional AMS43 Audio Control Panel Installation	DHC-6-100/200/300	As per Genesys Certification Services Inc. authorisation letter dated 29-Jan-21	TMA	Transport Canada STC SA19-111

CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2020-02-05	MOD/DHC-6/2020/04	LH & RH Wings Stringer Splice Repairs	DHC-6-300	754	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K046-SADD-001
2020-02-06	MOD/DHC-6/2020/05	Manufacturing and Installation of Bracket - Electrical Bonding	DHC-6-100/200/300	MSN listed on KNSI CB 19K577 Rev1	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K577-SADD-001
2020-02-19	MOD/DHC-6/2020/06	Cabin Ceiling Panel Replacement	DHC-6-300	As per Authorisations Letter(s) issued by the STC Holder	TMA	Transport Canada STC SA17-111
2020-02-25	MOD/DHC-6/2020/07	Minor Change - Protection of Fuel Gallery	DHC-6-100/200/300	As per KNSI document 19K567-SADD-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 19K567-MA-001
2020-04-06	MOD/A320/2020/08	Installation Bennetts Seat Coverter Stowage Compartments	A320/A321	All	IASL	CASA STC ASA028ML
2020-04-06	MOD/A320/2020/09	Installation of cargo restrains on aircraft passenger seats	A320/A321	02599 / 02347	IASL	IASL EO Q2/A320/EO/121 CAA Exemption 201-ASD-D/EX/IAS/2020/02
2020-04-25	MOD/DHC-6/2020/10	Minor Repair - LH and RH Wing Stringer Splice Repair	DHC-6	493	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K183-SADD-001
2020-05-02	MOD/DHC8/2020/11	Installation Bennetts Seat Coverter Stowage Compartments	DHC-8	All	IASL	CASA STC ASA028ML
2020-08-12	MOD/DHC-6/2020/12	De-Modification Of Bleed Air, Cabin Heating & Engine Air Intake System Removal	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K288-SADD-001
2020-08-13	MOD/DHC-6/2020/13	De-modifications related to 14 change bulletins	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K278-SADD-001
2020-08-14	MOD/DHC-6/2020/14	De-Modification Of Fuel Gallery Corrosion Protection	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K287-SADD-001
2020-08-16	MOD/DHC-8/2020/15	Upgrade of TCAS 7.0 to 7.1	DHC-8-315	542, 544, 546 and 557	IASL	EASA STC 10056169
2020-08-26	MOD/DHC-6/2020/16	Installation of VIP Club Seating	DHC-6-200	226	Manta	Transport Canada STC SA15-70
2020-08-26	MOD/DHC-6/2020/17	Stretcher Rack Installation	DHC-6-200/300	ALL	Manta	Transport Canada STC SA13-1 at latest revision
2020-09-06	MOD/DHC-6/2020/18	Removal of Cabin Blower Fan	DHC-6-300	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K349-SADD-001at latest revision and accompanying documents
2020-09-24	MOD/DHC-6/2020/19	De-modification of Relocation of External Power Receptacle and Main Battery	DHC-6-300 Series	234, 308, 372, 451, 493, 640, 687, 700, 701, 751	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Document # 20K339-SADD-001
2020-12-17	MOD/DHC-6/2020/16R1	Installation of VIP Club Seating	DHC-6	As per IKHANA Aircraft Canada Inc. authorisation	Manta	Transport Canada STC SA15-70
2020-12-28	MOD/DHC-6/2020/20	Installation of Document Holder	DHC-6	MSNs on Change Bulletin 16K564-CB-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 19K564-MA-001 at latest revision

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2021-01-03	MOD/DHC-6/2021/01	Minor change - KNSI CB 19K571 - Installation of Emergency Equipment Provisions	DHC-6	MSNs on Change Bulletin 19K571-CB-001	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 19K571-MA-001 at latest revision
2021-01-13	MOD/DHC-6/2021/02	20K499 - Wings - Wing Upper Skin Damage Repair	DHC-6-300 Series	754	TMA	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document #20K499-MA-001 at latest revision
2021-01-24	MOD/DHC-6/2021/03	Major change - Inst. of Fuselage Hinged Fuel Caps	DHC-6-300 Series	355	Manta	FAA STC # SA09653RC and Texas Air Services Installation instructions and IPC document # TAS281001
2021-01-25	MOD/ATR 72/2021/04	Minor change - Inst. of Provisions for Apple iPad 9.7" (6th Gen)	ATR 72-600	1506 & 1508	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 18K293-MA-001 at latest revision
2021-01-31	MOD/DHC-6/2021/05	Minor change - Protection of Fuel Gallery and Its Components	DHC-6-300 Series	MSNs on Change Bulletin	Manta	EASA.21J.560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 19K561-MA-001 at latest revision
2021-02-09	MOD/DHC-6/2021/06	Minor Change - Wings Alternate Fasteners	DHC-6	MSNs on Change Bulletin	TMA	DOA No. UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U022-MA-001 at latest revision
2021-03-18	MOD/DHC-6/2021/07	Minor Change - Face Mask Caution Decal	DHC-6-100/200/300/400	All	TMA	TMA Modification Bulletin TMA 2021-01 Rev. A
2021-03-23	MOD/DHC-6/2021/08	Major Change - DHC-6 Flap Roller Modification	DHC-6	MSNs in the Zimex Authorisation Letter	Manta	Zimex Aviation Ltd, EASA STC #10072571 Rev 1
2021-03-29	MOD/DHC-6/2021/09	Major Change - STC SA09-69 - Decommission of SOO 6095 Fuel System	DHC-6	MSNs in Kenn Borek Air Authorisation Letter dated 1-Mar-2021	TMA	Transport Canada STC SA09-69 and AERO Design Ltd. Document Control List, DCL812, Revision 1, dated 11 September 2009, or later Transport Canada approved revision
2021-03-30	MOD/DHC-6/2021/10	Installation of VIP Club Seating	DHC-6-300 Series	655	TMA	Transport Canada STC SA15-70
2021-04-05	MOD/DHC-6/2021/11	Installation of ELT model ELT4000 (Manufacturer - Artex)	DHC-6-100/200/300	MSNs on Change Bulletin	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U026-MA-001 at latest revision
2021-04-14	MOD/DHC-6/2021/12	RH Wing Stringer Splice Repairs	DHC-6-300	657	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U079-MA-001 at latest revision
2021-05-02	MOD/DHC-6/2021/13	RH Wing Stringer Splice Repairs	DHC-6-300	657	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U097-MA-001 at latest revision
2021-05-03	MOD/DHC-6/2021/14	Installation of Concorde Lead Acid Battery	DHC-6-100/200/300	All	TMA	FAA STC# SA03971AT at latest revision
2021-05-18	MOD/DHC-6/2021/15	Ram Air Valve Removal and Blanking Plate Fabrication & Installation	DHC-6-100/200/300	As per KNSI document 21U084-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U084-MA-001 at latest revision

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2021-06-09	MOD/DHC-6/2021/16	Wing Main Spar Lower Fwd Cap & Stringer Repair Scheme	DHC-6-100/200/300	As per KNSI document 21U125-MA-001	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U125-MA-001 at latest revision
2021-06-29	MOD/DHC-6/2021/17	NS/FSB Sign Relocation - DHC-6-200 MSN 045	DHC-6-200	45	TMA	DOA UK.21J.5060 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U129-MA-001 at latest revision
2021-07-07	MOD/DHC-6/2021/18	LH Wing Main Spar Web & RH Wing Stringer Repair	DHC-6-300	722	TMA	#REF!
2021-08-02	MOD/ATR-72/2021/19	Information Systems: Flight Compartment EFB Mount Installation	ATR 72-600	As per KNSI document 21U119-MA-001	Manta	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U119-MA-001 at latest revision
2021-08-10	MOD/DHC-6/2021/20	Installation of Document Holders in Flight Deck	DHC-6-300	367	Manta	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U117-MA-001 at latest revision
2021-08-11	MOD/DHC-6/2021/21	DHC-6 RH Wing Top Skin Repair, P/N: WR6-1002-61, S/N 108	DHC-6-300	As per IKHANA RD57-529-30A	TMA	IKHANA Repair Drawing RD57-529-30A and FAA Form 8110-3 dated 10 August 2021 (signed by DERT-605164-MN)
2021-10-31	MOD/DHC-6/2015/11R1	First Aid Kit (FAK) Stowage Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U203-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2015/17R1	Relocation of Main Battery and External Power Receptacle to Nose Compartment	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U205-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2015/21R1	Rain gutter installation - Cabin and Cockpit doors	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U191-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2016/01R1	Infant Life Vest Pouch Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U182-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2016/07R1	Equipment and Furnishing - Cargo Net Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U204-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2016/14R1	Installation of Document Holders on DHC-6-100/200 and 300 Series	DHC-6-100/200/300	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U183-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2016/18R1	Installation of card holder on control yokes	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U193-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2016/19R1	Installation of Window Shield on RH Rear cabin door window	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U184-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2017/04R1	Crash Axe Installation on Cockpit Sidewall	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U185-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2017/11R1	Aluminium tape to prevent seawater ingress into fuel gallery	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U195-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2017/14R1	Cockpit Life Vest Pouch Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U189-MA-001 at latest revision

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2021-10-31	MOD/DHC-6/2017/15R1	Emergency Torch Pouch Installations	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U187-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2017/22R1	Fuel Drain Valve Cap Installation	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U200-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2018/08R1	Removal of Ashtray Assy Bracket of the Control Column	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U196-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2019/01R1	Installation of Alternative Hardware in Various Components	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U197-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2019/05R1	Fabrication & Installation of float pump stowage brkt., clips & dip stick brkt.	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U199-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2019/10R1	Cabin Reconfiguration	DHC-6-100/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U202-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2019/13R1	Installation of roof access steps on fuselage	DHC-6-100/200/300	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U192-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2019/28R1	LOPA Cabin Reconfiguration	DHC-6-100/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U223-MA-001 at latest revision
2021-10-31	MOD/DHC-6/2020/05R1	Manufacturing and Installation of Electrical bonding brackets.	DHC-6-100/200/300/400	All	TMA	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U188-MA-001 at latest revision
2021-11-04	MOD/DHC-6/2021/22	Installation of PDM Airstair door	DHC-6-100/200/300	All	TMA	FAA STC SA612NE dated March 4, 2020 or later and PMA Design & Manufacturing (PDM) ICA Doc # PDM-ICA110 Rev B dated 8 Dec 2020 or later
2021-11-08	MOD/DHC-6/2021/23	Generic Structural Repairs on Wing Box SNs 210053 & 230057	DHC-6-300	Wing Box SNs: 210053 (LH) & 230057 (RH)	TMA	FAA Form 8110-3 dated 15 October 2021 (SIE EO #: SIE-23-936 Rev. H, SIE-23-967 Rev. M, SIE-23-999 Rev. B, SIE-23-1001 Rev. L, SIE-23-1003 Rev. G and SIE-23-1038 Rev. IR)
2021-12-28	MOD/DHC-6/2021/24	Aluminium Tape Installation to Prevent Sea Water Ingress	DHC-6-300	As per KNSI Doc. 20K106-MA-001	IASL	EASA.21.J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 20K106-MA-001 at latest revision
2022-01-12	MOD/DHC-6/2022/01	Life Vest Pouch Installation	DHC-6-300	As per R&R Consulting Doc RRC-FOR88-01-TMA001	TMA	EASA.21J.749 R&R Consulting, Under EASA Approval Number 10078038 at latest revision
2022-01-20	MOD/DHC-6/2022/02	Aluminium Tape Installation to Prevent Sea Water Ingress	DHC-6-200/300	As per KNSI Doc. 22U009-MA-001	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U009-MA-001 at latest revision
2022-01-26	MOD/DHC-6/2016/09R1	Removal of Bleed Air, Cabin Heat & Engine Intake Deflectors	DHC-6	As specified in KNSI 15K263-SADD-008, Rev 00	TMA	UK STC 00101

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2022-02-21	MOD/DHC-6/2022/03	Aluminium Tape Installation to Prevent Sea Water Ingress	DHC-6-200	As per KNSI Doc. 22U277-MA-001. MSN 045	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U277-MA-001 at latest revision
2022-02-28	MOD/DHC-6/2015/16R1	Fuel Gallery Corrosion Protection	DHC-6-100/200/300	As per KNSI document 21U190-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 21U190-MA-001 at latest revision
2022-02-28	MOD/DHC-6/2016/28R1	Wing Tip Cap Access Cut Out Doubler & Cover Panel Installation	DHC-6-300	As per KNSI document 22U014-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U014-MA-001 at latest revision
2022-02-28	MOD/DHC-6/2019/11R1	Windows - Retaining Ring Installation	DHC-6-100/300/400	As per KNSI document 22U016-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U016-MA-001 at latest revision
2022-02-28	MOD/DHC-6/2019/25R1	Wiper Drain Assembly Installation	DHC-6-100/200/300/400	As per KNSI document 22U015-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U015-MA-001 at latest revision
2022-03-15	MOD/DHC-6/2022/04	Major Change - Replacement of Fixed Wing Control Cables	DHC-6	MSNs as listed in the Thunder Bay Aviation Authorisation Letter	TMA	Thunder Bay Aviation , FAA STC #SA04701NY
2022-03-16	MOD/DHC-8/2020/15R1	Upgrade of TCAS 7.0 to 7.1	DHC-8	As per Scandinavian Avionics Design ApS Authorization Letter	IASL	Scandinavian Avionics Design ApS, FAA STC ST03776NY at latest revision
2022-04-26	MOD/DHC-6/2022/05	Installation of Emergency Equipment Provisions	DHC-6	As per KNSI document 22U020-MA-001 at latest revision	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U020-MA-001 at latest revision
2022-05-18	MOD/DHC-6/2022/06	Major Repair - Wing Box SNs 525L26 LH & RH Along with incorporation of STC SA00364LA	DHC-6	Wing Box SNs 525L26 LH & RH	TMA	FAA 8110-3 of 9 May 2022 by DERT-605410-NM
2022-06-21	MOD/152/2022/07	FTS Aircraft - G5 Electronics Flight System	5/31/1900 0:00:00	Cessna 152	IASL	FAA STC SA01818WI
2022-06-13	MOD/150/2022/08	Garmin GTX 33X	C152	As per FAA Document ODA-240087-CE, Garmin International	IASL	FAA STC No# SA01714WI
2022-06-13	MOD/150/2022/09	Use of Automotive Gasoline	Cessna 152, A152 Textron Aviation F152, FA152	8Q-MFC, MSN 15283358 8Q-MFB, MSN 15280719 8Q-MFD, MSN F152-1893	IASL	FAA STC No. SA00329WI, SA2613CE, SE2606CE
2022-06-09	MOD/150/2022/10	Installation of Garmin Model 400W/500W Series GPS-WAAS Navigation System	C152	As per FAA Approved Model List attached with STC No. SA01933LA-D	IASL	FAA STC No# SA01933LA-D

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2022-06-26	MOD/DHC-6/2022/11	replacement of the Transmit/interphone switch (PTT sitch) on DHC6 Control Column Wheel.	DHC-6-200/300	Applicable for all TMA DHC6 -200-300 with MSN defined in RRC_FOR87_01_TMA003_00 §2.3	TMA	EASA.21J.749 R&R CONSULTING, Toulouse, France. Minor Change REF PROJECT: TMA003 REF DOC: RRC_FOR88_01_TMA003_00
2022-08-22	MOD/DHC-6/2022/12	LH and RH Wing Corrosion Damage Repair	DHC-6-200/300	451	TMA	22U220-SADD-001 22U219-SADD-001
2022-08-26	MOD/C150/2022/13	Instrument Panel Installation	C152	As per KNSI SADD 22U197-SADD-001 at latest Revision	IASL	UK.21J.0560 Minor Change Approval Ref 22U197-MA-001 and Statement of Approved Design Data 22U197-SADD-001
2022-08-28	MOD/C152/2022/14	Use of Automotive Gasoline	C152	8Q-MFF MSN 15279718	IASL	FAA STC No. SE2606CE
2022-08-29	MOD/C152/2022/15	Installation of BENDIX/KING KI 204 AND KX 155A on Cessna 152	Cessna 152	As per KNSI document 22U195-MA-001 at latest revision	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U195-MA-001 at latest revision
2022-09-30	MOD/DHC-6/2022/16	Removal of the optional additional rear baggage compartment and the installation of a cover at the station 376.0.	DHC-6-200/300	Applicable to MSN specified in R&R Consulting document no. RRC_FOR88_01_TMA002_02	TMA	EASA.21J.749 R&R CONSULTING, Toulouse, France. Minor Change REF PROJECT: TMA002 REF DOC: RRC_FOR88_01_TMA002_02
2022-10-06	MOD/DHC-6/2022/17	Generic Structural Repairs on Wing Box SNs 210161 & 230160	DHC-6-300	Wing Box SNs: 210161 (LH) & 230160 (RH)	TMA	FAA Form 8110-3 dated 28 September 2022 (SIE EO #: SIE-23-936 Rev. J, SIE-23-967 Rev. N, SIE-23-1002 Rev. F and SIE-23-1003 Rev. J)
2022-10-19	MOD/C152/2022/18	Installation of Sensenich 72CK56 Props on Cessna 152	Cessna 152	MSN 152-79718	IASL	FAA STC No. SA1219EA
2022-10-23	MOD/C152/2022/18R1	Installation of Sensenich 72CK56 Props on Cessna 152	Cessna 152	Applicable to all IASL Cessna 152 & F152 as defined in FAA STC SA1219EA	IASL	FAA STC No. SA1219EA
2022-11-02	MOD/DHC-6/2022/19	LH & RH Wings Corrosion Damage Repair SN 250160 & 270160	DHC-6-300	Wing Box SNs: SN 250160 & 270160	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U290-MA-001 & 22U291-MA-001 at latest revision
2022-11-17	MOD/DHC-6/2022/20	RD53-529-28A Fuselage repair FS 60:00 to 466:00 on 8Q-TMU	DHC-6-300	467	TMA	FAA Form 8110-3 dated 6-Sep-2022 and Repair Drawing RD53-529-28A, Rev A
2022-11-17	MOD/DHC-6/2017/26R1	Re-Life of the Viking Air Limited DHC-6 fuselage, horizontal stabilizer and vertical stablizer	DHC-6	As specified in the authorisation document	TMA	FAA STC SA02380LA
2023-01-02	MOD/DHC-6/2023/01	Seats Installation & LOPA Approval	DHC-6-200 HG	As specified in the authorisation document	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U356 -SADD-001

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2023-04-01	MOD/A320/2023/02	Galley rail fabrication and replacement	A321	2599	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U040 -SADD-001
2023-04-03	MOD/A321/2023/03	Manufacture and Installation of Interior Placards, Signs and Markings	A321-211	2599	IASL	Transport Canada STC SA15-95 at latest revision
2023-04-04	MOD/A321/2023/04	Cabin Attendant Seat Covers and Cushions Replacement	A321-211	2599	IASL	DOA EASA.21J.455 Industrial Neotex. S.A. Minor Design Change Approval Certificate No. 0005/23 Rev.00
13/4/2023	MOD/ATR-42/2023/05	Seat Pack Installation For Cargo	ATR 42-500	All	IASL	CASA STC No. ASA028ML
2023-06-04	MOD/A321/2023/06	Cabin Attendant Seat Covers and Cushions Replacement	A321-211	2599	IASL	DOA EASA.21J.455 Industrial Neotex. S.A. Minor Design Change Approval Certificate No. 0002/23 Rev.00
2023-04-17	MOD/A321/2023/07	Dado Panel Textile Covering Replacement	A321-211	2599	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U035 -SADD-001
2023-05-04	MOD/ATR-72/2023/08	Attendant Handset Strap Installation	ATR72-212A	1506, 1508, 1515	Manta	EASA 21J.664 ReCaero Project RCP023
2023-05-31	MOD/DHC-6/2023/02	Replacement of Connectors	DHC-6	Ref. KNSI CB 23U074	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 23U074-SADD-001
2023-05-31	MOD/DHC-6/2023/09	Installation of Fuel Pressure Switch	DHC-6	As specified in the authorisation document	TMA	Transport Canada STC SA10-85
2023-06-08	MOD/DHC-6/2023/10	LH Wing Main Spar Web Corrosion Damage Permanent Repair	DHC-6	As per KNSI document 23U081-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 23U081-MA-001
2023-06-08	MOD/DHC-6/2023/11	LH Wing Top Skin Corrosion Damage Permanent Repair	DHC-6	As per KNSI document 23U082-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 23U082-MA-001
2023-06-08	MOD/DHC-6/2023/12	RH Wing Top Skin and Internal Corrugation Sheet Corrosion Damage Permanent Repair	DHC-6	As per KNSI document 23U083-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 23U083-MA-001
2023-06-22	MOD/DHC-6/2023/13	Alternate Altimeter (Part Number 23U119)	DHC-6	As per KNSI document 23U119-MA-001 at latest revision	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 23U119-MA-001
2023-10-04	MOD/A319/2023/14	BeOnd Livery	A319-111	2119	Beond	DOA EASA.21J.534 Aero Inspection Service Bulletin # SB-0171-01
2023-09-13	MOD/A319/2023/15	Single HF System	A319-111	2119	Beond	DOA EASA.21J.722 Aerospace Engineering Solutions Document Release Note # AES-0157-01
2023-09-25	MOD/DHC-6/2023/16	8Q-TAU LOPA Re-configuration	DHC-6	634	TMA	UK DOA UK.21J.0653 Documents stated in the MEADS1149DTL-002 Document Transmittal List
2023-09-25	MOD/DHC-6/2023/17	Lug Repair, Cockpit Seat Pedestal, PN C3FF20-5	DHC-6	All	TMA	Transport Canada Repair Design Approval No. C-RA16-049/D



**CAA Aircraft Modification Register**

**Retrieved On: 3/19/2025**

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2023-10-09	MOD/A319/2023/18	Portable IFE Mounting Tray Installation	A319-111	2119	Beond	DOA EASA.21J.487 PMV Engineering Minor Change Approval # SCA-01800-MCA-S01-R00 at latest revision
2023-10-09	MOD/A319/2023/19	Last row curtain installation	A319-111	2119	Beond	DOA EASA.21J.769 Modification approval document MB-A319C099-0001 at latest revision
2023-10-15	MOD/DHC-6/2023/20	DHC-6 Wing Main Spar Web & Stringer #5 Repairs	DHC-6	Wing Box PNs: WR6-1002-61 S/N: 224	TMA	FAA Form 8110-3 dated 11-Oct-2023 and Repair Drawing RD53-529-40A, Rev NC

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2023-10-16	MOD/DHC-6/2023/21	Installation of FWD cabin lavatory on Viking Air Limited DHC-6 400 series	DHC-6	As specified in the authorisation document	TMA	Transport Canada STC no. O-LSA23-118/D
2023-10-26	MOD/DHC-6/2023/22	TCCA STC SA15-71 - DHC-6 Twin Otter Seat Installation	DHC-6	As specified in the authorisation document	TMA	Transport Canada STC no. SA15-71
2023-11-13	MOD/A319/2023/23	44 B/C - 6 Y/C Cabin Reconfiguration	A319-111	2119	Beond	EASA STC 10083262
2023-11-15	MOD/B1900/2023/24	Stretcher module kit mechanical installation	Beechcraft 1900D	As specified in the minor change approval document	Manta	DOA EASA.21J.409 Solutions for Aviation S.L Minor Change Approval # B30_082 at latest revision
2023-11-27	MOD/DHC-6/2023/25	Wing Box SN 148 Main Spar Web Corrosion Repair	DHC-6	Wing Box PN: WR6-1002-61, SN: 148	TMA	FAA Form 8110-3 dated 22 Nov 2023 issued by and Repair Drawing RD57-529-41A Rev NC issued by AEVEX Aerospace, DER/ODA Number: 999817965
2023-12-07	MOD/DHC-8/2023/26	Seat Covers and Cushions Replacement in Dash 8-200	DHC-8-202	542	IASL	DOA EASA.21J.455 Industrial Neotex. S.A. Minor Design Change Approval Certificate No. 0026/23 Rev.00
2023-12-24	MOD/DHC-8/2023/27	UNS-1Ew FMS & TDR 94D XPNDR with ADS-B Install	DHC-8-202/315	542 & 546	IASL	CASA.DEL21.0178 Minor Change Engineering Order Number: SM6215-300-002 at the latest revision
2024-01-03	MOD/DHC-6/2024/01	Roof Access Steps Installation	DHC-6-300	MSN 516 as per Kenn Borek Air 'Authorisation Letter' no. KBAL 917	Manta	Transport Canada STC no. SA09-59
2024-02-04	MOD/DHC-6/2024/02	Float Step Cover	DHC-6-300	As specified in the minor change approval document	TMA	DOA UK.21J.0653 EUROAV design services Minor Change Approval # MEADS1163MCA-001
2024-02-21	MOD/DHC-6/2024/03	Installation of electrical connectors alternate P/Ns interchangeability and backshell	DHC-6-300	As specified in the minor change approval document	TMA	DOA UK.21J.0653 EUROAV design services Minor Change Approval # MEADS1180MCA-001

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2024-03-03	MOD/DHC-6/2024/04	Installation of Parmetheus Plus and Parmetheus Gen 3 LED Landing Lights	DHC-6	As per authorisation letter(s) issued by the STC Holder	TMA	FAA STC SA00344BO
2024-03-03	MOD/DHC-6/2024/05	PMA Windshield Alternate P/N Installation	DHC-6	As per MEADS1185SB-001 issued by UK.21J.0653 European Aviation Design Services Ltd	TMA	MEADS1185SADD-001 at latest amendment issued by UK.21J.0653 European Aviation Design Services Ltd
2024-04-25	MOD/DHC-6/2024/06	MORE Company, Inc. STCs Validation	DHC-6	Pratt and Whitney Canada PT6A engines referenced in MORE Compnay, Inc. FAA STCs	Applicable to all Operators	FAA STCs; SE000EN, SE00001EN, SE00002EN, SE00003EN, SE00004EN, SE00006EN, SE00010EN and SE00011EN
2024-04-30	MOD/A321/2024/07	Beond Livery	A321-231	1711	Beond	AES-0243-03-MS Revision 01
2024-05-07	MOD/A321/2024/08	Replacement of galley inserts MSN 01711	A321-231	1711	Beond	AES-0243-06-MS-Revision 01
2024-05-08	MOD/A321/2024/09	Replacement of CAS Dress Covers MSN 01712	A321-231	1711	Beond	AES-0243-05-MS-Revision 00
2024-05-19	MOD/A321/2023/18R1	Portable IFE Mounting Tray Installation	A318/A319/A320/A321	SCA-01800-MDL-S01 at the latest revision	Beond	DOA EASA.21J.487 PMV Engineering Minor Change Approval # SCA-01800-MCA-S01 at latest revision
2024-05-14	MOD/DHC-6/2024/10	Cockpit & Cabin Interior Replacement	DHC-6	Refer to the KBAL Authorisation Letter as amended	TMA	TCCA STC SA09-7 Issue 3
2024-05-21	MOD/DHC-6/2024/11	LOPA Re configuration MSN 283	DHC-6	As per MEADS1174SB-001 Issue 2 issued by UK.21J.0653 European Aviation Design Services Ltd	TMA	MEADS1174SADD-002 at latest amendment issued by UK.21J.0653 European Aviation Design Services Ltd
2024-05-22	MOD/DHC-6/2024/12	Wing structure damage generic repairs in support of FAA STC SA00364LA	DHC-6-300	Wing Box SNs: 375 (LH & RH)	TMA	FAA Form 8110-3 dated 16 May 2024
2024-05-26	MOD/DHC-6/2024/13	Head protection padding installation	DHC-6	As per MEADS1179SB-001 Issue 1, issued by UK.21J.0653 European Aviation Design Services Ltd	TMA	MEADS1179SADD-001 at latest amendment issued by UK.21J.0653 European Aviation Design Services Ltd
2024-05-28	MOD/DHC-6/2024/14	Wing structure damage generic repairs in support of FAA STC SA00364LA	DHC-6-300	Wing Box SNs: 590020 & 610020	TMA	FAA Form 8110-3 dated 16 May 2024

**CAA Aircraft Modification Register**

**Retrieved On: 3/19/2025**

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2024-06-04	MOD/DHC-6/2024/15	Cargo Net Assembly Installation	DHC-6-300	As per KNSI document 23U099-MA-001 at latest revision	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 23U099-MA-001 at latest revision
2024-06-23	MOD/A321/2024/16	Interior Dual Language Placards	A321-231	1711	Beond	DOA EASA.21J.722 Aerospace Engineering Solutions Minor Change Approval # AES-0243-04-MS Revision 05
2024-07-01	MOD/DHC-6/2024/17	Installation of Rain Gutters Over Fuel Caps	DHC-6-200/300	As per KNSI document 22U226-MA-001at latest revision	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 22U226-MA-001 at latest revision
2024-07-02	MOD/DHC-6/2024/18	Roof Access Steps Installation - AERO Design Ltd	DHC-6-100/200/300	All	TMA	Transport Canada STC no. SA09-59
2024-06-11	MOD/DHC-6/2024/19	ELT Replacement	DHC-6	As per EUROAV MEADS1196SB-001	TMA	DOA UK.21J.0653 European Aviation Design Services Ltd Minor Change Approval Document # MEADS1196SADD-001 at latest revision

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2024-07-15	MOD/DHC-6/2024/20	LH Wing Box Main Spar Lower Cap and #5 Stinger Corrosion Repair	DHC-6 LH Wing Box WR6-1002-59	232	TMA	FAA Form 8110-3 dated 11 Jul 2024 and Repair Drawing RD57-529-42A Rev NC issued by AEVEX Aerospace, DER/ODA Number: 999817965
2024-07-29	MOD/DHC-6/2024/21	Installation of Alternate Fire Extinguisher	DHC-6	As per KNSI document 24U010-SADD-001	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Repair Approval Document # 24U010-MA-001 at latest revision
2024-08-05	MOD/DHC-6/2024/22	Installation of cockpit clock	DHC-6-100/200/300	As specified in the minor change approval document	TMA	DOA UK.21J.0653 EUROAV design services Minor Change Approval # MEADS1213MCA-001 at latest revision
2024-08-19	MOD/A320/2024/23	Dado Panel Textile Covering Replacement	A320-214	2347	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 24U057 -SADD-001
2024-08-27	MOD/A321/2024/24	68 Passenger Seating Configuration This modification introduces a cabin layout using 34 business class seats generating a 68-passenger seating configuration.	A321-231	01711	Beond	EASA STC 10085153 DOA Aesglobal Limited
2024-09-08	MOD/ATR 42/72/2024/25	Installation and removal of Bucher Leichtbau AG 16G NGS XL stretcher 1120030-Series	ATR 42/72	As per EASA STC 10027884, 16G NGS XL-24-002	IASL	EASA STC 10027884 Rev.12 Bucher Leichtbau Group
2024-09-10	MOD/DHC-6/2024/26	Equipment & Furishing - Layout of Passenger Accomodation Approval	DHC-6	As per AeroKnow document PR00503-SADD-001	TMA	DOA EASA.21J.791 AeroKnow SIA Minor Change Approval Document PR00503-MCA-001
2024-09-11	MOD/DHC-6/2024/27	Installation, Window Vents	DHC-6	MSNs as listed in the Thunder Bay Aviation Ltd. Authorisation Letter	TMA	Thunder Bay Aviation Ltd. , Transport Canada STC no. SA24-12
2024-09-16	MOD/DHC-6/2024/28	Major Repair - Wing Boxes: LH - PN: C6W1002-21, SN: 210180 and RH - PN: C6W1002-23, SN: 230179	DHC-6	Wing Boxes: LH - PN: C6W1002-21, SN: 210180 and RH - PN: C6W1002-23, SN: 230179	TMA	SIE Eos: SIE-210180-LH-Exhst SIE-210180L&230179R_F-spar
2024-09-17	MOD/DHC-6/2024/29	Minor Modification - AeroKnow Modification Bulletin PR00499 (Fabrication and Installation of Interior Placards)	DHC-6	As per AeroKnow Ltd document PR00499-SADD-001	TMA	DOA EASA.21J.791 AeroKnow Ltd. Minor Change Approval Document # PR00499-MCA-001 at latest revision
2024-09-23	MOD/DHC-6/2024/30	Installation of Garmin GI275 Multi-Function Display System	DHC-6	FAA STC No. SA02658SE and Gamin Authorisation Letter	TMA	FAA STC No. SA02658SE

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2024-09-23	MOD/DHC-6/2024/31	Installation of Garmin GTX 33/330 or GTX 335/345 Transponders	DHC-6-100/200/300	As per authorisation letter(s) issued by the STC Holder	TMA	FAA STC No. SA01714WI
2024-09-24	MOD/DHC-6/2024/32	Installation of Garmin GTN 6XX/7XX and GTN Xi Series Navigation System	DHC-6-100/200/300	All	TMA	FAA STC No. SA02019SE-D
2024-10-02	MOD/DHC-6/2024/33	Installation of life vest pouch	DHC-6-200/300	As per serial no. in EuroAV Design Services MEADS1217MCA-001	Manta	DOA CAA UK.21J.0653 EuroAV Design Services MEADS1217MCA-001 at latest revision
2024-10-08	MOD/DHC-6/2024/34	Crash Axe Installation on Cockpit Sidewall	DHC-6-300	As per KNSI document 22U119-SADD-001 at latest revision	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U119-MA-001 at latest revision
2024-10-13	MOD/DHC-6/2024/35	Installation of Document Holder in the cockpit	DHC-6-300	As per KNSI document 22U118-MA-001 at latest revision	IASL	UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Change Approval Document # 22U118-MA-001 at latest revision
2024-10-14	MOD/DHC-8/2024/36	Installation of Spectrum Aeromed Ambulance Module	DHC-8-202	542	IASL	TCCA STC A-LSA24-064/D at latest Revision
2024-10-17	MOD/ATR 42/72/2024/37	Container Unit Additional Restraining Installation	ATR 42/72	As per KNSI document 24U056-MA-001 at latest revision	IASL	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Changes to Type-Certificate Approval Document # 24U056-MA-01
2024-10-24	MOD/DHC-6/2024/38	Installation of Garmin GTS 825 (TAS) or GTS 855 (TCAS I) Traffic System	DHC-6 Series 100/200/300	As per STC Authorization Letter	TMA	Installation of Garmin GTS 825 (TAS) or GTS 855 (TCAS I) Traffic System in accordance with Master Drawing List, GTS 8XX Part 23 AML STC, 005-00738-01, Revision 1, dated May 2, 2014, or later FAA approved revision
2024-11-17	MOD/DHC-6/2024/39	Installation of Seats	DHC-6-300	As per STC Authorization Letter	IASL	TCCA STC SA 15-71 at latest Revision
2024-11-18	MOD/DHC-6/2024/40	EuroAV MEADS1211 - Interior Furnishings Alt PN	DHC-6 Series 100/200/300	As per European Aviation Design Services Ltd document MEADS1211MCA-001	TMA	DOA CAA UK.21J.0653 EuroAV Design Services MEADS1211MCA-001 at latest revision
2024-11-21	MOD/DHC-6/2024/41	DHC-6 FS 60.00 - 600.00 Fuselage Repairs on 8Q-TAE	DHC-6-300	372	TMA	FAA Form 8110-3 dated 12-Nov-2024 and Repair Drawing RD53-529-48A, Rev NC, dated 12-Nov-2024
2024-12-09	MOD/DHC-6/2024/42	Wings Main Spar Web Splice Repair	DHC-6-300	As per AeroKnow Repair Approval Document no. PR00532-RAD-001 at latest revision	TMA	DOA EASA.21J.791 AeroKnow Repair Approval Document PR00532-RAD-001

## CAA Aircraft Modification Register

Retrieved On: 3/19/2025

DATE	APPROVAL #	SUBJECT	AIRCRAFT / PART #	MSN	OPERATOR	DESIGN INFORMATION
2024-12-10	MOD/DHC-6/2024/43	Carpet Replacement	DHC-6 Series 200/300	As per AeroKnow Repair Approval Document no. PR00504-MCA-001 at latest revision	Manta	DOA EASA.21J.791 AeroKnow Repair Approval Document PR00504-MCA-001
2024-12-24	MOD/DHC-6/2024/44	Fuselage Repairs	DHC-6-300	700	TMA	FAA Form 8110-3 dated 13-Dec-2024 and Repair Drawing RD53-529-49A
2025-02-27	MOD/DHC-6/2025/01	Major Repair - Wing SIE-23-1003: Repair for corrosion damage to top skin and corrugation around fairing nutplate holes	DHC-6-300	Wing Boxes: LH - PN: C6W1002-25, SN: 503L25 and RH - PN: C6W1002-27, SN: 503L25	TMA	FAA Form 8110-3 by DER 948361366 dated 23 Feb 2025 and SIE Repair Drawing No.: SIE-23-1003, Rev. P dated 16 Feb 2025
2025-03-09	MOD/DHC-6/2025/02	Cabin Aft Bulkhead Non-Metallic Panel Modification	DHC-6-300	As per KNSI document 24U229-MA-001 at latest revision	Manta	DOA UK.21J.0560 KNSI Aviation Engineering Ltd. Minor Changes to Type-Certificate Approval Document # 24U229-MA-001 at latest revision
2025-03-10	MOD/DHC-8/2024/36R1	Installation of Spectrum Aeromed Ambulance Module with Electrical Module	DHC-8-202	542	IASL	TCCA STC A-LSA24-064/D at latest Revision
2025-03-11	MOD/DHC-6/2025/03	Whelen Anti-Collision and Position Light System	DHC-6 Series 100/200/300	As per STC Authorization Letter	TMA	FAA STC# SA800EA at latest Revision
2025-03-12	MOD/DHC-6/2025/04	OB Exhaust Path Existing RD6-57-618 Repair Doubler Rework + Tab due to LH Wing top skin exhaust path corrosion	DHC-6-300	LH Wing Box PN: C6W1002-25, SN: 503L25	TMA	FAA Form 8110-3 by DER 948361366 dated 26 Feb 2025 and SIE EO No.: SIE-SN503L25-LH-OB, dated Feb. 25, 2025
2025-03-16	MOD/DHC-6/2025/05	Indicating /Recording Systems - Audio Control Box Replacement	DHC-6 Series 100/200/300	As per EuroAv Minor Change Approval No: MEADS1224MCA-001	TMA	DOA CAA UK.21J.0653 Minor Changes to Type Certificate Approval Document # MEADS1224MCA-001
2025-03-19	MOD/DHC-6/2025/06	Minor Repair - Horizontal Stabilizer Lower Skin Panel Corrosion Damage	DHC-6 Series 300	410	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Minor Repair Approval document #25U012-MA-001
2025-03-19	MOD/DHC-6/2025/07	Minor Repair - Vertical Stabilizer Skin Panel Disbond Damage	DHC-6 Series 300	410	TMA	DOA UK.21J.0560 KNSI Aviation Engineering Minor Repair Approval document #25U011-MA-001
2025-03-19	MOD/DHC-6/2025/08	Major Change - Installation, Subsitute Composite Floor Panels	DHC-6 Series 300	MSNs as listed in the Thunder Bay Aviation Ltd. STC Authorisation Letter	TMA	Thunder Bay Aviation Ltd. , Transport Canada STC no. SA05-30